



This Service Information bulletin supersedes S.I. B61 14 03 **dated March 2007.**

NEW designates changes to this revision

SUBJECT

Software Errors Corrected with Progman

MODEL

E60, E61 (5 Series)

E63, E64 (6 Series)

Vehicles produced up to **NEW** March 30, 2007

SITUATION

Customer may complain of the following:

NEW The following software errors were corrected with the release of Progman 25.01.00 (Target data Status E060-07-03-520). Only software corrections for the last 2 Progman versions are listed below.

1. CCC (Car Communication Computer) equipped vehicle, the SDARS (Satellite Radio) stored station list is intermittently empty since programming with Progman V25.00.00.
2. Poor RTTI (Real Time Traffic Information) reception. The CID (Central Information Display) is constantly displaying "Transferring Messages" since programming with Progman V25.00.00.

The following software errors were corrected with the release of Progman 25.00.00 (Target data Status E060-07-03-510).

1. Engine pinging and cold idle fluctuation complaints. A jolt may be felt under braking. Only N62TU.
2. CCC: The programmable diamond MFL button does not work when set to "Next entertainment source" when vehicle is in motion.
3. CCC: The customer occasionally has poor radio reception after the vehicle was programmed with Progman V23.x or V24.x.
4. The speedometer and tachometer needles shake when the vehicle is idling.
5. CCC: Slow response to inputs made when using controller after startup.
6. CCC: A high frequency whistling noise intermittently can be heard in radio mode
7. CCC: Navigation system pop-up arrow display missing. Refer to [SI B84 61 06](#).
8. CCC: CD/CDC track advances after key cycled. Refer to [SI B65 32 05](#).

The following software errors were corrected with the release of Progman 24.00.00 (Target data Status E060-06-

12-510).

1. CCC (Car Communication Computer): The "dynamic route" SVS (Voice Recognition System) option is missing on vehicles with RTTI (Real Time Traffic Information).
2. Front side marker lights erroneously coded off after software update with Progman 23.x.

The following software errors were corrected with the release of Progman 23.00.00 (Target data Status E060-06-09-520).

1. CCC: Voice input system incorrectly states speed limit in "km". Refer to [SI B84 24 05](#).
2. CCC with Top HiFi (SA 677) loses surround sound settings after a Navigation system announcement. Refer to [SI B65 08 06](#).
3. CCC: The CD/DVD/CDC drive continues to spin even after the key is off. No audio output is heard. When the customer returns to the vehicle the audio CD is on a different track. This is most noticeable while listening to audio books on CD.
4. CCC: The customer states that sporadically, it is not possible to acknowledge the "Accept" button on the navigation system disclaimer screen using the controller. Refer to [SI B84 20 06](#).
5. CCC: Radio failure after entering the destination in the Navigation system via the voice input system. Other audio sources are not affected.
6. CCC: Sporadically the radio continues to play after the key is turned off. This fault occurred after programming the vehicle using Progman V19.1.
7. CCC: After changing the road map scale using the voice input system; it is not possible to change the map scale using the controller.
8. CCC: The audible warning gong sounds intermittently after the vehicle is started and cannot be turned off unless the vehicle key is cycled. No check control message is displayed while the gong is sounded.
9. CCC: The radio audio cuts out briefly in FM mode only while driving. Vehicle already has the tuner profile corrected as per [SI B65 26 05](#) and fault code CCC-ANT "DACA" hardware reset fault is stored.
10. CCC: The radio station that is currently being listened to intermittently changes to the next station in the station list. This can happen every 2 seconds
11. CCC: Check control gongs and PDC tones have no audio. Other audio functions operate correctly
12. Blower motor stays on with key off. Refer to [SI B64 01 06](#).
13. The speedometer and revolution counter needles shake when the vehicle is idling.

PROCEDURE

For all vehicles, on a customer complaint basis only, refer to the following procedure and warranty information.

1. Update the complete vehicle per [SI B09 05 01](#) (Coding, Individualization, Programming) Procedure B, using **Progman** **NEW** **25.01.00 (Target Data Status E060-07-03-NEW 520)** or higher.

WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty.

Defect Code

Refer to KSD

Labor Operation:

Refer to KSD

[Copyright © 2007 BMW of North America, LLC]