

This Service Information bulletin supersedes S.I. 65 12 06 dated December 2006.

NEW designates changes to this revision

SUBJECT

Popping/Crackling Noise from Audio System

MODEL

E60, E61 (5 Series) from 7/03 to 2/06 production

E63, E64 (6 Series) from 11/03 to 2/06 production

E65, E66 (7 Series) from NEW 1/03 to 3/06 production

E90, E91 (3 Series) from 3/05 to 2/06 production with Premium Package (ZPP) or BMW AssistTM (SA 639)

SITUATION

The customer may complain there is a popping/crackling noise coming from the audio sound system. The complaint may have started occurring after the vehicle software was updated. This noise can happen with or without telephone usage.

CAUSE

The Non-Volatile Memory (NVM) within the Network Access Device (NAD) may have been corrupted.

PROCEDURE:

- 1. Duplicate customer complaint.
- 2. Perform a short test on the complete vehicle using the DIS or GT1.
- 3. Check the vehicle history report on DSCnet to see if the vehicle is covered by service bulletin <u>B84 23 06</u> (defect code 00 84 31 01 00). If applicable per DCSnet, complete this work prior to continuing diagnosis.
- 4. Check the integrity of the NAD by using the procedure outline in <u>SI B84 25 06</u> as repair as outline in the bulletin.
- 5. Check the audio system to make sure the popping/cracking noise has been eliminated before returning the vehicle to the customer.

WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty.

Defect Code

84 11 92 02 00

Select one of the following labor operations:

Labor Operation: 00 56 194

Check the NAD (Vehicle at the latest

integration level)

Check value "0" fro	m step 10 in SI B84 25 06
---------------------	---------------------------

Labor Allowance:	All vehicles	7 FRU	-
Labor Operation:	00 56 195		Check NAD, flash recover the NAD via the
			MOXA and perform a complete vehicle
			encoding (Vehicle at the latest integration level)
			Check value "1" from step 10 in SI B84 25 06
Labor Allowance:	E60	19 FRU	
	E61	18 FRU	
	E63, E64	22 FRU	
	E65, E66	20 FRU	
	E90	18 FRU	
	E91	20 FRU	
Labor Operation:	00 56 196		Check NAD, replace the TCU and perform a
			complete vehicle encoding (Vehicle at the
			latest integration level)
			Check value "2, 3 or 4" from step 10 in SI B84 25 06
Labor Allowance:	E60 except M5	16 FRU	
	E60 M5	15 FRU	
	E61	14 FRU	
	E63, E64	19 FRU	
	E65, E66	16 FRU	
	E90	13 FRU	

	E91	14 FRU	
Labor Operation:	00 56 197		Check NAD, flash recover the NAD via the
			MOXA (TCU failed to program correctly),
			replace TCU (Vehicle at the latest integration
			level), program and code the complete vehicle
			because the TCU was replaced.
			Check value "1" from step 10 in SI B84 25 06
Labor Allowance:	E60	20 FRU	
	E61	19 FRU	
	E63, E64	23 FRU	
	E65, E66)	21 FRU	
	E90	18 FRU	
	E91	20 FRU	
Labor Operation:	00 56 198		Check NAD, program and code the complete
			vehicle
			Check value "0" from step 10 in SI B84 25 06
Labor Allowance:	All vehicles	16 FRU	
Labor Operation:	00 56 199		Check NAD, program and code the complete
			vehicle (Including programming of the CAS)
			Check value "0" from step 10 in SI B84 25 06
Labor Allowance:	All vehicles	17 FRU	
Labor Operation:	00 56 200		Check NAD, program and code the complete
			vehicle (Including programming of the NAV)
			Check value "0" from step 10 in SI B84 25 06
Labor Allowance:	E65, E66	19 FRU	

Labor Operation:	00 56 201		Check NAD, program and code the complete
			vehicle (Including programming of the CAS and
			the NAV)
			Check value "0" from step 10 in SI B84 25 06
Labor Allowance:	E65, E66	20 FRU	
Labor Operation:	00 56 202		Check NAD, flash recover the NAD via the
			MOXA, program and code the complete vehicle
			Check value "1" from step 10 in SI B84 25 06
Labor Allowance:	E60 except M5	25 FRU	
	E60 M5	24 FRU	
	E61	24 FRU	
	E63, E64	28 FRU	
	E65, E66	26 FRU	
	E90	24 FRU	
	E91	26 FRU	
Labor Operation:	00 56 203		Check NAD, flash recover the NAD via the
-			MOXA, program and code the complete vehicle
			(Including programming of the CAS)
			Check value "1" from step 10 in SI B84 25 06
Labor Allowance:	E60)	26 FRU	
	E61	25 FRU	
	E63, E64	29 FRU	
	E65, E66	27	

		FRU	
	E90	25 FRU	
	E91	27 FRU	
Labor Operation:	00 56 204		Check NAD, flash recover the NAD via the
			MOXA, program and code the complete vehicle
			(Including programming of the NAV)
			Check value "1" from step 10 in SI B84 25 06
Labor Allowance:	E65, E66	29 FRU	
Labor Operation:	00 56 205		Check NAD, flash recover the NAD via the
			MOXA, program and code the complete vehicle
			(Including programming of the CAS and the
			NAV)
			Check value "1" from step 10 in SI B84 25 06
Labor Allowance:	E65, E66	30 FRU	
Labor Operation:	00 56 206		Check NAD, replace the TCU, program and
			code the complete vehicle
			Check value "2, 3 or 4" from step 10 in
			SI B84 25 06
Labor Allowance:	E60	21 FRU	
	E61	20 FRU	
	E63, E64	24 FRU	
	E65, E66	22 FRU	
	E90	19 FRU	
	E91	19 FRU	
Labor Operation:	00 56 207		Check NAD, replace the TCU, program and
			code the complete vehicle (Including
			programming of the CAS)
			Check value "2, 3 or 4" from step 10 in
			SI B84 25 06

Labor Allowance:	E60	23 FRU	
	E61	21 FRU	
	E63, E64	25 FRU	
	E65, E66	23 FRU	
	E90	20 FRU	
	E91	21 FRU	
Labor Operation:	00 56 208		Check NAD, replace the TCU, program and
			code the complete vehicle (Including
			programming of the NAV)
			Check value "2, 3 or 4" from step 10 in
			SI B84 25 06
Labor Allowance:	E65, E66	25 FRU	
Labor Operation:	00 56 209		Check NAD, replace the TCU, program and
			code the complete vehicle (Including
			programming of the CAS and the NAV)
			Check value "2, 3 or 4" from step 10 in
			SI B84 25 06
Labor Allowance:	E65, E66	26 FRU	
Labor Operation:	00 56 210		Check NAD, flash recover the NAD via the
			MOXA (TCU failed to program correctly),
			replace the TCU, program and code the
			complete vehicle
			Check value "1" from step 10 in SI B84 25 06 &
			Check value "1, 2, 3, 4" from step 28 in
			SI B84 25 06
Labor Allowance:	E60 except M5	26 FRU	
	E60 M5	25 FRU	
	E61	25 FRU	
		29	

	E63, E64	FRU	
	E65, E66	27 FRU	
	E90	24 FRU	
	E91	26 FRU	
Labor Operation:	00 56 211		Check NAD, flash recover the NAD via the
			MOXA (TCU failed to program correctly),
			replace the TCU, program and code the
			complete vehicle (Including programming of the
			CAS) Check value "1" from step 10 in from step
			28 in SI B84 25 06
			& Check value "1, 2, 3, 4"SI B84 25 06
Labor Allowance:	E60	27 FRU	
	E61	26 FRU	
	E63, E64	30 FRU	
	E65, E66	28 FRU	
	E90	25 FRU	
	E91	27 FRU	
Labor Operation:	00 56 212		Check NAD, flash recover the NAD via the
			MOXA (TCU failed to program correctly),
			replace the TCU, program and code the
			complete vehicle (Including programming of the
			NAV) Check value "1" from step 10 in from step
			28 in SI B84 25 06
			& Check value "1, 2, 3, 4"SI B84 25 06

Labor Allowance:	E65, E66	30 FRU		
Labor Operation:	00 56 213		Check N	NAD, flash recover the NAD via the
			MOXA	(TCU failed to program correctly),
			replace	the TCU, program and code the
			complet the	e vehicle (Including programming of
			CAS an	d the NAV) Check value "1" from step
			10 in fro	om step 28 in SI B84 25 06
			& Chec	k value "1, 2, 3, 4"SI B84 25 06
Labor Allowance:	E65, E66	31 FRU		
Labor Operation:	84 99 000		For cent	ters outside of the Verizon
			Wireles	s Network
Labor Allowance:		2 FRU		
Labor Operation:	+00 57 501			Check the NAD, Deactivate Telematics and
				encoding of control unit (+Associated Work)
Labor Allowance:	E60,E61		9 FRU	
	E63,E64, E65,E66,E90,E9	91	8 FRU	
Labor Operation:	+00 57 502			Check the NAD, Deactivate Telematics,
				programming control unit(s) and performing
				complete coding (not including CAS)
				(+Associated Work)
Labor Allowance:	E60,E61, E63,E64, E65,E66,E90,E9	91	14 FRU	
Labor Operation:	+00 57 503			Check the NAD, Deactivate Telematics,

Page 9 of 11

			programming control unit(s) and
			performing
			complete coding (with CAS)
			(+Associated Work)
Labor Allowance:	E60,E61, E63,E64,E65,E66, E90,E91	15 FRU	
Labor Operation:	+00 57 504		Check the NAD, Deactivate Telematics,
			programming control unit(s) and performing
			complete coding (with navigation system)
			(+Associated Work)
Labor Allowance:	E65/E66	16 FRU	
Labor Operation:	+00 57 505		Check the NAD, Deactivate Telematics,
			programming control unit(s) and performing
			complete coding (with CAS and navigation
			system)
			(+Associated Work)
Labor Allowance:	E65/E66	18 FRU	
Labor Operation:	00 57 001		Check the NAD, Deactivate Telematics and
			encoding of control unit
			(Main work)
Labor Allowance:	E60,E61, E63,E64,E65,E66, E90,E91	10 FRU	
Labor Operation	: 00 57 002	Che	eck the NAD, Deactivate Telematics,
			gramming control unit(s) and forming
		con	pplete coding (not including CAS)

			(Main work)
Labor Allowance:	E60,E61	16 FRU	
	E63,E64, E65,E66,E90,E91	15 FRU	
Labor Operation:	00 57 003		Check the NAD, Deactivate Telematics,
			programming control unit(s) and performing
			complete coding (with CAS)
			(Main work)
Labor Allowance:	E60,E61	17 FRU	
	E63,E64, E65,E66,E90,E91	16 FRU	
Labor Operation:	00 57 004		Check the NAD, Deactivate Telematics,
			programming control unit(s) and performing
			complete coding (with navigation system)
			(Main work)
Labor Allowance:	E65/E66	18 FRU	
Labor Operation:	00 57 005		Check the NAD, Deactivate Telematics,
			programming control unit(s) and performing
			complete coding (with CAS and navigation
Labor Allowance:	E65/E66	19 FRU	system)
			(Main work)

TCU shipping charges for BMW centers outside Verizon Wireless network

All shipping charges (both ways) are to be billed to the dealer's Fed-Ex account. On the warranty claim, submit the Fed-Ex shipping charges (double the amount provided to you by Technical Hotline to cover shipment both ways) in the sublet section (using sublet code 4).

Additional Programming Information

If the measures plan in Progman specifies that programming should be repeated and/or control units should be replaced proceed as follows:

- Print measure plan and final report.
- Refer to KSD for additional labor information.
- Additional costs associated with programming should be charged to the defect code listed in this bulletin.

[Copyright © 2007 BMW of North America, LLC]