



SUBJECT

CCC: CD/CDC Track Counter Advances After Mute Selected

MODEL

E90, E91 (3 Series) with SA 609 CCC-Navigation

E60, E61 (5 Series) with SA 609 CCC-Navigation

E63, E64 (6 Series)

SITUATION

One or more of the following situations can occur since the vehicle software was updated with CIP 16.1, while the customer is listening to an audio CD in the CCC (Car Communication Computer) or the CDC (CD Changer):

1. The customer presses the rotary knob to mute the audio and turns the controller to highlight the next track, the track counter starts to advance.
2. The customer presses the rotary knob to mute the audio and turns the ignition off. The vehicle enters sleep mode and then the customer turns the ignition back on, the audio is still muted but the track counter is advancing.

CAUSE

CCC software error

PROCEDURE

Do not replace any parts.

Once a software solution is available this service information will be updated.

WARRANTY INFORMATION

For Information only