



This Service Information bulletin supersedes S.I. 65 35 06 dated **December 2006**.

NEW designates changes to this revision

SUBJECT

Poor Radio Reception in FM Mode

MODEL

E60 (5 Series) with M-ASK (Multi Audio System Controller)

From start of production to December 2003

SITUATION

Poor radio reception and/or interference in FM mode.

NEW CAUSE

Hardware error in the M-ASK.

NEW PROCEDURE

On a customer complaint basis only, replace the M-ASK with improved part.

NEW PARTS INFORMATION

Part Number	Description	Quantity
65 12 6 942 521	M-ASK	1

NEW WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty.

Please refer to the latest KSD for all applicable labor operations and allowances.

If the appropriate labor operation is not contained in KSD, then a work time labor operation should be used.

Defect Code **65 10 23 39 00** Analogue Radio Reception Unpleasant Noises