	COMPILED AND EDIT	TED BY COBF	RADAV - COURTE	ESY OF KoTR @ bimmerdrivers.com
Category	SIBs (SI B## ## ##)	<u>Date</u>	<u>Application</u>	<u>Title</u>
Maintenance and General Hints	00 04 02	March-08	All	BMW Group Technical Hotlline (rpl 1/08)
Maintenance and General Hints Maintenance and General Hints	00 06 03 00 01 05	November-03 June-06	All All	General info on TIS Website New Vehicle Preparation and Maintenance Requirements (Supercedes Jan 06)
Maintenance and General Hints	B000105ATT_VehChk	P/O 00 01 05	525/530	Quality Certification Form
Maintenance and General Hints	00 02 06	March-07	All	New Vehicle Preparation and Maintenance Requirements (MY07) (Rpl 11/06)
Maintenance and General Hints	00 01 07	May-08	ALL	New Vehicle Preparation and Maintenance Requirements (rpl 3/8 adds M3 DCT and 1 series)
Maintenance and General Hints	00 03 07	August-07	ALL	PuMA Enhancements for TeileClearing Process
Maintenance and General Hints Maintenance and General Hints	00 04 07 00 08 07	March-08 October-07	X3, X5 All	New Vehicle Preparation and Maintenance Requirements (rpl 12/07 adds X6) Construction Group Changes
Maintenance and General Hints	00 01 08	March-08	BMW Centers	BMW Center Technical Support Overview
Maintenance and General Hints	00 02 08	March-08	E82/E88	E82, E88 (1 Series) Quality Control Information
Maintenance and General Hints	00 03 08	April-08	E71 (X6)	E71 (X6) Quality Control Information
Maintenance and General Hints	00 04 08	April-09	ALL	New Vehicle Preparation and Maintenance Requirements (add new Z4)
Maintenance and General Hints	00 05 08 00 06 08	January-09 September-08	ALL	New Vehicle Preparation and Maintenance Requirements
Maintenance and General Hints Maintenance and General Hints	00 08 08	October-08	ALL 3 series	Information Tags E90, E91 (3 Series) LCI Quality Control Information
Maintenance and General Hints	00 08 08	December-08	335d & X5d	E90, E70 Diesel Quality Control Information
Maintenance and General Hints	00 01 09	March-09	5, 6 Series	New Vehicle Preparation and Maintenance Requirements
Maintenance and General Hints	00 02 09	February-09	7 series	F01, F02 Quality Control Information
Maintenance and General Hints Maintenance and General Hints	00 04 09 00 05 09	May-09 June-09	Z4 (e89) All	E89 Quality Control Information CBS Service Maintenance Substitute Checklists
Maintenance and General Filits	00 03 09	Julie-05	All	CBS Service Maintenance Substitute Checklists
	09 na			
	0.4.00.00	0	511111 6	DANKA CONTRACTOR OF THE CONTRA
Warranty	01 02 03 01 07 03	September-03	BMW Centers BMW Centers	BMW Maintenance Program 4 Years - 50,000 Miles
Warranty Warranty	01 07 03	January-07 November-06	BMW Centers	BMW Center Administered Customer Assistance Program (CACAP) BMW Tire Center Target Satisfaction Program
Warranty	01 06 05	March-05	BMW Centers	BMW Maintenance Program 2005 Laminated Reference Chart and Mouse Pad
Warranty	B010605Attachment.	P/O 01 06 05	BMW Centers	Chart of Warranty Codes/Services
Warranty	01 07 05	March-05	BMW Centers	Warranty Claims Processing – "Overnight Payments"
Warranty Warranty	01 10 05 B011005Attachment.	August-05 P/O 01 10 05	BMW Centers BMW Centers	TCU ESN Registration via DCSnet FAQ's for TCU Claims
Warranty	01 01 06	January-08	BMW Centers	BMW Warranty Policy and Procedures Manual – Updates from 01/01/05 through 12/21/07)
Warranty	B010106Attachment	P/O 01 01 06	BMW Centers	BMW Warranty Policy and Procedures Manual – Updates from 01/01/05 through 12/21/05 rev notes
Warranty	01 02 06	February-06	BMW Centers	BMW Electronic Archiving System (EAS) Evaluation and Certification
Warranty	B010206EAS_Flowchart.	February-06	BMW Centers	EAS Flowchart
Warranty	01 03 06 01 04 06	February-07	BMW Centers BMW Centers	Warranty Claims for Software Update Programming (Progman) (Replace NOV 06)
Warranty Warranty	01 04 06	April-06 February-07	BMW Centers	Reasons for Vehicle Update Programming Reminder Magnet Defect Code for Programming Prior to Accessory Retrofit (Supercedes 12/06)
Warranty	01 03 00	June-07	BMW Centers	New Pricing Plan and Program Enhancements - Maintenance Program Upgrade
Warranty	01 02 08	February-08	BMW Centers	BMW Performance Line of Accessories
Warranty	01 03 08	May-08	BMW Centers	OEM Tire Manufacturer Warranty Coverage CD-ROM
Warranty	01 05 08	July-08	BMW Centers	Certified Pre-Owned (CPO) Reconditioning Changes
Warranty Warranty	01 06 08 01 07 08	December-08 December-08	BMW Centers BMW Centers	Warranties Knowledge Portal (WKP) Labor Rate Calculation on all Reimbursed Labor as of 1/1/09
wanany	01 07 00	December-00	DIVIVY Certers	Labor Nate Calculation on all Nerribursed Labor as or 1/1/09
After Sales Business Development	02 01 05 B020105KeyBenefitChart	October-05 P/O 02 01 05	All	BMW Assist changes for September 2005 BMW Assist - Key Benefits
After Sales Business Development After Sales Business Development	02 01 06	February-06	All	Updated DCSnet Vehicle History Inquiry Information on BMW Assist™ (Supercedes Jan 06)
After Sales Business Development	02 02 06	November-06	All	BMW Assist TM Service Extension Incentive Program (Supercedes 02/06)
After Sales Business Development	02 01 07	February-07	All	Mobile Assistance Program
Tools and Equipment	04 02 05	January-05	E60/E63	Zero-Coded Cover
Tools and Equipment	04 04 05	January-05	E60	Antenna Knife
Tools and Equipment Tools and Equipment	04 04 05 04 07 05	January-05 April-05	E60 N52 Engine	Antenna Knife N52 Special Tools
Tools and Equipment Tools and Equipment Tools and Equipment	04 04 05 04 07 05 04 08 05	January-05 April-05 February-05	E60 N52 Engine E60/E63	Antenna Knife N52 Special Tools Aluminum Body Tools
Tools and Equipment Tools and Equipment	04 04 05 04 07 05	January-05 April-05 February-05 March-05	E60 N52 Engine	Antenna Knife N52 Special Tools Aluminum Body Tools Tailgate Support
Tools and Equipment	04 04 05 04 07 05 04 08 05 04 13 05	January-05 April-05 February-05	E60 N52 Engine E60/E63 E61	Antenna Knife N52 Special Tools Aluminum Body Tools
Tools and Equipment	04 04 05 04 07 05 04 08 05 04 13 05 04 14 05 04 15 05 04 29 05	January-05 April-05 February-05 March-05 April-05 May-05 November-05	E60 N52 Engine E60/E63 E61 E60/E63 E90 E60/E63	Antenna Knife N52 Special Tools Aluminum Body Tools Tailgate Support CD Eject Tool DME Test Cable AC Sprayer Wand
Tools and Equipment	04 04 05 04 07 05 04 08 05 04 13 05 04 14 05 04 15 05 04 29 05 04 02 06	January-05 April-05 February-05 March-05 April-05 May-05 November-05 January-06	E60 N52 Engine E60/E63 E61 E60/E63 E90 E60/E63 M - S85 engine	Antenna Knife NS2 Special Tools Aluminum Body Tools Tailgate Support CD Eject Tool DME Test Cable AC Sprayer Wand Backlash Gauge
Tools and Equipment	04 04 05 04 07 05 04 08 05 04 13 05 04 14 05 04 15 05 04 29 05 04 02 06 04 04 07	January-05 April-05 February-05 March-05 April-05 May-05 November-05 January-06 April-07	E60 N52 Engine E60/E63 E61 E60/E63 E90 E60/E63 M - \$85 engine Turbocharged	Antenna Knife N52 Special Tools Aluminum Body Tools Tailgate Support CD Eject Tool DME Test Cable AC Sprayer Wand Backlash Gauge Turbocharger Diagnostic Tool
Tools and Equipment	04 04 05 04 07 05 04 08 05 04 13 05 04 14 05 04 15 05 04 29 05 04 02 06	January-05 April-05 February-05 March-05 April-05 May-05 November-05 January-06	E60 N52 Engine E60/E63 E61 E60/E63 E90 E60/E63 M - S85 engine	Antenna Knife NS2 Special Tools Aluminum Body Tools Tailgate Support CD Eject Tool DME Test Cable AC Sprayer Wand Backlash Gauge
Tools and Equipment	04 04 05 04 07 05 04 08 05 04 13 05 04 14 05 04 15 05 04 29 05 04 02 06 04 07 07	January-05 April-05 February-05 March-05 April-05 May-05 November-05 January-06 April-07 December-07	E60 N52 Engine E60/E63 E61 E60/E63 E90 E60/E63 M - S85 engine Turbocharged All	Antenna Knife N52 Special Tools Aluminum Body Tools Tailgate Support CD Eject Tool DME Test Cable AC Sprayer Wand Backlash Gauge Turbocharger Diagnostic Tool Fuel Injection and Induction System Cleaning
Tools and Equipment	04 04 05 04 07 05 04 08 05 04 13 05 04 14 05 04 15 05 04 29 05 04 02 06 04 07 04 07 07 04 01 08	January-05 April-05 February-05 March-05 April-05 May-05 November-05 January-06 April-07 December-07	E60 N52 Engine E60/E63 E61 E60/E63 E90 E60/E63 M - S85 engine Turbocharged All	Antenna Knife N52 Special Tools Aluminum Body Tools Tailgate Support CD Eject Tool DME Test Cable AC Sprayer Wand Backlash Gauge Turbocharger Diagnostic Tool Fuel Injection and Induction System Cleaning
Tools and Equipment	04 04 05 04 07 05 04 08 05 04 13 05 04 14 05 04 15 05 04 29 05 04 02 06 04 04 07 04 07 07 04 01 08	January-05 April-05 February-05 March-05 April-05 May-05 November-05 January-06 April-07 December-07	E60 N52 Engine E60/E63 E61 E60/E63 E90 E60/E63 M - S85 engine Turbocharged All	Antenna Knife N52 Special Tools Aluminum Body Tools Tailgate Support CD Eject Tool DME Test Cable AC Sprayer Wand Backlash Gauge Turbocharger Diagnostic Tool Fuel Injection and Induction System Cleaning
Tools and Equipment	04 04 05 04 07 05 04 08 05 04 13 05 04 14 05 04 15 05 04 29 05 04 02 06 04 07 04 07 07 04 01 08	January-05 April-05 February-05 March-05 April-05 May-05 November-05 January-06 April-07 December-07	E60 N52 Engine E60/E63 E61 E60/E63 E90 E60/E63 M - S85 engine Turbocharged All	Antenna Knife N52 Special Tools Aluminum Body Tools Tailgate Support CD Eject Tool DME Test Cable AC Sprayer Wand Backlash Gauge Turbocharger Diagnostic Tool Fuel Injection and Induction System Cleaning
Tools and Equipment	04 04 05 04 07 05 04 08 05 04 13 05 04 13 05 04 14 05 04 15 05 04 29 05 04 02 06 04 04 07 04 07 04 01 08 thru - 2106 no value 07-0307/0507-0607/ & 0807-2807 no value	January-05 April-05 February-05 March-05 April-05 May-05 November-05 January-06 April-07 December-07	E60 N52 Engine E60/E63 E61 E60/E63 E90 E60/E63 M - S85 engine Turbocharged All	Antenna Knife N52 Special Tools Aluminum Body Tools Tailgate Support CD Eject Tool DME Test Cable AC Sprayer Wand Backlash Gauge Turbocharger Diagnostic Tool Fuel Injection and Induction System Cleaning
Tools and Equipment	04 04 05 04 07 05 04 08 05 04 13 05 04 14 05 04 14 05 04 15 05 04 29 05 04 02 06 04 07 04 07 04 07 07 04 01 08 thru - 2106 no value 07-0307/0507-0607/ & 0807-2807 no value	January-05 April-05 February-05 March-05 April-05 May-05 November-05 January-06 April-07 December-07 January-08	E60 N52 Engine E60/E63 E61 E60/E63 E90 E60/E63 M - S85 engine Turbocharged All S65/M3	Antenna Knife N52 Special Tools Aluminum Body Tools Tailgate Support CD Eject Tool DME Test Cable AC Sprayer Wand Backlash Gauge Turbocharger Diagnostic Tool Fuel Injection and Induction System Cleaning New Special Tools
Tools and Equipment	04 04 05 04 07 05 04 08 05 04 13 05 04 13 05 04 14 05 04 15 05 04 29 05 04 02 06 04 04 07 04 07 04 01 08 thru - 2106 no value 07-0307/0507-0607/ & 0807-2807 no value	January-05 April-05 February-05 March-05 April-05 May-05 November-05 January-06 April-07 December-07 January-08	E60 N52 Engine E60/E63 E61 E60/E63 E90 E60/E63 M - S85 engine Turbocharged All S65/M3	Antenna Knife N52 Special Tools Aluminum Body Tools Tailgate Support CD Eject Tool DME Test Cable AC Sprayer Wand Backlash Gauge Turbocharger Diagnostic Tool Fuel Injection and Induction System Cleaning New Special Tools
Tools and Equipment	04 04 05 04 07 05 04 07 05 04 08 05 04 13 05 04 14 05 04 15 05 04 29 05 04 02 06 04 07 04 07 04 07 07 04 01 08 thru - 2106 no value 07-0307/0507-0607/ & 0807-2807 no value	January-05 April-05 February-05 March-05 April-05 May-05 November-05 January-06 April-07 December-07 January-08	E60 N52 Engine E60/E63 E61 E60/E63 E90 E60/E63 M - S85 engine Turbocharged All S65/M3	Antenna Knife NS2 Special Tools Aluminum Body Tools Tailgate Support CD Eject Tool DME Test Cable AC Sprayer Wand Backlash Gauge Turbocharger Diagnostic Tool Fuel Injection and Induction System Cleaning New Special Tools Teleservice Changing a Customer's Preferred Home Dealer
Tools and Equipment	04 04 05 04 07 05 04 07 05 04 08 05 04 13 05 04 14 05 04 15 05 04 19 05 04 02 06 04 07 04 07 04 07 07 04 01 08 thru - 2106 no value 07-0307/0507-0607/ & 0807-2807 no value 05 01 05 end 07 02 96 07 03 02 07 05 02	January-05 April-05 February-05 March-05 April-05 May-05 November-05 January-06 April-07 December-07 January-08	E60 N52 Engine E60/E63 E61 E60/E63 E90 E60/E63 M - S85 engine Turbocharged All S65/M3 All BMW Centers BMW Centers BMW Centers	Antenna Knife NS2 Special Tools Aluminum Body Tools Tailgate Support CD Eject Tool DME Test Cable AC Sprayer Wand Backlash Gauge Turbocharger Diagnostic Tool Fuel Injection and Induction System Cleaning New Special Tools Teleservice Changing a Customer's Preferred Home Dealer CD42: Updated DISplus & GT1 Software (update to Mar 07) Optical Testing & Programming System - OPPS Online Update
Tools and Equipment	04 04 05 04 07 05 04 07 05 04 08 05 04 13 05 04 14 05 04 14 05 04 15 06 04 29 05 04 02 06 04 04 07 04 07 07 04 01 08 thru - 2106 no value 07-0307/0507-0607/ & 0807-2807 no value 07 02 96 07 03 02 07 05 02 07 05 02	January-05 April-05 February-05 March-05 April-05 May-05 November-05 January-06 April-07 December-07 January-08 September-05 June-07 June-04 June-05 November-04	E60 N52 Engine E60/E63 E61 E60/E63 E90 E60/E63 M - S85 engine Turbocharged All S65/M3 All BMW Centers BMW Centers BMW Centers BMW Centers	Antenna Knife NS2 Special Tools Aluminum Body Tools Tailgate Support CD Eject Tool DME Test Cable AC Sprayer Wand Backlash Gauge Turbocharger Diagnostic Tool Fuel Injection and Induction System Cleaning New Special Tools Teleservice Changing a Customer's Preferred Home Dealer CD42: Updated DISplus & GT1 Software (update to Mar 07) Optical Testing & Programming System - OPPS Online Update Optical Programming System - OPS
Tools and Equipment Tools	04 04 05 04 07 05 04 07 05 04 08 05 04 13 05 04 14 05 04 14 05 04 15 05 04 29 05 04 02 06 04 04 07 04 07 07 04 01 08 thru - 2106 no value 07-0307/0507-0607/ & 0807-2807 no value 07 03 02 07 05 02 07 05 02 07 05 02 07 02 04 07 01 05	January-05 April-05 February-05 March-05 April-05 May-05 November-05 January-06 April-07 December-07 January-08 September-05 June-07 June-04 June-04 June-04 December-04 December-04 December-05	E60 N52 Engine E60/E63 E61 E60/E63 E90 E60/E63 M - S85 engine Turbocharged All S65/M3 All BMW Centers BMW Centers BMW Centers BMW Centers BMW Centers BMW Centers	Antenna Knife NS2 Special Tools Aluminum Body Tools Tailgate Support CD Eject Tool DME Test Cable AC Sprayer Wand Backlash Gauge Turbocharger Diagnostic Tool Fuel Injection and Induction System Cleaning New Special Tools Teleservice Changing a Customer's Preferred Home Dealer CD42: Updated DISplus & GT1 Software (update to Mar 07) Optical Testing & Programming System - OPPS Online Update Optical Programming System - OPS Software Service Station 12 (SSS12)
Tools and Equipment Tools	04 04 05 04 07 05 04 07 05 04 08 05 04 13 05 04 14 05 04 14 05 04 15 06 04 29 05 04 02 06 04 04 07 04 07 07 04 01 08 thru - 2106 no value 07-0307/0507-0607/ & 0807-2807 no value 07 02 96 07 03 02 07 05 02 07 05 02	January-05 April-05 February-05 March-05 April-05 May-05 November-05 January-06 April-07 December-07 January-08 September-05 June-07 June-04 June-05 November-04 December-05 August-06	E60 N52 Engine E60/E63 E61 E60/E63 E90 E60/E63 M - S85 engine Turbocharged All S65/M3 All BMW Centers	Antenna Knife NS2 Special Tools Aluminum Body Tools Tailgate Support CD Eject Tool DME Test Cable AC Sprayer Wand Backlash Gauge Turbocharger Diagnostic Tool Fuel Injection and Induction System Cleaning New Special Tools Teleservice Changing a Customer's Preferred Home Dealer CD42: Updated DISplus & GT1 Software (update to Mar 07) Optical Testing & Programming System - OPPS Online Update Optical Programming System - OPS Software Service Station r2 (SSSr2) Next Generation Workshop Technology – iBase Server Readiness Project
Tools and Equipment Tools	04 04 05 04 07 05 04 07 05 04 08 05 04 13 05 04 14 05 04 15 05 04 19 05 04 02 06 04 02 06 04 07 07 04 01 08 thru - 2106 no value 07-0307/0507-0607/ & 0807-2807 no value 05 01 05 end 07 02 96 07 03 02 07 02 04 07 01 05 07 01 05	January-05 April-05 February-05 March-05 April-05 May-05 November-05 January-06 April-07 December-07 January-08 September-05 June-07 June-04 June-04 June-04 December-04 December-04 December-05	E60 N52 Engine E60/E63 E61 E60/E63 E90 E60/E63 M - S85 engine Turbocharged All S65/M3 All BMW Centers BMW Centers BMW Centers BMW Centers BMW Centers BMW Centers	Antenna Knife NS2 Special Tools Aluminum Body Tools Tailgate Support CD Eject Tool DME Test Cable AC Sprayer Wand Backlash Gauge Turbocharger Diagnostic Tool Fuel Injection and Induction System Cleaning New Special Tools Teleservice Changing a Customer's Preferred Home Dealer CD42: Updated DISplus & GT1 Software (update to Mar 07) Optical Testing & Programming System - OPPS Online Update Optical Programming System - OPS Software Service Station 12 (SSS12)
Tools and Equipment Tools	04 04 05 04 07 05 04 07 05 04 08 05 04 13 05 04 14 05 04 15 05 04 14 05 04 19 05 04 02 06 04 04 07 04 07 07 04 01 08 thru - 2106 no value 07-0307/0507-0607/ & 0807-2807 no value 05 01 05 end 07 02 96 07 03 02 07 02 04 07 01 05 07 01 06 07 03 06 07 04 06 07 04 06 07 04 06 07 01 07	January-05 April-05 February-05 March-05 April-05 May-05 November-05 January-06 April-07 December-07 January-08 September-05 June-07 June-04 June-05 November-04 December-05 August-06 October-06 January-07 March-07	E60 N52 Engine E60/E63 E61 E60/E63 E90 E60/E63 M - S85 engine Turbocharged All S65/M3 All BMW Centers	Antenna Knife NS2 Special Tools Alumirum Body Tools Tailgate Support CD Eject Tool DME Test Cable AC Sprayer Wand Backlash Gauge Turbocharger Diagnostic Tool Fuel Injection and Induction System Cleaning New Special Tools Teleservice Changing a Customer's Preferred Home Dealer CD42: Updated DISplus & GT1 Software (update to Mar 07) Optical Testing & Programming System - OPPS Online Update Optical Programming System - OPS Software Service Station r2 (SSSr2) Next Generation Workshop Technology - iBase Server Readiness Project Next Generation Workshop Technology 3G Use Agreement for 3G Workshop Technology USI V49 Corrections Based on Diagnosis Feedback
Tools and Equipment Tools	04 04 05 04 07 05 04 07 05 04 08 05 04 13 05 04 14 05 04 14 05 04 15 05 04 29 05 04 02 06 04 04 07 04 07 07 04 01 08 thru - 2106 no value 07-0307/0507-0607/ & 0807-2807 no value 07 03 02 07 03 02 07 05 02 07 02 04 07 01 05 07 01 06 07 03 06 07 04 06 07 03 06 07 04 06 07 01 07 B070107_Feedback PDF	January-05 April-05 February-05 March-05 April-05 May-05 November-05 January-06 April-07 December-07 January-08 September-05 June-07 June-04 June-05 November-04 December-05 August-06 October-06 January-07 March-07 March-07	E60 N52 Engine E60/E63 E61 E60/E63 E90 E60/E63 M - S85 engine Turbocharged All S65/M3 All BMW Centers	Antenna Knife NS2 Special Tools Aluminum Body Tools Tailgate Support CD Eject Tool DME Test Cable AC Sprayer Wand Backlash Gauge Turbocharger Diagnostic Tool Fuel Injection and Induction System Cleaning New Special Tools Teleservice Changing a Customer's Preferred Home Dealer CD42: Updated DISplus & GT1 Software (update to Mar 07) Optical Testing & Programming System - OPPS Online Update Optical Programming System - OPS Software Service Station r2 (SSSr2) Next Generation Workshop Technology - iBase Server Readiness Project Next Generation Workshop Technology 3G Use Agreement for 3G Workshop Technology DIS V49 Corrections Based on Diagnosis Feedback B070107Diagnosis Feedback_Corrected_DIS_V49.
Tools and Equipment Tools	04 04 05 04 07 05 04 07 05 04 08 05 04 13 05 04 14 05 04 14 05 04 14 05 04 19 05 04 19 05 04 02 06 04 04 07 04 07 07 04 01 08 thru - 2106 no value 07-0307/0507-0607/ & 0807-2807 no value 07 03 02 07 05 02 07 05 02 07 05 02 07 05 02 07 01 06 07 01 06 07 01 07 080707-5edback PDF 07 03 07	January-05 April-05 February-05 March-05 April-05 May-05 November-05 January-06 April-07 December-07 January-08 September-05 June-07 June-04 June-05 November-04 December-05 August-06 October-06 January-07 March-07	E60 N52 Engine E60/E63 E61 E60/E63 E90 E60/E63 M - S85 engine Turbocharged All S65/M3 All BMW Centers	Antenna Knife NS2 Special Tools Alumirum Body Tools Tailgate Support CD Eject Tool DME Test Cable AC Sprayer Wand Backlash Gauge Turbocharger Diagnostic Tool Fuel Injection and Induction System Cleaning New Special Tools Teleservice Changing a Customer's Preferred Home Dealer CD42: Updated DISplus & GT1 Software (update to Mar 07) Optical Testing & Programming System - OPPS Online Update Optical Programming System - OPS Software Service Station r2 (SSSr2) Next Generation Workshop Technology - iBase Server Readiness Project Next Generation Workshop Technology 3G Use Agreement for 3G Workshop Technology USI V49 Corrections Based on Diagnosis Feedback
Tools and Equipment Tools	04 04 05 04 07 05 04 07 05 04 08 05 04 13 05 04 14 05 04 14 05 04 15 05 04 29 05 04 02 06 04 04 07 04 07 07 04 01 08 thru - 2106 no value 07-0307/0507-0607/ & 0807-2807 no value 07 03 02 07 03 02 07 05 02 07 02 04 07 01 05 07 01 06 07 03 06 07 04 06 07 03 06 07 04 06 07 01 07 B070107_Feedback PDF	January-05 April-05 February-05 March-05 April-05 May-05 November-05 January-06 April-07 December-07 January-08 September-05 June-07 June-04 June-05 November-04 December-05 August-06 October-06 January-07 March-07 March-07	E60 N52 Engine E60/E63 E61 E60/E63 E90 E60/E63 M - S85 engine Turbocharged All S65/M3 All BMW Centers	Antenna Knife NS2 Special Tools Aluminum Body Tools Tailgate Support CD Eject Tool DME Test Cable AC Sprayer Wand Backlash Gauge Turbocharger Diagnostic Tool Fuel Injection and Induction System Cleaning New Special Tools Teleservice Changing a Customer's Preferred Home Dealer CD42: Updated DISplus & GT1 Software (update to Mar 07) Optical Testing & Programming System - OPPS Online Update Optical Programming System - OPS Software Service Station r2 (SSSr2) Next Generation Workshop Technology - iBase Server Readiness Project Next Generation Workshop Technology 3G Use Agreement for 3G Workshop Technology DIS V49 Corrections Based on Diagnosis Feedback B070107Diagnosis Feedback_Corrected_DIS_V49.
Tools and Equipment Tools	04 04 05 04 07 05 04 07 05 04 08 05 04 13 05 04 14 05 04 14 05 04 15 05 04 12 05 04 02 06 04 04 07 04 07 07 04 01 08 thru - 2106 no value 07-0307/0507-0607/ & 0807-2807 no value 05 01 05 end 07 02 96 07 03 02 07 05 02 07 05 02 07 05 02 07 05 02 07 01 06 07 01 06 07 01 07 07 01 07 080707_Feedback PDF 07 03 07 07 04 07 07 04 07 07 04 07	January-05 April-05 February-05 March-05 April-05 May-05 November-05 January-06 April-07 December-07 January-08 September-05 June-07 June-04 June-05 November-04 December-05 August-06 October-06 January-07 March-07 June-07 August-07 June-07	E60 N52 Engine E60/E63 E61 E60/E63 E90 E60/E63 M - S85 engine Turbocharged All S65/M3 All BMW Centers	Antenna Knife NS2 Special Tools Aluminum Body Tools Tailgate Support CD Eject Tool DME Test Cable AC Sprayer Wand Backlash Gauge Turbocharger Diagnostic Tool Fuel Injection and Induction System Cleaning New Special Tools Teleservice Changing a Customer's Preferred Home Dealer CD42: Updated DISplus & GT1 Software (update to Mar 07) Optical Testing & Programming System - OPPS Online Update Optical Programming System - OPS Software Service Station 12 (SSS12) Next Generation Workshop Technology - iBase Server Readiness Project Next Generation Workshop Technology - iBase Server Readiness Project Next Generation Workshop Technology DIS V49 Corrections Based on Diagnosis Feedback B070107Diagnosis_Feedback_Corrected_DIS_V49. DIS V50 Corrections Based on Diagnosis Feedback DIS V51 Corrections Based on Diagnosis Feedback Update to June 07) DIS V50 Release Notes
Tools and Equipment Tools	04 04 05 04 07 05 04 07 05 04 08 05 04 13 05 04 14 05 04 15 05 04 15 05 04 29 05 04 02 06 04 04 07 04 07 07 04 07 07 04 01 08 thru - 2106 no value 07-0307/0507-0607/ & 0807-2807 no value 05 01 05 end 07 02 96 07 03 02 07 05 02 07 05 02 07 05 02 07 04 06 07 01 05 07 01 05 07 01 07 B070307_Feedback PDF 07 03 07 B070307_Feedback PDF 07 04 07 07 05 07 07 05 07	January-05 April-05 February-05 March-05 April-05 May-05 November-05 January-06 April-07 December-07 January-08 September-05 September-05 June-04 June-05 November-04 December-05 August-06 October-06 January-07 March-07 June-07 August-07 June-07 August-07 June-07 August-07 August-07	E60 N52 Engine E60/E63 E61 E60/E63 E90 E60/E63 M - S85 engine Turbocharged All S65/M3 All BMW Centers	Antenna Knife NS2 Special Tools Aluminum Body Tools Tailgate Support CD Eject Tool DME Test Cable AC Sprayer Wand Backlash Gauge Turbocharger Diagnostic Tool Fuel Injection and Induction System Cleaning New Special Tools Teleservice Changing a Customer's Preferred Home Dealer CD42: Updated DISplus & GT1 Software (update to Mar 07) Optical Testing & Programming System - OPPS Online Update Optical Programming System - OPS Software Service Station /2 (SSSr2) Next Generation Workshop Technology – iBase Server Readiness Project Next Generation Workshop Technology 3G Use Agreement for 3G Workshop Technology DIS V49 Corrections Based on Diagnosis Feedback B070107Diagnosis_Feedback_Corrected_DIS_V49. DIS V50 Corrections Based on Diagnosis Feedback Update to June 07) DIS V50 Release Notes Diagnosis Process
Tools and Equipment Tools	04 04 05 04 07 05 04 07 05 04 08 05 04 13 05 04 14 05 04 14 05 04 14 05 04 29 05 04 02 06 04 04 07 04 07 07 04 01 08 thru - 2106 no value 07-0307/0507-0607/ & 0807-2807 no value 05 01 05 end 07 02 96 07 03 02 07 05 02 07 05 02 07 05 02 07 01 06 07 01 06 07 01 07 08 070 10 07 08 070 10 07 08 070 10 07 07 05 07 08 070 04 07 07 05 07 07 04 07 07 05 07 07 06 07 07 06 07 07 06 07 07 06 07	January-05 April-05 February-05 March-05 April-05 May-05 November-05 January-06 April-07 December-07 January-08 September-05 June-07 June-04 June-05 November-04 December-05 August-06 January-07 March-07 June-07 August-07	E60 N52 Engine E60/E63 E61 E60/E63 E90 E60/E63 M - S85 engine Turbocharged All S65/M3 All BMW Centers	Antenna Knife NS2 Special Tools Aluminum Body Tools Tailgate Support CD Eject Tool DME Test Cable AC Sprayer Wand Backlash Gauge Turbocharger Diagnostic Tool Fuel Injection and Induction System Cleaning New Special Tools Teleservice Changing a Customer's Preferred Home Dealer CD42: Updated DISplus & GT1 Software (update to Mar 07) Optical Testing & Programming System - OPPS Online Update Optical Programming System - OPS Software Service Station r2 (SSSr2) Next Generation Workshop Technology – iBase Server Readiness Project Next Generation Workshop Technology 3G Use Agreement for 3G Workshop Technology DIS V49 Corrections Based on Diagnosis Feedback B070107Diagnosis Feedback Corrected_DIS_V49, DIS V50 Corrections Based on Diagnosis Feedback DIS V51 Corrections Based on Diagnosis Feedback Update to June 07) DIS V50 Release Notes Diagnosis Process Diagnosis Process DIS V51 Release Notes
Tools and Equipment Tools	04 04 05 04 07 05 04 07 05 04 08 05 04 13 05 04 14 05 04 14 05 04 14 05 04 12 06 04 02 06 04 04 07 04 07 07 04 01 08 thru - 2106 no value 07-0307/0507-0607/ & 0807-2807 no value 05 01 05 end 07 02 96 07 03 02 07 05 02 07 05 02 07 05 02 07 04 06 07 01 06 07 01 07 B07017_Feedback PDF 07 03 07 07 04 07 07 04 07 07 05 07 07 06 07 07 06 07 07 08 07 07 08 07 07 08 07 07 08 07 07 08 07	January-05 April-05 February-05 March-05 April-05 May-05 November-05 January-06 April-07 December-07 January-08 September-05 June-07 June-04 June-05 November-04 December-05 August-06 October-07 August-07 June-07 August-07 October-07	E60 N52 Engine E60/E63 E61 E60/E63 E90 E60/E63 M - S85 engine Turbocharged All S65/M3 All BMW Centers	Antenna Knife NS2 Special Tools Aluminum Body Tools Tailgate Support CD Eject Tool DME Test Cable AC Sprayer Wand Backlash Gauge Turbocharger Diagnostic Tool Fuel Injection and Induction System Cleaning New Special Tools Teleservice Changing a Customer's Preferred Home Dealer CD42: Updated DISplus & GT1 Software (update to Mar 07) Optical Testing & Programming System - OPPS Online Update Optical Programming System - OPS Software Service Station r2 (SSSr2) Next Generation Workshop Technology - iBase Server Readiness Project Next Generation Workshop Technology - iBase Server Readiness Project Next Generation Workshop Technology DIS v49 Corrections Based on Diagnosis Feedback B070107Diagnosis_Feedback_Corrected_DIS_V49. DIS V50 Corrections Based on Diagnosis Feedback DIS V51 Corrections Based on Diagnosis Feedback DIS V51 Corrections Based on Diagnosis Feedback DIS V51 Release Notes Diagnosis Process DIS V51 Release Notes Importance of Using the Most Current Diagnostic / Programming Software
Tools and Equipment Tools	04 04 05 04 07 05 04 07 05 04 08 05 04 13 05 04 14 05 04 14 05 04 14 05 04 29 05 04 02 06 04 04 07 04 07 07 04 01 08 thru - 2106 no value 07-0307/0507-0607/ & 0807-2807 no value 05 01 05 end 07 02 96 07 03 02 07 05 02 07 05 02 07 05 02 07 01 06 07 01 06 07 01 07 08 070 10 07 08 070 10 07 08 070 10 07 07 05 07 08 070 04 07 07 05 07 07 04 07 07 05 07 07 06 07 07 06 07 07 06 07 07 06 07	January-05 April-05 February-05 March-05 April-05 May-05 November-05 January-06 April-07 December-07 January-08 September-05 June-07 June-04 June-05 November-04 December-05 August-06 January-07 March-07 June-07 August-07	E60 N52 Engine E60/E63 E61 E60/E63 E90 E60/E63 M - S85 engine Turbocharged All S65/M3 All BMW Centers	Antenna Knife NS2 Special Tools Aluminum Body Tools Tailgate Support CD Eject Tool DME Test Cable AC Sprayer Wand Backlash Gauge Turbocharger Diagnostic Tool Fuel Injection and Induction System Cleaning New Special Tools Teleservice Changing a Customer's Preferred Home Dealer CD42: Updated DISplus & GT1 Software (update to Mar 07) Optical Testing & Programming System - OPPS Online Update Optical Programming System - OPS Software Service Station r2 (SSSr2) Next Generation Workshop Technology – iBase Server Readiness Project Next Generation Workshop Technology 3G Use Agreement for 3G Workshop Technology DIS V49 Corrections Based on Diagnosis Feedback B070107Diagnosis Feedback Corrected_DIS_V49, DIS V50 Corrections Based on Diagnosis Feedback DIS V51 Corrections Based on Diagnosis Feedback Update to June 07) DIS V50 Release Notes Diagnosis Process Diagnosis Process DIS V51 Release Notes
Tools and Equipment Tools	04 04 05 04 07 05 04 07 05 04 08 05 04 13 05 04 14 05 04 14 05 04 14 05 04 29 05 04 02 06 04 04 07 04 07 07 04 07 07 04 01 08 thru - 2106 no value 07-0307/0507-0607/ & 0807-2807 no value 05 01 05 end 07 02 96 07 03 02 07 05 02 07 05 02 07 05 02 07 07 03 07 07 04 06 07 01 05 07 01 07 07 03 07 B070107_Feedback PDF 07 03 07 B070307_Feedback PDF 07 05 07 07 04 07 07 05 07 07 06 07 07 08 07 07 08 07 07 08 07 07 08 07 07 10 07	January-05 April-05 February-05 March-05 April-05 May-05 November-05 January-06 April-07 December-07 January-08 September-05 September-05 June-04 June-04 June-05 November-05 August-06 October-06 January-07 March-07 June-07 August-07 August-07 August-07 August-07 August-07 August-07 November-07 November-07	E60 N52 Engine E60/E63 E91 E60/E63 E90 E60/E63 M - S85 engine Turbocharged All S65/M3 All BMW Centers	Antenna Knife NS2 Special Tools Aluminum Body Tools Tailgate Support CD Eject Tool DME Test Cable AC Sprayer Wand Backlash Gauge Turbocharger Diagnostic Tool Fuel Injection and Induction System Cleaning New Special Tools Teleservice Changing a Customer's Preferred Home Dealer CD42: Updated DISplus & GT1 Software (update to Mar 07) Optical Testing & Programming System - OPPS Online Update Optical Programming System - OPS Software Service Station /2 (SSS/2) Next Generation Workshop Technology - iBase Server Readiness Project Next Generation Workshop Technology - iBase Server Readiness Project Next Generation Workshop Technology DIS V49 Corrections Based on Diagnosis Feedback B070107Diagnosis_Feedback_Corrected_DIS_V49. DIS V50 Corrections Based on Diagnosis Feedback USS ORelease Notes Diagnosis Process DIS V51 Release Notes Importance of Using the Most Current Diagnostic / Programming Software DIS V52 Corrections Based on Diagnosis Feedback (December 2007 Release)
Tools and Equipment Tools	04 04 05 04 07 05 04 07 05 04 08 05 04 13 05 04 14 05 04 14 05 04 15 06 04 29 05 04 02 06 04 04 07 04 07 07 04 01 08 thru - 2106 no value 07-0307/0507-0607/ & 0807-2807 no value 05 01 05 end 07 02 96 07 03 02 07 05 02 07 05 02 07 05 02 07 07 04 06 07 01 05 07 01 05 07 01 07 07 03 07 B070307_Feedback PDF 07 03 07 07 04 07 07 05 07 07 08 07 07 08 07 07 08 07 07 08 07 07 10 07 07 13 07 07 13 07 07 15 07 07 15 07 07 15 07 07 15 07 07 15 07 07 15 07 07 15 07	January-05 April-05 February-05 March-05 April-05 May-05 November-05 January-06 April-07 December-07 January-08 September-05 September-05 June-04 June-04 June-05 November-05 August-06 October-06 January-07 March-07 March-07 June-07 August-07 August-07 August-07 August-07 August-07 October-07 November-07 December-07 December-07 June-07 June-07 June-07 June-07 June-07 August-07 August-07 October-07 November-07 December-07 January-08 March-08	E60 N52 Engine E60/E63 E61 E60/E63 E90 E60/E63 M - S85 engine Turbocharged All S65/M3 All BMW Centers	Antenna Knife NS2 Special Tools Aluminum Body Tools Tailgate Support CD Eject Tool DME Test Cable AC Sprayer Wand Backlash Gauge Turbocharger Diagnostic Tool Fuel Injection and Induction System Cleaning New Special Tools Teleservice Changing a Customer's Preferred Home Dealer CD42: Updated DISplus & GT1 Software (update to Mar 07) Optical Testing & Programming System - OPPS Online Update Optical Programming System - OPS Software Service Station 72 (SSS12) Next Generation Workshop Technology – iBase Server Readiness Project Next Generation Workshop Technology 3G Use Agreement for 3G Workshop Technology DIS V49 Corrections Based on Diagnosis Feedback B070107Diagnosis_Feedback_Corrected_DIS_V49. DIS V50 Corrections Based on Diagnosis Feedback USV 50 Release Notes Diagnosis Process DIS V51 Release Notes Importance of Using the Most Current Diagnostic / Programming Software DIS V52 Corrections Based on Diagnosis Feedback (December 2007 Release) DIS V52 Release Notes DIS V52 Corrections Based on Diagnosis Feedback (December 2007 Release) DIS V52 Release Notes DIS V52 Corrections Based on Diagnosis Feedback (December 2007 Release) DIS V52 Release Notes DIS V52 Release Notes DIS V52 Corrections Based on Diagnosis Feedback (March 2008 Release)
Tools and Equipment Tools	04 04 05 04 07 05 04 07 05 04 08 05 04 13 05 04 14 05 04 14 05 04 14 05 04 29 05 04 02 06 04 04 07 04 07 07 04 01 08 thru - 2106 no value 07-0307/0507-0607/ & 0807-2807 no value 05 01 05 end 07 02 96 07 03 02 07 05 02 07 05 02 07 05 02 07 04 06 07 01 06 07 01 06 07 03 07 B07017/ Feedback PDF 07 03 07 07 04 06 07 07 06 07 07 06 07 07 06 07 07 06 07 07 06 07 07 08 07 07 10 07 07 08 07 07 10 07 07 11 08 07 02 08	January-05 April-05 February-05 March-05 April-05 May-05 November-05 January-06 April-07 December-07 January-08 September-05 June-05 November-05 August-06 October-06 January-07 March-07 June-07 August-07 August-07 August-07 Cotober-07 November-07 December-07 December-07 June-07 August-07 August-07 August-07 October-07 November-07 December-07 January-08 March-08	E60 N52 Engine E60/E63 E91 E60/E63 E90 E60/E63 M - S85 engine Turbocharged All S65/M3 All BMW Centers	Antenna Knife NS2 Special Tools Aluminum Body Tools Tailgate Support CD Eject Tool DME Test Cable AC Sprayer Wand Backlash Gauge Turbocharger Diagnostic Tool Fuel Injection and Induction System Cleaning New Special Tools Teleservice Changing a Customer's Preferred Home Dealer CD42: Updated DISplus & GT1 Software (update to Mar 07) Optical Testing & Programming System - OPPS Online Update Optical Programming System - OPS Software Service Station r2 (SSSr2) Next Generation Workshop Technology – iBase Server Readiness Project Next Generation Workshop Technology 3G Use Agreement for 3G Workshop Technology DIS V49 Corrections Based on Diagnosis Feedback B070107Diagnosis, Feedback Corrected, DIS_V49, DIS V50 Corrections Based on Diagnosis Feedback DIS V51 Corrections Based on Diagnosis Feedback Update to June 07) DIS V50 Release Notes Diagnosis Process Dis V51 Release Notes Uis V52 Corrections Based on Diagnosis Feedback (December 2007 Release) DIS V52 Release Notes Uis V53 Changes Based on Diagnosis Feedback (March 2008 Release) DIS V53 Changes Based on Diagnosis Feedback (March 2008 Release) DIS V53 Release Based on Diagnosis Feedback (March 2008 Release) DIS V53 Release Based on Diagnosis Feedback (March 2008 Release) DIS V53 Release Based on Diagnosis Feedback (March 2008 Release)
Tools and Equipment Tools	04 04 05 04 07 05 04 07 05 04 08 05 04 13 05 04 14 05 04 14 05 04 15 05 04 12 05 04 02 06 04 04 07 04 07 07 04 01 08 thru - 2106 no value 07-0307/0507-0607/ & 0807-2807 no value 05 01 05 end 07 02 96 07 03 02 07 05 02 07 05 02 07 05 02 07 01 06 07 01 06 07 01 07 B070107_Feedback PDF 07 03 07 B070307_Feedback PDF 07 03 07 07 04 07 07 04 07 07 05 07 07 06 07 07 06 07 07 08 07 07 08 07 07 10 07 07 11 07 07 11 07 07 13 07 07 15 07 07 10 10 07 01 08 07 02 08 07 05 08	January-05 April-05 February-05 March-05 April-05 May-05 November-05 January-08 April-07 December-07 January-08 September-05 June-07 June-04 June-05 November-04 December-05 August-06 October-07 March-07 August-07 June-07 August-07 December-07 January-08 March-08 March-08 March-08 March-08 March-08	E60 N52 Engine E60/E63 E61 E60/E63 E90 E60/E63 M - S85 engine Turbocharged All S65/M3 All BMW Centers	Antenna Knife NS2 Special Tools Aluminum Body Tools Tailgate Support CD Eject Tool DME Test Cable AC Sprayer Wand Backlash Gauge Turbocharger Diagnostic Tool Fuel Injection and Induction System Cleaning New Special Tools Teleservice Changing a Customer's Preferred Home Dealer CD42: Updated DISplus & GT1 Software (update to Mar 07) Optical Testing & Programming System - OPPS Online Update Optical Programming System - OPS Software Service Station r2 (SSSr2) Next Generation Workshop Technology - iBase Server Readiness Project Next Generation Workshop Technology - iBase Server Readiness Project Next Generation Workshop Technology DIS v49 Corrections Based on Diagnosis Feedback B070107Diagnosis_Feedback_Corrected_DIS_V49. DIS V50 Corrections Based on Diagnosis Feedback DIS V51 Corrections Based on Diagnosis Feedback DIS V51 Corrections Based on Diagnosis Feedback DIS V51 Release Notes Diagnosis Process DIS V51 Release Notes Importance of Using the Most Current Diagnostic / Programming Software DIS V52 Release Notes University of the Programming Software DIS V52 Release Notes DIS V53 Release Notes DIS V54 Changes Based on Diagnosis Feedback (June 2008 Release) DIS V53 Release Notes DIS V54 Changes Based on Diagnosis Feedback (June 2008 Release)
Tools and Equipment Tools	04 04 05 04 07 05 04 07 05 04 08 05 04 13 05 04 14 05 04 14 05 04 14 05 04 29 05 04 02 06 04 04 07 04 07 07 04 01 08 thru - 2106 no value 07-0307/0507-0607/ & 0807-2807 no value 05 01 05 end 07 02 96 07 03 02 07 05 02 07 05 02 07 05 02 07 04 06 07 01 06 07 01 06 07 03 07 B07017/ Feedback PDF 07 03 07 07 04 06 07 07 06 07 07 06 07 07 06 07 07 06 07 07 06 07 07 08 07 07 10 07 07 08 07 07 10 07 07 11 08 07 02 08	January-05 April-05 February-05 March-05 April-05 May-05 November-05 January-06 April-07 December-07 January-08 September-05 June-05 November-05 August-06 October-06 January-07 March-07 June-07 August-07 August-07 August-07 Cotober-07 November-07 December-07 December-07 June-07 August-07 August-07 August-07 October-07 November-07 December-07 January-08 March-08	E60 N52 Engine E60/E63 E91 E60/E63 E90 E60/E63 M - S85 engine Turbocharged All S65/M3 All BMW Centers	Antenna Knife NS2 Special Tools Aluminum Body Tools Tailgate Support CD Eject Tool DME Test Cable AC Sprayer Wand Backlash Gauge Turbocharger Diagnostic Tool Fuel Injection and Induction System Cleaning New Special Tools Teleservice Changing a Customer's Preferred Home Dealer CD42: Updated DISplus & GT1 Software (update to Mar 07) Optical Testing & Programming System - OPPS Online Update Optical Programming System - OPS Software Service Station r2 (SSSr2) Next Generation Workshop Technology – iBase Server Readiness Project Next Generation Workshop Technology 3G Use Agreement for 3G Workshop Technology DIS V49 Corrections Based on Diagnosis Feedback B070107Diagnosis, Feedback Corrected, DIS_V49, DIS V50 Corrections Based on Diagnosis Feedback DIS V51 Corrections Based on Diagnosis Feedback Update to June 07) DIS V50 Release Notes Diagnosis Process Dis V51 Release Notes Uis V52 Corrections Based on Diagnosis Feedback (December 2007 Release) DIS V52 Release Notes Uis V53 Changes Based on Diagnosis Feedback (March 2008 Release) DIS V53 Changes Based on Diagnosis Feedback (March 2008 Release) DIS V53 Release Based on Diagnosis Feedback (March 2008 Release) DIS V53 Release Based on Diagnosis Feedback (March 2008 Release) DIS V53 Release Based on Diagnosis Feedback (March 2008 Release)
Tools and Equipment Tools	04 04 05 04 07 05 04 07 05 04 08 05 04 13 05 04 14 05 04 14 05 04 15 06 04 29 05 04 02 06 04 04 07 04 07 07 04 07 07 04 01 08 thru - 2106 no value 07-0307/0507-0607/ & 0807-2807 no value 05 01 05 end 07 02 96 07 03 02 07 05 02 07 05 02 07 05 02 07 01 05 07 01 06 07 03 06 07 04 06 07 01 07 B070307_Feedback PDF 07 03 07 B070307_Feedback PDF 07 05 07 07 06 07 07 08 07 07 10 07 07 10 07 07 11 07 07 13 07 07 11 07 07 11 07 07 11 07 07 11 07 07 11 07 07 11 07 07 11 07 07 11 07 07 11 07 07 11 07 07 11 07 07 11 07 07 11 07 07 11 07 07 11 07 07 11 07 07 11 07 07 10 08 07 02 08 07 06 08 07 06 08	January-05 April-05 February-05 March-05 April-05 May-05 November-05 January-06 April-07 December-07 January-08 September-05 September-05 June-04 June-05 November-04 December-06 April-07 June-05 November-04 December-07 August-07 August-07 March-07 June-07 August-07 August-07 June-07 August-07 June-07 August-07 June-07 August-07 June-07 June-07 August-07 June-07 June-07 June-07 June-07 June-07 August-07 June-07 June-07 June-07 August-07 August-07 June-07 January-08 March-08 March-08 March-08 August-08 September-08	E60 N52 Engine E60/E63 E61 E60/E63 E90 E60/E63 M - S85 engine Turbocharged All S65/M3 All BMW Centers	Antenna Knife NS2 Special Tools Aluminum Body Tools Tailgate Support CD Eject Tool DME Test Cable AC Sprayer Wand Backlash Gauge Turbocharger Diagnostic Tool Fuel Injection and Induction System Cleaning New Special Tools Teleservice Changing a Customer's Preferred Home Dealer CD42: Updated DISplus & GT1 Software (update to Mar 07) Optical Testing & Programming System - OPPS Online Update Optical Programming System - OPS Software Service Station /2 (SSSr/2) Next Generation Workshop Technology - iBase Server Readiness Project Next Generation Workshop Technology - iBase Server Readiness Project Next Generation Workshop Technology IS 449 Corrections Based on Diagnosis Feedback B070107Diagnosis_Feedback_Corrected_DIS_V49. DIS V50 Corrections Based on Diagnosis Feedback B070107Diagnosis_Feedback_Corrected_DIS_V49. DIS V50 Release Notes Diagnosis Process DIS V51 Release Notes Importance of Using the Most Current Diagnostic / Programming Software DIS V52 Corrections Based on Diagnosis Feedback (December 2007 Release) DIS V52 Release Notes DIS V53 Changes Based on Diagnosis Feedback (March 2008 Release) DIS V53 Release Notes DIS V54 Changes Based on Diagnosis Feedback (June 2008 Release) DIS V55 Changes Based on Diagnosis Feedback (June 2008 Release) DIS V55 Changes Based on Diagnosis Feedback (June 2008 Release) DIS V55 Changes Based on Diagnosis Feedback (June 2008 Release) DIS V55 Changes Based on Diagnosis Feedback (June 2008 Release) DIS V55 Celases Notes
Tools and Equipment Tools	04 04 05 04 07 05 04 07 05 04 08 05 04 13 05 04 14 05 04 14 05 04 14 05 04 29 05 04 02 06 04 04 07 04 07 07 04 01 08 thru - 2106 no value 07-0307/0507-0607/ & 0807-2807 no value 05 01 05 end 07 02 96 07 03 02 07 05 02 07 05 02 07 05 02 07 01 05 07 01 06 07 01 05 07 01 06 07 03 07 B070107_Feedback PDF 07 03 07 B07037_Feedback PDF 07 03 07 07 04 07 07 05 07 07 06 07 07 08 07 07 11 07 07 11 07 07 13 07 07 15 07 07 11 07 07 13 07 07 15 07 07 10 08 07 02 08 07 02 08 07 05 08 07 06 08 07 07 08 08 07 07 08 08 07 07 08 08 07 07 08 08	January-05 April-05 February-05 March-05 April-05 May-05 November-05 January-06 April-07 December-07 January-08 September-05 June-07 June-04 June-05 November-04 December-05 August-06 October-06 January-07 March-07 June-07 August-07 June-07 August-07 August-07 June-07 August-07 June-07 August-07 June-07 September-08 March-08 March-08 May-08 August-08 August-08 August-08 September-08 September-08 September-08	E60 N52 Engine E60/E63 E61 E60/E63 E90 E60/E63 M - S85 engine Turbocharged All S65/M3 All BMW Centers	Antenna Knife NS2 Special Tools Aluminum Body Tools Tailgate Support CD Eject Tool DME Test Cable AC Sprayer Wand Backlash Gauge Turbocharger Diagnostic Tool Fuel Injection and Induction System Cleaning New Special Tools Teleservice Changing a Customer's Preferred Home Dealer CD42: Updated DISplus & GT1 Software (update to Mar 07) Optical Testing & Programming System - OPPS Online Update Optical Programming System - OPS Software Service Station 12 (SSSr2) Next Generation Workshop Technology – iBase Server Readiness Project Next Generation Workshop Technology 3G Use Agreement for 3G Workshop Technology DIS V49 Corrections Based on Diagnosis Feedback B070107Diagnosis Feedback, Corrected_DIS_V49. DIS V50 Corrections Based on Diagnosis Feedback B1S V51 Corrections Based on Diagnosis Feedback DIS V51 Release Notes DIS V51 Release Notes DIS V52 Release Notes DIS V52 Release Notes DIS V52 Release Notes DIS V53 Release Notes DIS V54 Changes Based on Diagnosis Feedback (March 2008 Release) DIS V53 Release Notes DIS V53 Release Notes DIS V54 Changes Based on Diagnosis Feedback (June 2008 Release) DIS V55 Release Notes Notes Technical Data 2.8.0 Changes Based on Diagnosis Feedback Notes Technical Data 2.8.0 Changes Based on Diagnosis Feedback Notes Technical Data 2.8.0 Changes Based on Diagnosis Feedback Notes Technical Data 2.8.0 Changes Based on Diagnosis Feedback Notes Technical Data 2.8.0 Changes Based on Diagno
Tools and Equipment Tools	04 04 05 04 07 05 04 07 05 04 08 05 04 13 05 04 14 05 04 14 05 04 15 05 04 29 05 04 02 06 04 04 07 04 07 07 04 01 08 thru - 2106 no value 07-0307/0507-0607/ & 0807-2807 no value 05 01 05 end 07 02 96 07 03 02 07 05 02 07 05 02 07 05 02 07 04 06 07 01 05 07 01 06 07 01 07 B07017_Feedback PDF 07 03 07 B070307_Feedback PDF 07 03 07 07 04 06 07 01 07 07 05 07 07 06 07 07 06 07 07 08 07 07 10 07 07 11 07 07 11 07 07 11 07 07 15 07 07 10 08 07 02 08 07 05 08 07 06 08 07 07 08 08 07 08 08 07 08 08 07 08 08 07 08 08 07 08 08 07 08 08 07 08 08 07 08 08 07 08 08 07 09 08	January-05 April-05 February-05 March-05 April-05 May-05 November-05 January-06 April-07 December-07 January-08 September-05 June-07 June-04 June-05 November-04 December-05 August-06 October-06 January-07 March-07 June-07 August-07 June-07 August-07 October-07 November-07 December-07 June-07 August-07 August-07 August-07 August-07 October-07 November-08 March-08 March-08 May-08 August-08 September-08 September-08 November-09	E60 N52 Engine E60/E63 E91 E60/E63 E90 E60/E63 M - S85 engine Turbocharged All S65/M3 All BMW Centers	Antenna Knife NS2 Special Tools Aluminum Body Tools Tailgate Support CD Eject Tool DME Test Cable AC Sprayer Wand Backlash Gauge Turbocharger Diagnostic Tool Fuel Injection and Induction System Cleaning New Special Tools Teleservice Changing a Customer's Preferred Home Dealer CD42: Updated DISplus & GT1 Software (update to Mar 07) Optical Testing & Programming System - OPPS Online Update Optical Programming System - OPPS Online Update Optical Programming System - OPS Software Service Station 12 (SSSr2) Next Generation Workshop Technology – iBase Server Readiness Project Next Generation Workshop Technology also Server Readiness Project Next Generation Workshop Technology Us Agreement for 3G Workshop Technology DIS V49 Corrections Based on Diagnosis Feedback B070107Diagnosis_Feedback_Corrected_DIS_V49. DIS V50 Corrections Based on Diagnosis Feedback US V51 Corrections Based on Diagnosis Feedback US V51 Corrections Based on Diagnosis Feedback (Update to June 07) DIS V50 Release Notes Dis V51 Release Notes Dis V52 Corrections Based on Diagnosis Feedback (December 2007 Release) DIS V52 Corrections Based on Diagnosis Feedback (December 2007 Release) DIS V52 Release Notes DIS V53 Changes Based on Diagnosis Feedback (March 2008 Release) DIS V53 Changes Based on Diagnosis Feedback (June 2008 Release) DIS V53 Release Notes DIS V54 Changes Based on Diagnosis Feedback (June 2008 Release) DIS V55 Release Notes DIS V56 Release Notes New ISTA/P Software STA December 2007 Release Notes New ISTA/P Software
Tools and Equipment Tools	04 04 05 04 07 05 04 07 05 04 08 05 04 13 05 04 14 05 04 14 05 04 14 05 04 29 05 04 02 06 04 04 07 04 07 07 04 01 08 thru - 2106 no value 07-0307/0507-0607/ & 0807-2807 no value 05 01 05 end 07 02 96 07 03 02 07 05 02 07 05 02 07 05 02 07 01 05 07 01 06 07 01 05 07 01 06 07 03 07 B070107_Feedback PDF 07 03 07 B07037_Feedback PDF 07 03 07 07 04 07 07 05 07 07 06 07 07 08 07 07 11 07 07 11 07 07 13 07 07 15 07 07 11 07 07 13 07 07 15 07 07 10 08 07 02 08 07 02 08 07 05 08 07 06 08 07 07 08 08 07 07 08 08 07 07 08 08 07 07 08 08	January-05 April-05 February-05 March-05 April-05 May-05 November-05 January-06 April-07 December-07 January-08 September-05 June-07 June-04 June-05 November-04 December-05 August-06 October-06 January-07 March-07 June-07 August-07 June-07 August-07 August-07 June-07 August-07 June-07 August-07 June-07 September-08 March-08 March-08 May-08 August-08 August-08 August-08 September-08 September-08 September-08	E60 N52 Engine E60/E63 E61 E60/E63 E90 E60/E63 M - S85 engine Turbocharged All S65/M3 All BMW Centers	Antenna Knife NS2 Special Tools Aluminum Body Tools Tailgate Support CD Eject Tool DME Test Cable AC Sprayer Wand Backlash Gauge Turbocharger Diagnostic Tool Fuel Injection and Induction System Cleaning New Special Tools Teleservice Changing a Customer's Preferred Home Dealer CD42: Updated DISplus & GT1 Software (update to Mar 07) Optical Testing & Programming System - OPPS Online Update Optical Programming System - OPS Software Service Station 12 (SSSr2) Next Generation Workshop Technology – iBase Server Readiness Project Next Generation Workshop Technology 3G Use Agreement for 3G Workshop Technology DIS V49 Corrections Based on Diagnosis Feedback B070107Diagnosis Feedback, Corrected_DIS_V49. DIS V50 Corrections Based on Diagnosis Feedback B1S V51 Corrections Based on Diagnosis Feedback DIS V51 Release Notes DIS V51 Release Notes DIS V52 Release Notes DIS V52 Release Notes DIS V52 Release Notes DIS V53 Release Notes DIS V54 Changes Based on Diagnosis Feedback (March 2008 Release) DIS V53 Release Notes DIS V53 Release Notes DIS V54 Changes Based on Diagnosis Feedback (June 2008 Release) DIS V55 Release Notes Notes Technical Data 2.8.0 Changes Based on Diagnosis Feedback Notes Technical Data 2.8.0 Changes Based on Diagnosis Feedback Notes Technical Data 2.8.0 Changes Based on Diagnosis Feedback Notes Technical Data 2.8.0 Changes Based on Diagnosis Feedback Notes Technical Data 2.8.0 Changes Based on Diagno

<u>Category</u>	SIBs (SI B## ## ##)	<u>Date</u>	Application	Title
General	07 02 09	July-09	BMW Centers	Activating ISTA in Offline Mode when ISIS is Not Available
Programming/Coding Explainations	09 03 98	May-06	E60/E63/E90	Car & Key Memory (Updated date with additional E90 info Supercedes Nov 05)
Programming/Coding Explainations	B090398_Att5_CKM_E60	P/O 09 03 98	E60/E63	PDF of car and Key memory settings
Programming/Coding Explainations Programming/Coding Explainations	09 05 01 Att3_CBSCheck	March-06 P/O 09 05 01	E60/E63 E60/E63	CIP General Info (Supercedes Dec 05) Condition Based Service Plausibility Check
Programming/Coding Explainations	Att4_CBSCorrct	P/O 09 05 01	E60/E63	Condition Based Service Adjustments based on previous service
Programming/Coding Explainations Programming/Coding Explainations	ProgCoding 09 07 02	P/O 09 05 01 March-03	E60/E63 E65	Detailed Description of programming and coding using CIPs CIP 7.0
Programming/Coding Explainations	09 01 04 09 01 05	January-05	BMW Centers All	Programming Manager
Programming/Coding Explainations Programming/Coding Explainations	09 02 05	May-05 July-05	All	CIP 17.0 Release Notes OBD Replacement Cables for GTI/DISplus Diagnostic Heads
Programming/Coding Explainations	09 03 05 09 04 05	January-07	E90 All	Personal Profile (Replaces 8/05) CIP 18.0 release notes
Programming/Coding Explainations Programming/Coding Explainations	09 04 05	July-05 July-05	E60 w/o NAV	After Programming, CIP shows MASK-H to be replaced
Programming/Coding Explainations Programming/Coding Explainations	09 06 05 09 07 05	August-05 September-05	E60/E63 All	CIP Shows IHKA (Automatic heating & AC) to be Replaced CIP 19.0 and 19.1 release notes
Programming/Coding Explainations Programming/Coding Explainations	09 07 05 09 08 05	October-05	E64 Cabrio	Service Action: Correction to Integration Level
Programming/Coding Explainations Programming/Coding Explainations	09 09 05 09 11 05	November-05 October-06	BMW Centers E60/E63/E90	CIP: Report Recurring Irregularities CCC Fails to Program with CIP 19.x (Supercedes Dec 05, Feb 06, May 06, Aug 06)
Programming/Coding Explainations	09 01 06	February-06	E90	JBE Fails to Program (supercedes Jan 06)
Programming/Coding Explainations Programming/Coding Explainations	09 02 06 09 03 06	January-06 January-06	E90 All	Replacement FZD Not Accepted by CIP/PROGMAN Deciphering and Troubleshooting the Vehicle Order
Programming/Coding Explainations	09 05 06	January-06	E60/E63/E90	Release Notes Progman V20.0 and V20.0.1
Programming/Coding Explainations Programming/Coding Explainations	09 06 06 09 07 06	February-06 January-06	E90 E90/x drives	RAD2 Cannot be Programmed after Programming Abort (Supercedes Jan 06 - Online 20.02.00) DSC Cannot be Encoded
Programming/Coding Explainations	09 08 06	February-06	E90	DWA LED on Rearview Mirror Cannot be Activated
Programming/Coding Explainations Programming/Coding Explainations	09 09 06 09 10 06	March-06 May-06	All All	Release Notes Progman 21.0 Release Notes Progman V21.02 and V21.02.01
Programming/Coding Explainations	09 11 06	May-06	E60	Replacement SZL Not Accepted By Progman
Programming/Coding Explainations Programming/Coding Explainations	09 13 06 09 14 06	June-06 July-06	All E60/E63/E90	Release Notes Progman V22.0 and V22.0.1 Maintenance Interval Retrofit is Not Used in US Market Vehicles
Programming/Coding Explainations	09 15 06	July-06	E90	Personal Profile Settings for Alarm System Missing
Programming/Coding Explainations Programming/Coding Explainations	09 16 06 09 17 06	August-06 December-06	E60/E63/E90 ALL	Release Notes Progman V22.1 and V22.1.1 and V22.1.2 Vehicle Order (VO) Cannot be Adapted Using CIP
Programming/Coding Explainations	09 20 06	October-06	E90	Daytime Running Lamps Switched On after Update with Progman V23
Programming/Coding Explainations Programming/Coding Explainations	09 21 06 09 22 06	October-06 October-06	E90 E60/E63/E90	Satellite Radio Inoperable after Programming with Progman V23 - Need 23.01.03 Coding Function for Headunit Available in Progman V23
Programming/Coding Explainations	09 01 07	January-07	E60/E63/E90	CCC: Programming or Coding Fails with Progman V24
Programming/Coding Explainations Programming/Coding Explainations	09 02 07 B090207Attachment.	October-07 P/O 09 02 07	All w/CCC BMW Centers	CCC: Enabling Code (FSC) Required for Voice Recognition System(update to May 07 B090207Parts_Info_V1_1
Programming/Coding Explainations	09 03 07	June-07	E92	FRM Fails Coding
Programming/Coding Explainations Programming/Coding Explainations	09 04 07 09 05 07	August-07 September-07	ALL w/CCC E90	Programming Failure Due to CD or DVD in Drives CAS2 Programming with Special Measure not Possible
Programming/Coding Explainations	09 07 07	May-09	ALL	Progman Version vs. Vehicle Data Status (update to 1/09) 2.33.02 latest shown
Programming/Coding Explainations Programming/Coding Explainations	09 01 09 09 02 09	April-09 August-09	F01/02 1/3 Series	Programming Fails for the IHKA, FKA, or CON RAD2 Programming with ISTA/P 2.34.2 - No MOST Communication
		_		
	06 other model			
Engine System Engine System	11 08 98 11 04 03	June-06 February-07	All E60	BMW Engine Oils (Includes Annual Change Coverage) (Supercedes Oct 05) Recurring Noise Complaints From Mechanical Alternator Belt Tensioners (Replaces 7/05)
Engine System	11 02 05	January-06	E60/E63	N62 - Rough Idle, Misfire faults after cold start (Supercedes May 05)
Engine System Engine System	11 03 05 11 05 05	June-05 December-06	E60/E63 E60	N62 and N62TU Valve Cover and Valve Cover Gasket Replacement N52 Engine Runs Poorly with Camshaft Sensor and VANOS Faults (Supercedes Novr 06)
Engine System	11 07 05	July-05	E60/E63	N62 and N62TU Water Pump Replacement - corrects installation procedure
Engine System Engine System	11 09 05 11 10 05	April-06 February-06	E60/E63 E60 (M5)	Non-Return Valve Parts Found In Engine Oil Filter During Engine Oil Service Supercedes Dec 05) Service Action: S85 Replace VANOS High Pressure Line (Supercedes Jan 06)
Engine System	11 01 06	March-06	M5/M6	S85 Engine Oil Level and Oil Service Information
Engine System Engine System	Replaced by 11 06 09 11 03 06	December-06 June-06	E60 All w/N62 Engine	NG6 Engines - Front and Rear Radial Crankshaft Seal Replacement Voluntary Emissions Recall 06E-A02: N62 - Crankcase Ventilation Valves Replacement
Engine System	11 04 06	June-06	All	Engine, Transmission, or Clutch Related Complaints
Engine System Engine System	11 06 06 11 07 06	June-06 October-06	M54/M54TU All w/N62 Engine	Head Bolt Threads Pulling Out of Block During Engine Reassembly N62 Engine - Rough Idle at Operating Temperature
Engine System	11 13 06	January-08	E90/E92 w N54	N54 Engine Compression and Cylinder Leakage Test Procedures (rpl 11/06)
Engine System Engine System	11 01 07 11 05 07	October-07 April-07	All with N62 (4.4I) All S85 (V10)	N62 Crankcase Ventilation System – Cold Climate Conditions (rpl 6/07) Service Action: Replace Front Crankshaft Radial Seal
Engine System	11 09 07	July-07	All N52 Engine	Intermittent Hydraulic Valve Adjuster (HVA) "Ticking" or "Rattling" Noises
Engine System Engine System	11 12 07 11 13 07	October-07 May-08	N62/N62TU N54	N62 and N62TU Engine Replacement (after an engine has been replaced) N54 Rattle Noise from Turbocharger Area
Engine System	11 14 07	November-07	N54	N54 Turbocharger Waste Gate Control Noises and Operation
Engine System Engine System	11 01 08 11 02 08	April-08 February-08	E60/E70/E83/3 series N54	Service Action: Replace the Chain Tensioning Rail Bearing Bolt N54: Power Reduction - DME Fault 2A82 VANOS Inlet is Stored
Engine System	11 03 08	November-08	All engines	Crankcase Ventilation System Specification
Engine System Engine System	11 04 08 11 05 08	July-08 August-08	All 1, 3 Series	TeileClearing for Engine Components N51 Engine: Cylinder Head Bolt Torque Is not Available via TIS
Engine System	11 07 08	August-08	E46 1 & 3 Series w/N54	Overheated Engine - Diagnostic Tips Alternator Drive Belt Broken
Engine System Engine System	11 09 08 11 10 08	October-08 October-08	S62 (E39 M5 & Z8)	S62 VANOS Assembly Mode Test Plan
Engine System Engine System	11 01 09 11 03 09	March-09 March-09	All M3 w/S65	CPO Inspection Guidelines - Engine Inspection on Vehicles with Extended ("Overdue") Oil Service Intervals Engine Oil Residue Found Near Oil Filler Cap
Engine System	11 03 09 11 04 09	April-09	3 & X5 w/diesel	Soot Deposits Found Around Turbocharger Waste Gate Shaft Pivot
Engine System Engine System	11 06 09 11 07 09	July-09 August-09	All w/N52, N54 M3 w/S65	NG6 Crankshaft Seal and Bed Plate Sealer Service Action: M3 S65 – Thermostat Housing Inspection
Liigilie Oysteili	11 07 03	August-03	WIS W/505	Service Action: its 300 - Friedmostat Housing inspection
	06 - Alpina B7			
Engine Electrical System	12 01 99	June-06	All	High Performance Platinum Spark Plug/Spark Plug Application Chart
Engine Electrical System Engine Electrical System	12 01 04 12 03 04	October-04 September-04	N62 in E60 M54 in E60	E60 with N62; DME Reprogramming Voluntary Emissions Recall Campaign 04E-A02: Emission Readiness Codes Not Completely Setting
Engine Electrical System	12 04 04	July-04	E60/E63	Safety Recall Campaign 04V-344: DME Replacement on N62/N73 Engines
Engine Electrical System Engine Electrical System	12 05 04 12 09 04	October-05 August-06	E60/E63 All	Voluntary Emissions Recall 04E-A04: Reprogram DME for Oxygen Sensor Diagnostics on E53, E60, Special DME Programming - Shipping Procedure (Replaces 12/04)
Engine Electrical System	12 10 04	December-04	M54 in E60	Intermittent Hesitation While Driving or Intermittent Crank, No Start Situation
Engine Electrical System Engine Electrical System	12 01 05 12 03 05	March-08 September-05	N52 in E60 N62 in E60/E63	High Perf Iridium spark Plugs (rpl 06/06) CBS Oil Message
Engine Electrical System	12 04 05	July-07	N52 in E60	Check Engine light or engine overheats (Supercedes Mar 06)
Engine Electrical System Engine Electrical System	12 06 05 12 08 05	June-05 July-05	N52 in E60 E60	DME FC CDA7 CAN Message Oxygen Sensor
Engine Electrical System	12 11 05	January-06	N62 in E60/E63	Service Action: Reprogramming for Incorrect Oil Service (Supercedes August 05)
Engine Electrical System Engine Electrical System	12 15 05 12 16 05	March-08 September-05	N62 in E60/E63 E60	Map Thermostat faults (rpl 12/07) Mixture is too Lean, Fault codes 2882, 2883
Engine Electrical System	12 17 05	September-05	E60	Engine Power drops at 4000 RPM

Category	SIBs (SI B## ## ##)	<u>Date</u>	<u>Application</u>	<u>Title</u>
Engine Electrical System	12 19 05	October-05	N52 in E60/E90	Service Action: Reprogram for OBD Diagnostic
Engine Electrical System	12 20 05	October-05	E60/E63	Loss of Power while decelerating & turning or coming to stop
Engine Electrical System	12 25 05	December-05	E90	CBS Oil formula (different but similar to E60/63)
Engine Electrical System Engine Electrical System	12 27 05 12 29 05	April-07 March-06	E60/E63 M5	N62TU (4.8L) Pinging and Surging (Supercedes Jul 06) S85 Engine Diagnosis Test Plan Updates (Supercedes Dec 05 - minor change)
Engine Electrical System	12 03 06	February-06	E60/M52	Loss of Power or Intermittent Crank, No Start Situation
Engine Electrical System	12 04 06	February-06	E60/M52	DMTL Diagnosis Test Plan Error
Engine Electrical System	12 06 06	April-07	E60/E90/N52	Voluntary Emissions Recall 06E-A01: N52 - Reprogramming Vehicle for OBD Diagnostic (Supercedes 5/06)
Engine Electrical System	12 07 06	January-07	E60/E90/N52	Service Engine Soon Light Illuminated: FC 2EF4 Map Thermostat (Replaces 5/06)
Engine Electrical System	12 10 06	September-06	E60/E90/N52	Service Engine Soon Lamp Illuminated: FC 2C2D, 2C3D, 2C2E, 2C3E
Engine Electrical System Engine Electrical System	12 12 06 12 16 06	April-07	E60/E63/N62TU E90/E92 w N54	N62TU - Diagnosis for DME FC 2A90 (Supercedes Dec 06) E90, E92 with N54 - Diagnostic for DME FC 29F1/29F2
Engine Electrical System Engine Electrical System	12 18 06	September-06 November-06	Ms	Voluntary Emissions Recall 06E-A04: S85 - DME Reprogramming for OBD Monitoring
Engine Electrical System	12 19 06	October-06	E60/E63/E90	Check Gas Cap Warning with DME FC 2A17 – DMTL, System Error
Engine Electrical System	12 25 06	November-06	All	Fuel Quality Determination (Supercedes August 06)
Engine Electrical System	12 27 06	November-06	E60/N62	DME Fault Codes 278B and 278D
Engine Electrical System	12 28 06	October-06	E60	DME Fault Code 27CD
Engine Electrical System	12 29 06 12 33 06	November-06 October-06	E60/M54	DME Fault Codes 2896, 2877, 2766 Various Complaints Caused by Defective Oil Level Sensor - Diagnostic Hints
Engine Electrical System Engine Electrical System	12 33 06	October-06	E60/E63 E60/M54	E60, M54 - Various Oxygen Sensor FC's Caused by Defective Transmission Harness
Engine Electrical System	12 38 06	October-06	E90	MSV70 - DME, FC 29DA Segment Adaptation
Engine Electrical System	12 40 06	October-06	E60	MS45.1 – Various O2 Sensor Faults Stored in DME
Engine Electrical System	12 42 06	November-06	E60	E60, MS45.1 – DME FC 28A2 and FC 2783
Engine Electrical System	12 43 06	October-06	E60/E63	N62 DME ME9.2.1 Engine Difficult to Restart at Operating Temperatures
Engine Electrical System	12 46 06	November-06	E90/E92 w N54	N54 – Slight Bucking is Felt During Acceleration With a Cold Engine
Engine Electrical System Engine Electrical System	12 47 06 12 49 06	November-06 April-07	E60/E63 E60/M54	Break Out Box Overlay Identification DME MS45 - FC28B2, 28AA, 28AC; Internal RAM Faults (Rpl 11/06)
Engine Electrical System	12 50 06	November-06	E60/E63/E90	OBD II Fault Codes List in TIS
Engine Electrical System	12 51 06	December-06	E92	MSD80 N54 Engine Diagnostic Test Plans Inoperative
Engine Electrical System	12 54 06	December-06	E90/92	N54 CBS4 Oil Service Indicates 25,000 Miles
Engine Electrical System	12 55 06	January-08	E90/92	E90, E92 with N54 - Diagnosis for DME FC 29DC/2FBF (Replaces 1/07)
Engine Electrical System	12 58 06	January-07	E90	Service Action: Replace the Alternator
Engine Electrical System	12 05 07	January-08	E60/E90	Erroneous Low Oil Level Warning Message While Driving (rpl 120/07)
Engine Electrical System Engine Electrical System	12 06 07 12 07 07	September-07 June-07	E90/E92 E90/E92	Voluntary Emissions Recall 07E-A01: N54 - Reprogramming Vehicle (DME) for OBD Diagnostic N51 - Fault 2A43: Valvetronic, Thermal Overload Protection
Engine Electrical System	12 09 07	May-07	M5/M6	Service Engine Soon Light Illuminated: S85 - Various VANOS Related Faults Stored
Engine Electrical System	12 10 07	October-07	E60/E63/N62TU	Service Action: N62TU - Retrofit Engine Compartment Ground Cables - rpl 7/07 (now recall)
Engine Electrical System	12 11 07	July-07	E60/E63/N62TU	N62TU: EDK Throttle Faults - Diagnostic
Engine Electrical System	12 15 07	October-07	3 Series	N52K - Loss of Power
Engine Electrical System	12 16 07	October-07	3 Series	N51 - EAC Sensor Fault 2AD8 is Stored
Engine Electrical System Engine Electrical System	12 18 07 12 22 07	October-07 November-07	3/5 w N54 All	N54: Running Issues with Various Faults in DME TeileClearing (Enhanced Technical Support) for DME
Engine Electrical System	12 23 07	November-07	E70 (X5)	FC 2EF4 Characteristic Map Thermostat
Engine Electrical System	12 25 07	November-07	E70 (X5)	E70 N62TU: Pressure Sensor Fault 2D32
Engine Electrical System	12 28 07	December-07	3/5 w N54	N54 Engine Failsafe: FC 3100, FC 30FE and/or FC 30FF is stored in DME Fault Memory
Engine Electrical System	12 01 08	January-08	3/5 w N52	N52 EDK Throttle Jamming Faults 2D09, 2CED and 2CEC
Engine Electrical System	12 02 08 12 03 08	January-08	3/5 w N54 X5 w N54	N54 - Diagnosis for DME Fuel Injector Faults
Engine Electrical System Engine Electrical System	12 03 08	January-08 February-08	X5 w N62TU	N52K - Diagnosis of DME FC 2E97 N62TU: Fault 2A17 - DMTL System Error is Stored
Engine Electrical System	12 06 08	July-08	1/3 series, X5	CBS4 Oil Service Forecast Displays Due in 25,000 miles
Engine Electrical System	12 09 08	February-08	E60/63/70	Driveability Complaints due to Cooling Fan Relay Failure
Engine Electrical System	12 10 08	April-08	All w N54	N54 – Aftermarket "Engine Performance Tuning" Kits
Engine Electrical System	12 12 08	March-08	3 Series/N52/N52K	DME FC 2A15 Minor Leak and 2A16 Superfine Leak in Evaporation System
Engine Electrical System Engine Electrical System	12 13 08 12 14 08	March-08 May-08	3/5 ser w/M54/N52 New M3 /S65	After Vehicle Repair, Service Engine Soon Lamp Cannot Be Switched Off Service Engine Soon Lamp Is Illuminated, EKP FC 2786, 2787, 2788 (rpl 3/08)
Engine Electrical System	12 15 08	August-08	E65/66	E65, E66 with N62TU - Various Driveability Complaints
Engine Electrical System	12 16 08	June-08	M5/M6 V10	Voluntary Emissions Recall 08E-A02: M5 and M6 with S85 - OBD Communication
Engine Electrical System	12 17 08	June-08	E65/66	Service Action: E65 and E66 with N62, N62TU, or N73 – OBD Communication
Engine Electrical System	12 18 08	June-08	All w/N54	Service Action: N54 Oil Level Programming
Engine Electrical System Engine Electrical System	12 19 08 12 20 08	June-08 June-08	M5/M6 V10 All w/N54	S85 - Power Reduction with Idle Actuator Faults Stored N54 - Various Complaints Caused by Aftermarket "Tuning Kits"
Engine Electrical System	12 21 08	July-08	M5/M6	S85 - DME Fault 2742/2743 for O2 Sensor
Engine Electrical System	12 23 08	July-08	E65/66/B7	Service Action: E65 and E66 with N62, N62TU, or N73 - OBD Communication
Engine Electrical System	12 24 08	September-08	E65/66/B7	Service Action: E65 and E66 with N62TU or N73 – OBD Communication
Engine Electrical System	12 25 08	September-08	1/3/5 series & X6	Charge Air Pressure Control B1214_D16LDRN Test Plan Is Inoperative
Engine Electrical System Engine Electrical System	12 26 08 12 27 08	October-08 October-08	All w/N54 & N63 engine All w/N54 & N63 engine	e Injector Removal, Installation, and Replacement Procedures
Engine Electrical System	12 27 08	December-08	S65 / S85	S65 / S85 Rough Running During the Catalyst Heating Phase
Engine Electrical System	12 01 09	February-09	1,3,5/X5	Service Engine Soon Lamp or Check Gas Cap Warning Illuminated
Engine Electrical System	12 02 09	February-09	1,3,5,6/X5,X3	Service Engine Soon or Check Gas Cap Warning Is Illuminated: Tank Leakage
Engine Electrical System	12 03 09	March-09	X5 (E70)	The Engine Oil Level Is Displayed as Overfilled
Engine Electrical System	12 04 09	February-09	M3 w/S65	M3 S65 - Diagnosis for DME Fault Code 2AFD
Engine Electrical System	12 05 09	April-09	5 Series	N54 E60, E61- Misfire Faults Are Stored due to DME Software Errors
Engine Electrical System Engine Electrical System	12 06 09 12 07 09	April-09 April-09	1, 3 series 1, 3 series	N54 E9x, E82, E88 - Misfire Faults Are Stored due to a DME Software Error N51 – Service Engine Soon Lamp Is On with Fault Code 2A38 Stored
Engine Electrical System Engine Electrical System	12 09 09	May-09	3 & X5 w/diesel	M57Y – The Service Engine Soon Lamp (MIL) Is On with Fault Codes 46CE, 4D11, or 4D12 Stored
Engine Electrical System	12 10 09	February-09	3 & X5 w/diesel	E90, E70 M57Y Diesel - Diagnosis for DDE FC 4521/4530
Engine Electrical System	12 11 09	April-09	F01/02 w/N63	Service Action: Program Control Units (DME)
Engine Electrical System	12 12 09	April-09	X6 w/N63	Service Action: Program Control Units (DME)
Engine Electrical System	12 13 09	March-09	M3 w/S65	M3 S65 - Various Oxygen Sensor Faults Stored in DME Memory
Engine Electrical System Engine Electrical System	12 14 09 12 17 09	June-09 May-09	M57Y Eng X5/X6	M57Y Diesel; Service Engine Soon Lamp Illuminated - No Faults Stored Water Is Leaking into the Electronics Box
Engine Electrical System Engine Electrical System	12 17 03	May-09	X5	Service Action: Program Control Units (DME – DMTL Diagnosis)
Engine Electrical System	12 21 09	June-09	F01/02 w/N63	Loss of Power, Extended Engine Cranking, or Engine Cranks But Does Not Start

no 04, 06, 07, 08 02, 03, 04, 12, 13, 20, 24, 26 other models, 01, 14, 19, 21, 27 NU

	02, 00, 01, 12, 10, 20, 21, 20 04.01 11040.0, 01, 11, 10, 2	,		
Fuel Systems	13 01 04	July-04	E60/E63 (V8)	Recall Campaign 04V- 303: Retaining Clip Retrofit for the Fuel Line Quick Release Coupling
Fuel Systems	B130104Q&A	P/O 13 01 04	E60/E63 (V8)	Q&A
Fuel Systems	13 01 06	September-06	All	Alcohol Fuel Blends in BMW Vehicles (replaces March 06)
Fuel Systems	13 02 06	September-06	All	TOP TIER Detergent Gasoline in BMW Vehicles (Replaces 03/06)
Fuel Systems	13 03 06	May-06	All	Fuel Pump Failure after Refueling with Ethanol Fuel Blend
Fuel Systems	13 04 06	August-06	All	Alcohol Detection Procedure
Fuel Systems	13 05 06	September-06	All	BMW Group Fuel System Cleaner Plus (Supercedes Aug 06)
Fuel Systems	13 06 06	November-06	E90/E92	High Precision Injection (HPI) Information and Service Procedures
Fuel Systems	13 07 06	November-06	ALL	Gasoline Quality & Detergent Additives - Customer Information Brochure
Fuel Systems	13 01 07	March-09	ALL/ex turbo	Fuel Injection and Induction System Cleaning (rpl 12/07)
Fuel Systems	13 02 08	September-08	E90/92/93/w N54	Service Action: Replace the High Pressure Pump
Fuel Systems	13 03 08	September-08	E90/92/93/w N54	Service Action: Replace the High-Pressure Pump (older vehicles)
Fuel Systems	13 05 08	February-09	E90/92/93 M3	Rough Idle, Rough Running, Misfiring and Loss of Power (rpl 12/08)
Fuel Systems	13 02 09	March-09	X5d	E70 M57Y Diesel - Diagnosis for Low Pressure Fuel Supply Faults
Fuel Systems	13 04 09	March-09	All w/N54	N54 - Cold Start Rough Running with Misfire Fault
Fuel Systems	13 05 09	April-09	All w/N54	N54 - Diagnosis for FC 2AAF
Fuel Systems	13 06 09	June-09	All port inj	Fuel Injection and Induction System Cleaning - Customer Information Brochure

			Complied and edited	by cobladav
Category	SIBs (SI B## ## ##)	<u>Date</u>	<u>Application</u>	<u>Title</u>
Fuel Systems	13 07 09	June-09	All w/N54	N54 - Diagnosis for "Long Crank" Complaint
Fuel Supply	16 02 05	March-05	E60/E63	Fuel Tank Difficult to Refuel
Fuel Supply	16 01 06	September-06	E90	Fuel Level Sensor Repair Procedure w/N54
Fuel Supply	16 03 06	October-06	E90	Vehicle is Difficult to Refuel
Fuel Supply	16 06 06	October-06	E60	Humming/Buzzing Noise from Center Dash Area When Accelerator is Depressed
Fuel Supply	16 08 06	February-07	E90	N51 PZEV - Erroneous Fuel Gauge Reading (Replaces 12/06)
Fuel Supply	16 01 07	August-07	All	Testing Evaporative Systems for Leaks
Fuel Supply	16 02 07	December-07	E70 (X5)	Service Action: Repair the Fuel Tank Level Sensor
Fuel Supply	16 01 08	September-08	All w/N54	DMTL Tank Leakage Test Module Provides Inaccurate Results
Fuel Supply Fuel Supply	16 03 08 16 01 09	January-09 May-09	E90/X5 w/d X3/3 w/d	Diesel Misfueling Protection Bypass Adapter DEF Extraction and Refill
ruei Suppiy	10 01 09	Way-09	A3/3 W/U	DEF Extraction and Reilli
	- 02 other models			
Cooling Systems	17 01 07	October-07	ALL	BMW Long-Term Antifreeze/Coolant: Maintenance, Repairs and Replacement Requirements
Cooling Systems	17 01 08	July-08	E9x M3	Low Coolant Warning Lamp is Illuminated
Cooling Systems	17 01 09	June-09	X5 (E70)	Service Action: E70 N52K Coolant Hose Seal Plug Retrofit
Cooling Systems Cooling Systems	17 02 09 17 03 09	July-09 July-09	E70/E90 w/d E70/E90 w/d	Oil Leak from Turbocharger Charge Air Hose N63 Turbocharger Auxiliary Water Pump Faults
Cooming Cystems	17 00 00	ouly 05	L10/L30 W/G	100 Fulborial get Adamaty Water Fullip Fullio
Objects	04.00.00	0-1-100	E00 (ME)	OOF OMO Transmission Forths 4FAO 4FOO and Obtablis Demand
Clutch Clutch	21 02 06 07 for Z4	October-06 May-07	E60 (M5) Z4	S85 - SMG Transmission Faults 4FA0, 4F80 and Clutch is Damaged Service Action: Clutch Fork Lever Inspection
Cidicii	07 101 24	Way-07	24	Service Action. Clater in the Level Inspection
Drive Shaft	26 01 06	June-07	E65/E66	Noise from Driveshaft Area (Rpl 06/06)
Drive Shaft	26 01 08	July-08	3 Series Xi	Service Action: Replace Front Propeller Shaft Bolts (Build 12/07)
Manual Transmission	23 01 05	November-05	E60/M5	E60 M5 - CAN Communication Fault FFFF
Manual Transmission	23 01 06	February-06	M Cars	SMG III: Fault Code 5101 Analyze Hydraulic Sensor (Supercedes Jan 06)
Manual Transmission	23 02 06	January-06	SMG Tranny	Towing Vehicles with SMG Transmissions
Manual Transmission	23 03 06	April-07	M Cars	Getrag SMG Transmission Repair & Replacement Information (SMG II and III) (Rpl 02/06)
Manual Transmission	23 04 06	April-06	E60/E63	ZF SMG FC 4F6F - Hydraulic Pump Failure (Supercedes Mar 06)
Manual Transmission Manual Transmission	23 07 06 23 08 06	February-07 January-07	M Cars All SMG Cars	M5, M6 with SMG III; FC 4F42/4F43 - Hydraulic Unit Faults (Replaces 12/06) SMG - Service Functions Performed after Drivetrain Repairs
Manual Transmission	23 09 06	January-07	All non M SMG	ZF SMG - Replacement Parts Availability
Manual Transmission	23 01 07	August-07	\$85 M5	Service Action: Replace SMG Hydraulic Unit Electric Motor on M5 Vehicles (rpl 7/07)
Manual Transmission	23 02 07	March-08	E60/E63	Voluntary Emissions Recall 07E-A02: SMG Reprogramming
Manual Transmission	23 03 07	December-07	ZF SMG	TeileClearing (Enhanced Technical Support) for ZF SMG Transmissions
Manual Transmission	23 01 08	May-08	Many	Vehicles equipped with Manual Transmissions manufactured by Getrag:
Manual Transmission	23 02 08	July-08	E46	E46, E85 with M54 and ZF SMG - OBD Communication
Manual Transmission	23 03 08	December-08	M5/M6	M5, M6 with SMG III; FC 4F82/4F83/4F84/4F85 - Gear Blocking Faults (rpl 10/08)
Manual Transmission	23 01 09	May-09	1/3 series	Gears Difficult to Select in 6-Speed Manual Transmission - Diagnostic Hints
	- 06 other model			
Automatic Transmission	24 08 03	November-04	E60	EGS Fault 4F6A
Automatic Transmission	24 02 05	April-06	E60	Service Action: Replace Mechatronic Adapter (Supercedes May 05
Automatic Transmission Automatic Transmission	24 03 05 24 06 05	February-07 November-05	E60/E63 E60/E63	Harsh 2-1 Downshift (Replaces 6/05) Safety Recall Campaign 05V-504: Parking Lock Guide Plate
Automatic Transmission	B240605CustomerLetter	P/O 24 06 05	E60/E63	Recall Letter
Automatic Transmission	B240605Q&A.	P/O 24 06 05	E60/E63	Q&A
Automatic Transmission	24 06 06	October-06	E90	A Slight Bump is Felt Shortly after the Vehicle Comes to a Stop (Supercedes Aug 06)
Automatic Transmission	24 11 06	October-06	E92	E92; N54 with 6HP16 - Diagnosis for EGS FC 511B
Automatic Transmission	24 04 07	April-07	E90/E91/E92	ZF 6HP19TU in Failsafe Mode with Fault 4F8D Stored
Automatic Transmission	24 09 07	April-07	E90/E91/E92	The Service Engine Soon Light is on and EGS Fault CF1C Stored
Automatic Transmission	24 10 07	May-08	E60/3 Series	The Transmission is in "Failsafe" mode with EGS Fault CF33 Stored - rpl 4/07
Automatic Transmission Automatic Transmission	24 11 07 24 13 07	April-07 June-07	3 Series All STEP Equipped	GM6 - 6L46R Transmission Adaptations and Terminology (info only) Various Complaints Due to Poor Connection at Transmission Connector
Automatic Transmission	24 19 07	December-08	E60	Drive Position "D" Cannot be Engaged - rpl 6/08
Automatic Transmission	24 20 07	October-07	3 Xi	6L45R Transmission with AWD Leaks from the Selector Shaft Seal
Automatic Transmission	24 21 07	January-09	3 Series	Diagnosis - DME Fault CDB4: No Message (transmission data 3, 3B1)
Automatic Transmission	24 22 07	October-07	3 Series	6HP19TU (6HP21) - Fault 5087: One-Touch Hardware is Stored
Automatic Transmission	24 23 07	February-08	All STEP Equipped	6-Speed Automatic Transmissions Diagnosis and Troubleshooting Hints (rpl 12/07)
Automatic Transmission	24 01 08	December-08	E65/66	E65, E66 with 6HP26 - Diagnosis for EGS FC 4F81 - rpl 2/08
Automatic Transmission	24 02 08	September-08	E60/63/70	Driveability Complaints due to Cooling Fan Relay Failure - rpl 2/08
Automatic Transmission Automatic Transmission	24 03 08 24 04 08	June-09 September-08	E9x/E60 E70 (X5)	E60, E9x with N54 and 6HP19TU - Jolt and Delay when Pulling Away (rpl 1/09) E70, X5 3.0i with N52K and 6HP19TU - Transmission Driveability Complaints - rpl 7/08
Automatic Transmission Automatic Transmission	24 04 08	August-08	E65/66	E65, E66 with N62TU - Various Driveability Complaints
Automatic Transmission	24 06 08	October-08	E65/66	E70, X5 4.8i with N62TU and 6HP26TU - Various Driveability Complaints
Automatic Transmission	24 08 08	December-08	E60/61/X5(E70)	E6x with 6HP19TU - Transmission Clunks after Engine Start - rpl 10/08
Automatic Transmission	24 09 08	October-08	E60/61 & X5	GWS - Transmission Jumps Back to Neutral
Automatic Transmission	24 01 09	May-09	X5	E70 with ZF 6HP26TU - Delayed Up-shift in Hill Program
Automatic Transmission	24 03 09	April-09	E60/E63	550i and 650i with N62TU and 6HP26 - Various Drivability Complaints
	24 process info			
Gear Shift Mechanism	25 01 07 25 03 07	January-07	E70	Service Action: Gear Shift Knob Replacement
Gear Shift Mechanism Gear Shift Mechanism	25 02 07 25 03 07	November-07 November-07	E60	Diagnostic for GWS Faults - Drive Position "D" Cannot be Engaged Sport Transmission Paddle Shifters Inoperative - Diagnosis
Gear Shift Mechanism Gear Shift Mechanism	25 03 07 25 01 08	June-08	E60/E63 M5/M6	M5, M6 with SMG III - Gear Selector Display Position Changes from N to R (3-7/07)
Gear Shift Mechanism	25 01 09	February-09	E6x	E6x GWS: Gears D or R Cannot Be Selected
Gear Shift Mechanism	25 02 09	April-09	X5/X6	E70, E71 GWS - Gears Intermittently Cannot Be Engaged
	14 - 18 other models			
Double-clutch Transmission with Driv	28 01 08	June-09	M3	M Double-clutch Transmission with Drivelogic Fluid Requirements (rpl 5/08)
Double-clutch Transmission with Driv	28 01 08	June-09 May-09	M3	TeileClearing for M DCT Drivelogic (double-clutch) Transmission (rpl 7/08)
Double-clutch Transmission with Drivelo	28 03 08	July-08	M3	M Double-Clutch Transmission with Drivelogic - Transmission Filling and Fluid Level Checking Procedure
Double-clutch Transmission with Drivelo	28 04 08	November-08	M3	M Double-Clutch Transmission with Drivelogic Transmission Replacement Procedure
Double-clutch Transmission with Drivelo	28 05 08	October-08	M3	M3 with DCT with Drivelogic – Gearbox Emergency Program with FC 5060
Double-clutch Transmission with Drivelo	28 06 08	November-08	М3	Recall Campaign 08V-595: M3 with M DCT – Reprogramming for Incorrect DCT Clutch Operation
Double-clutch Transmission with Driv	28 07 08	June-09	M3	M3 with M DCT - Complaint of Delayed Throttle Response
Double-clutch Transmission with Drivelo	28 01 09	March-09	M3	M3 with M DCT – Gearbox Warning Lamp with FC 5A87, 5A81 or 5A5B
Front Axle	31 02 04	August-04	All	Rattling Noise From Front or Rear Axle

<u>Category</u> Front Axle	SIBs (SI B## ## ##) 31 02 06	<u>Date</u> June-06	Application E60/E63	<u>Title</u> Recall Campaign 06V-187 : Front Axle Control Arm and Tension Strut Fasteners
Front Axle Front Axle	31 03 06 31 01 07	November-06 January-08	E90 E70 (X5)	Recall Campaign 06V-400: Check Tightening Torque of Front Axle Control Arms and Tie Rods Knocking Noise from Front Suspension
Front Axle	31 01 08	November-08	E53 (X5)	E53 (X5) - Replacement of Front Outer CV Joint (rpl 10/08)
Front Axle	31 01 09	February-09	1, 3 ser not M3	Creaking or Groaning Noise During Compression and/or Rebound of Front Axle
Front Axle	31 02 09	June-09	E46/x	E46 All-wheel Drive - Replacement of Front Outer CV Joint
Steering and Wheel Alignment Steering and Wheel Alignment	32 01 05 32 04 05	July-05 June-05	E60 E60	Power Steering Assist Enhancement Steering Column Comfort Exit Feature
Steering and Wheel Alignment	32 07 05	September-05	E60/E63	Active Front Steering, Noise Fault Code 613E
Steering and Wheel Alignment	32 13 05	October-05 October-05	E60/E63	Active Front Steering, Fault Code 6141
Steering and Wheel Alignment Steering and Wheel Alignment	32 14 05 32 01 06	February-06	E60/E63 E90	Active Front Steering Sensitivity Service Action: Install Clip for Power Steering Line
Steering and Wheel Alignment	32 04 06	February-06	E60/E63	AFS Programming
Steering and Wheel Alignment Steering and Wheel Alignment	32 05 06 32 06 06	March-06 March-06	E90 E60/E63	Steering Wheel Offset Steering Angle Sensor Adjustment
Steering and Wheel Alignment	32 07 06	April-06	E90/91	Steering Column Clicking Noise
Steering and Wheel Alignment Steering and Wheel Alignment	32 04 07 32 07 07	May-08 January-08	ALL E60/E70	TeileClearing (Enhanced Technical Support) for Steering Systems Active Front Steering (AFS) Warning Lamp; Fault Code 6141 stored
Steering and Wheel Alignment	32 01 08	January-08	E70 (X5)	Active Steering Troubleshooting Procedures
Steering and Wheel Alignment	32 02 08	August-08	M5/M6	Repair Instructions for Power Steering Pump and Pressure Line
Steering and Wheel Alignment Steering and Wheel Alignment	32 04 08 32 06 08	January-09 October-08	1,3,5,6 & X5 X5/X6	Active Steering (AL) Warning Lamp Illuminated, Fault Code 6149 Stored Clicking Noise during Steering Column Adjustment
Steering and Wheel Alignment	32 07 08	March-09	E46/53/60/61/83	Squeaking Noise from the Steering Gear
Steering and Wheel Alignment Steering and Wheel Alignment	32 08 08 32 10 08	November-08 August-08	X5/X6 All	Steering Column Position Is Lost with Easy Entry Wheel Alignment Data
Steering and Wheel Alignment	31 01 09	May-09	3 series	Heated Steering Wheel Malfunction (rpl March/09)
		no 05, 06		
Rear Axle	33 01 02	March-08	M Cars	Grinding Noise from the Differential during Slow Cornering
Rear Axle Rear Axle	33 01 06 33 02 06	April-06 September-06	E60 (M5) E60/E63/E65	Grating Noise from Differential During Slow Cornering Recall Campaign 06V-277: Inspect Rear Shock Absorbers (Supercedes Aug 06)
Rear Axle	33 01 07	October-07	E60 - M5	E60 M5 Howling Noise from Rear Axle Area
Rear Axle Rear Axle	33 01 08 33 02 08	March-08 April-08	3 series M/S65 E70 (X5)	E90, E92, E93 M3 - "Clunk Noise" on Load Reversal Recall Campaign 08V-170: Replace Rear Stabilizer Bar (mfr March 08)
Rear Axle	33 03 08	April-08	All models	Differential Cover Sealer
Rear Axle Rear Axle	33 04 08 33 05 08	October-08 August-08	1,3,5,6,7 ser & Z4 X5, X6	Clicking or Cracking Noise from Rear Differential Cracking or Banging Noise from Rear Axle
Rear Axle	33 07 08	December-08	E36/46/Z4/9x/82	Rear Spring Repair Procedures
Rear Axle Rear Axle	33 08 08 33 09 08	December-08 December-08	X6 X6	Oil Ageing No Communication with ICM After Programming
Rear Axle	33 01 09	May-09	X6	Differential Output Flange Loose (QMVH)
Rear Axle	33 02 09	May-09	Х6	Rattle from Rear Suspension
Brakes	34 06 05	July-05	E90	DSC MK60E5 Fault Codes: 5DB6, 5DC6, 5E30, 5D8F
Brakes Brakes	34 02 06 34 04 06	March-06 April-07	E60/E63 E60/E63/E90	Brake Squeals DSC Warning - Various SZL FCs Stored (Supercedes Jun 06)-Changed to e90 only??
Brakes	34 05 06	September-06	E60/E63	Service Action: Replace SZL Optical Element (Made Svc Action)
Brakes Brakes	34 02 07 34 03 07	September-07 September-07	E70 (X5) E70 (X5)	Recall Campaign 07V-391: Inspect the Brake Fluid Reservoir Cap DSC Warning Lamp Illuminated
Brakes	34 04 07	October-07	E60/E63	DSC/DXC Warning Lamp, Fault Code 5EBA (may - June 07 production)
Brakes Brakes	34 05 07 34 06 07	October-07 November-07	E70 (X5) E90/91/92/93	Replacement of the Parking Brake Module (EMF) Additional Effort Required to Press Brake Pedal Prior to Engine Initial Start
Brakes	34 07 07	November-07	M5/M6	M5, M6 - DSC Disabling Function
Brakes Brakes	34 01 08 34 02 08	April-08 April-08	E70 (X5) 3 Series	The Parking Brake Warning Is Illuminated and Fault Code 6032 Is Stored Erroneous Brake Pad Replacement Message
Brakes	34 03 08	May-08	E65/66	Parking Brake Repair Instructions
Brakes Brakes	34 05 08 34 07 08	August-08 August-08	All X5/X6	Brake Rotor Minimum Thickness (Insp Only Spec 2.4mm non-M) Parking Brake Warning Illuminated; Fault Code 600D and/or 600B Is Stored
Brakes	34 08 08	October-08	X5/X6	Brake Squeal from Pad Wear Sensor (rpl 8/08)
Brakes Brakes	34 09 08 34 10 08	October-08 November-08	E60/E63 E9x & M3	Brake Squeak from Pad Wear Sensor Rattle Noise from Front Wheel Area
Brakes	34 11 08	December-08	1, 3 series & Z4	TeileClearing for Dynamic Stability Control (DSC)
Brakes	34 12 08	April-09	Х6	TeileClearing for Integrated Chassis Management (ICM)
Wheels and Tires Wheels and Tires	36 01 04 36 02 05	August-05 July-05	BMW Center E60	Hunter GSP97BMW Wheel Balancer - Features and Operator Training Noise and/or Vibration Caused by Irregular Tire Wear
Wheels and Tires	36 04 05	October-05	E60	Erroneous Flat Tire Monitor Warning
Wheels and Tires Wheels and Tires	36 05 05 36 06 05	June-05 May-05	All E60	Tire Pressure Monitoring Systems (TPMS) Wheels - Different between X models and regular models
Wheels and Tires	36 04 06	April-06	E60	Nitrogen Inflated Tires
Wheels and Tires Wheels and Tires	36 02 07 36 03 07	September-07 September-07	3 Series All	Service Action: Reprogram the Control Module for the Tire Pressure Monitoring System (RDC) Flat Tire Monitor System (FTM) Diagnosis
Wheels and Tires	36 01 08	August-08	All	Tire Pressure Warning Caused by Damaged Wheel Electronics
Wheels and Tires	36 02 09	June-09	5 series	Retrofit Spare Tire and Jack Kit
Suspension	37 02 05	August-05	E60/E63	Anti-Roll Stabilization Noise
Suspension Suspension	37 01 06 37 01 07	March-06 November-07	E61 E70 (X5)	Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension
Suspension	37 02 07	October-07	E70 (X5)	The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored
Suspension	37 03 07 37 01 09	January-08 April-09	E70 (X5) E61	Dynamic Drive (ARS) Front Sway Bar Repairs Self-leveling Suspension Faults
Suspension Suspension	37 01 09 37 02 09	May-09	X6	Seir-leveling Suspension Faults Rattle from Rear Axle
Body Body	41 01 05 41 05 06	May-05 February-06	E60/E63 E60/E63	Structural Aluminum Repair Precautions Trunk Lid Opens Too Fast/Slow
Body	41 02 07	October-07	E70(X5)	Water Leak from the Upper Tailgate Area
Body Body	41 01 08 41 02 08	April-08 March-09	E90/91 X5, X6	Rear Door Brake Connection Pulls out of the B-pillar Service Action: Remove Excessive Underbody Coating
Body	41 01 09	June-09	E46	Rear Axle Support Inspection
Body	41 02 09	June-09	E46	Rear Axle Carrier (Sub-frame) Support Proposed Class Action Settlement

			Compiled and edited	by cobradav
Category	SIBs (SI B## ## ##)	<u>Date</u>	Application	<u>Title</u>
Body Equipment	51 13 04	August-07	E60/E63	Rattling Noise from Center Display (Replaces 06/07)
Body Equipment	51 02 05	February-07	E60	Squeaking Noise from Door Frame area While Driving (Replaces 12/06)
Body Equipment	51 04 05 51 02 05	June-05	E60/E61 (xi, xiT)	Incorrect or Missing Floor Mats (deliveries before May 16, 05)
Body Equipment Body Equipment	51 08 05 51 17 05	July-05 July-05	E60/E63 E60	Door Mirror Glass Discolored after Programming Replacement Windshield - VIN Window in Wrong Position
Body Equipment	51 30 05	October-05	E90	Cracking or Ticking Noise from Lower B-Pillar
Body Equipment	51 31 05	March-06	E90	Center Console Heats Up In Knee Contact Area (Supercedes Nov 05)
Body Equipment	51 32 05	October-05	E90	Clicking Noise from Upper B-pillar Trim
Body Equipment	51 33 05	October-05	E90	Water Ingress from A/C Blower Housing
Body Equipment	51 37 05	December-05	E90	The cup holder jams when retracted
Body Equipment	51 10 06	May-07	E60	Anti-trap is Activated when Raising the Front Window (rpl 2/06)
Body Equipment Body Equipment	51 14 06 51 18 06	March-08 May-07	3 series/X5 E9x series	Outside Door Handles Hanging up in the Pulled Position (rpl 2/08) Interior Door Grab Handle Finish Peeling (rpl 8/06)
Body Equipment	51 24 06	November-06	E61	Luggage Compartment Roller Cover Malfunction
Body Equipment	51 27 06	January-07	E92	Rattle Noise from B-Pillar Trim
Body Equipment	51 06 07	March-07	E60 - M5	Service Action: Replace Underbody Panel
Body Equipment	51 08 07	March-07	E90/E91/E92	Erroneous Trunk Lid Open Check Control Message
Body Equipment	51 10 07	April-07	E90/E92/E93	Rear Window will not Fully Defrost
Body Equipment	51 12 07	May-07	E93	Service Action: Install Luggage Compartment Labels
Body Equipment	51 14 07 51 16 07	June-07	E93 E93	Center Console Lock Inoperative
Body Equipment Body Equipment	51 17 07	July-07 July-07	E93	Rear Roundel Emblem Comes Loose Rear Window(s) Inoperative
Body Equipment	51 19 07	November-07	E90	Doors will not Unlock Using the Key Fob or Central Locking Button (rpl 09/07)
Body Equipment	51 22 07	September-07	E91	Creaking Noise from the C-Pillar Area
Body Equipment	51 24 07	November-07	E93	Water Leaks into the Sides of the Luggage Compartment
Body Equipment	51 25 07	November-07	3 series	Floor Mat Retainer in Wrong Location
Body Equipment	51 28 07	December-07	E93	Compass Changes Direction when Operating the RHT
Body Equipment	51 29 07	December-07	E61	Luggage Compartment Roller Cover Symptom Diagnosis
Body Equipment	51 30 07	December-07	E91	Noises from the Roller Cover Retainers Tailgate Soft-close Malfunction
Body Equipment Body Equipment	51 31 07 51 32 07	December-07 January-08	E70 (X5) E70 (X5)	Rattle from the Upper Tailgate Trim
Body Equipment	51 32 07 51 35 07	January-08	E70 (X5)	Tailgate Latch Noisy when Closing
Body Equipment	51 02 08	February-08	3 series	Compass is Difficult to Read at High Temperatures
Body Equipment	51 03 08	February-08	E91	Luggage Compartment Roller Cover Symptom Diagnosis
Body Equipment	51 04 08	April-08	E93	RHT Rear Roof Shell Headliner Eliminated
Body Equipment	51 05 08	April-08	E60/63	Door Opening/Closing Symptom Diagnosis
Body Equipment	51 06 08	March-09	1 Series	Window Short-drop or Anti-trap Malfunctions
Body Equipment	51 07 08	May-08	E93	Rear Windows Inoperative After Junction Box Replacement
Body Equipment	51 08 08	May-08	E60/63	Power Window Drives: Symptom Diagnosis
Body Equipment	51 09 08 51 10 08	May-08	1 Series E60/63	Instrument Panel Symptom Diagnosis
Body Equipment Body Equipment	51 11 08	May-08 May-08	E63	Noises from the Front Doors - Symptom Diagnosis Water Ingress at the Doors: Symptom Diagnosis
Body Equipment	51 12 08	May-08	1 Series	Rattle from the Armrest Hinge
Body Equipment	51 16 08	June-08	3 series	Hood Insulation Pad Discontinued
Body Equipment	51 17 08	August-08	X5/X6	Grating Noise from the Instrument Panel
Body Equipment	51 18 08	June-08	3 series	Instrument Panel Symptom Diagnosis
Body Equipment	51 19 08	July-08	3 series	Passenger Side Floor Mat Curling
Body Equipment	51 20 08	July-08	Х3	Doors Will Not Unlock with the Remote or Central Locking Switch
Body Equipment	51 21 08	July-08	1 Series vert	Squeak from Rear Trim with the Convertible Top Open
Body Equipment	51 23 08 51 24 08	July-08	1 Series vert	Clicking Noise from the Bottom of the A-pillar
Body Equipment Body Equipment	51 24 08 51 25 08	September-08 September-08	M3 1 Series	Washer Fluids Leaking out of the Right Side M Vent Buzzing Noise from the Center Vent Area
Body Equipment	51 26 08	September-08	E64	Service Action: Modifying the Rear Water Drain Hoses
Body Equipment	51 27 08	October-08	E60/61	The Front and Rear Doors Do Not Unlock at the Same Time
Body Equipment	51 28 08	September-08	3 series	Door Mirrors Do Not Fold When Using "Convenient Closure"
Body Equipment	51 29 08	November-08	E64	Water Leak into the Trunk Area
Body Equipment	51 30 08	November-08	X5, X6	Water Leak in the Front Right Footwell Area
Body Equipment	51 34 08	November-08	1 series	Wind Noise from the B-pillar at High Speeds
Body Equipment	51 35 08	January-09	All	Cracked or Damaged Windshields
Body Equipment Body Equipment	51 36 08 51 01 09	February-09 January-09	All X6	Outside Mirror Moves when Unlocking the Vehicle Rear Bumper Cover Sticks Out Below the Tail Lamp
Body Equipment	51 02 09	January-09	1 Series	Buzzing Noise from the Door Panel Pocket
Body Equipment	51 04 09	February-09	X5/X6	Gas Strut for Spare Wheel Cover Deleted
Body Equipment	51 05 09	February-09	E90/91	Buzzing Noise from the Door Speaker Area
Body Equipment	51 06 09	February-09	5 Series	Squeaking Noise from the Top of the B-pillar
Body Equipment	51 07 09	March-09	1 Series	Creaking Noise from the Center Armrest
Body Equipment	51 08 09	March-09	X5/X6	Ashtray Does Not Pop Out When the Release is Pressed
Body Equipment	51 09 09 51 11 09	April-09	X5/X6	Rattle from the Luggage Compartment Wind Noise from the A-pillar Area
Body Equipment Body Equipment	51 11 09 51 13 09	April-09 July-09	F01/02 F01/02	Wind Noise from the A-pillar Area Rattling Noises from Around the Glove Box
Body Equipment	51 14 09	March-09	F01/02 F01/02	Automatic Trunk Lid Does Not Close Properly
Body Equipment	51 16 09	April-09	3 series	Rattle Noise from the Radio Area
Body Equipment	51 17 09	April-09	3 series	Replacing Front Cup Holders - part numbers
Body Equipment	51 18 09	May-09	1 series	Noises from the Glove Box Area
Body Equipment	51 19 09	May-09	1 series	Water Leaking into the Luggage Compartment
Body Equipment	51 20 09 51 31 00	June-09	3/5 touring	Tailgate Does Not Open Fully in Cold Temperatures
Body Equipment Body Equipment	51 21 09 51 22 09	June-09 June-09	1 series Z4 (E89)	Rattle Noise from the Center Vent on the Instrument Panel Creaking Noise from the Glove Box
Body Equipment	51 22 09	July-09	F01/02	Service Action: Replace the Front Door Handle Bowden Cables
Body Equipment	51 24 09	July-09	3 series	Smoker's Package, Option Code 441
Body Equipment	51 25 09	July-09	X5/X6	Rattle Noise from the Front Door
Body Equipment	51 27 09	July-09	F01/02	The DVD Changer Cover Doesn't Open Fully
Body Equipment	51 28 09	July-09	F01/02	Roof Rack Cannot Be Installed
0			=/=	Parall Commission OAV FTF, Its 199
Seats	52 02 04 52 05 07	April-05	E60/E63 E93	Recall Campaign 04V-575: Modification of the Front Seat Heater Circuit
Seats Seats	52 05 07 52 01 08	August-07 February-08	E60/E61	Lumbar Support Inoperative Active Backrest Width Adjustment Inoperative
Seats	52 01 08 52 02 08	January-08	Z4	Knocking Noise from the Seat Frame
Seats	52 03 08 52 03 08	March-08	X5	Lateral Seat Movement and/or Noises
Seats	52 04 08	June-08	E93	Backrest Seat Cover Material Loose
Seats	52 05 08	June-08	E92	Seat Frame Design Change
Seats	52 06 08	August-08	1/3 series	Raised Area on the Seat Bottom
Seats	52 07 08	November-08	E90/91	Stiffness in the Fore and Aft Adjustment of the Seat
Seats	52 09 08	April-09	X5, X6	Seat Heater Does Not Feel Hot Enough (rpl 11/08)
Seats	52 01 09 52 02 00	June-09	E64	Seat Adjustment when Unlocking (rpl 1/09)
Seats	52 02 09 52 05 09	March-09	E70/71 (X5/6)	Thigh Support Cover Loose Pattle from the Front Seat Head Restraints
Seats Seats	52 05 09 52 06 09	June-09 July-09	E70/71 (X5/6) X5/X6	Rattle from the Front Seat Head Restraints Squeaking Noise from the Passenger Seat
Seats	52 06 09 52 07 09	July-09 July-09	X5/X6 X5/X6	Noise from the Active Head Restraint Connecting Cable
Seats	52 08 09	July-09	X5/X6	Noises From the Forward/Back Seat Adjuster Drive Shaft
Seats	52 09 09	August-09	X5/X6	Seat Backrest Panel Creaks

Catamani	CIDa (CI D## ## ##)	Data	Application	Title
<u>Category</u> Special Roofs	SIBs (SI B## ## ##) 54 13 06	<u>Date</u> May-06	Application E60	Title SHD Coding Error - Progman V21.1
Special Roofs	54 17 06	November-06	E64 (Cabrio)	Convertible Top Does Not Completely Open or Close
Special Roofs Special Roofs	54 01 07 54 02 07	July-07	E93 E93	Service Action: Replace Roof Shell Trim Strips (rpl 4/07) RHT Opens but Trunk Lid will not Close
Special Roofs	54 02 07	April-07 April-07	E93	Convenience Open/Close Function
Special Roofs	54 06 07	March-08	E93	Roof Shell 1 Slams Down on the Cowl when Closing the RHT (rpl 5/07)
Special Roofs	54 08 07	May-07	E93	RHT Statuses Reversed in DIS/GT1
Special Roofs Special Roofs	54 09 07 54 10 07	June-07 August-07	E93 E93	RHT Status Request Supplement RHT Stops Opening in the Stacked/Extended Position
Special Roofs	54 11 07	September-07	E93	Headliner is Loose in the C-pillar Area
Special Roofs	54 12 07	September-07	E93	Rattle from the Front Latch of the RHT
Special Roofs Special Roofs	54 15 07 54 16 07	April-08 November-07	E93 E93	RHT Symptom Diagnosis Update (rpl 11/07) Headliner Loose Near A-pillar
Special Roofs	54 17 07	January-08	E93	Headliner Fabric is Creased and/or Stretched
Special Roofs	54 01 08	January-08	E61/91	Wind Noise from the Panoramic Sunroof
Special Roofs Special Roofs	54 02 08 54 03 08	January-08 February-08	E60 E93	Water Leak from Sunroof RHT Seal Replacement Update
Special Roofs	54 04 08	August-09	E93	Wind Buffeting/Pressure Noise at Highway Speeds (rpl 10/08)
Special Roofs	54 05 08	March-08	E83 (X3)	Rattle from Panoramic Roof when Fully Open
Special Roofs Special Roofs	54 06 08 54 07 08	May-08 September-08	(E70) X5 E88 (1 Series)	Clicking Noise From Sunroof Convertible Top Material Loose at Rear Bow (rpl 6/08)
Special Roofs	54 08 08	March-09	(E70) X5	The Sunroof's Rear Glass Panel Does Not Close from the Vent Position (rpl 8/08)
Special Roofs	54 09 08	August-08	E93	Cleaning Excess Butyl from RHT Roof Shells
Special Roofs Special Roofs	54 11 08 54 12 08	April-09 August-09	All w/Pan Roof (E70) X5	TeileClearing for Panoramic Roof (rpl 10/08) Water Leak from the Front of the Sunroof (rpl 11/08)
Special Roofs	54 01 09	February-09	E88 (1 Series)	Service Action: Repair of the Convertible Top
Special Roofs	54 03 09	May-09	1,3,6 Verts	Soft Top Switch Function and Window Operation (rpl 3/09)
Special Roofs Special Roofs	54 04 09 54 05 09	May-09 June-09	5, 7, X5/X6 1 Series	Wind Noise or Water Leak from the Sunroof Soft Top Does Not Close Fully
Special Roofs	54 06 09	July-09	1 Series	Soft Top Hydraulic System Inoperative
Special Roofs	54 07 09	July-09	X & Touring	Squeaking Noise from the Sliding Headliner
	18 , 19 other model			
General Electrical Systems	61 07 88	December-06	All	Battery Maintenance Requirements (Replaces 10/06)
General Electrical Systems	61 08 00 61 15 02	June-07	All	Closed-Circuit Current Measurement (Replaces 1/07 - new cars)
General Electrical Systems General Electrical Systems	B611502F_Description.	February-06 P/O 61 15 02	E60/E63 E60/E63	MOST Bus Diagnosis (Supercedes July 04 with new diagnostics & models) MOST Bus Diagnosis Description
General Electrical Systems	B611502ChartsA&B.	P/O 61 15 02	E60/E63	MOST Bus Diagnosis Troubleshooting Chart
General Electrical Systems	61 03 03	January-06	E60/E63	CAN/Byteflight Bus Diagnostics (Supercedes June 05 - Adds E61 & E91)
General Electrical Systems General Electrical Systems	61 13 02 61 14 03	December-05 September-07	E65 E60/E63	CIP 16.0 - 2002 MY Electrical complaints (Supercedes April 05 w/new info) CIP Updates (CIP 27.00.00) - (Supercedes Apri 07 - 25.01.00)
General Electrical Systems	61 01 04	June-05	E65	CIP 17.01 - MY02-05 various complaints
General Electrical Systems	61 01 04	September-06	E65	Various Complaints Caused by Software Errors (21.02.01) (Supercedes Mar 06 / CIP 20.00)
General Electrical Systems General Electrical Systems	61 01 05 61 03 05	December-05 October-07	E60/E63 E90	Special Survey for CAS related problems (Supercedes Apr 05 - Survey completed) CIP 27.00.00 - Software errors corrected with PROGMAN (Rpl 25.01.00 4/07)
General Electrical Systems	61 06 05	September-05	E60	High Drain Battery Message in CIP (N52 Engine)
General Electrical Systems General Electrical Systems	61 07 05	January-06	E60/E63 E90	PDC Light Flashing after SZM Replacement (Supercedes info in August 05)
General Electrical Systems	61 08 05 61 09 05	August-05 August-05	E90	Roof Functions Center Causes Various System Malfunctions Remote Key Sticks In/Falls Out of CAS Holder
General Electrical Systems	61 10 05	August-05	E90	Various Electrical Problems
General Electrical Systems	61 11 05	October-05	E60	Battery Safety Terminal
General Electrical Systems General Electrical Systems	61 12 05 61 13 05	November-05 May-08	E60/E63 E60/E63	Dead Battery by MPM Dead Battery - Perform Energy Diagnosis (update to 10/07 - added models)
General Electrical Systems	61 01 06	February-06	E90	Trunk Opens without Request
General Electrical Systems	61 02 06	February-06	E60/E63/E90	Key Falls Out of, or Gets Stuck in Key Holder (Supercedes 2/06 adding models)
General Electrical Systems General Electrical Systems	61 04 06 61 05 06	February-06 September-07	ALL E65	Exiting a Vehicle that is Double-Locked from the Outside Various Customer Complaints Corrected With Progman
General Electrical Systems	61 06 06	May-06	E90	Junction Box Pin Assignment Change
General Electrical Systems	61 07 06	August-06	E60/E63/E90	No Crank, No Start, CAS FC A111
General Electrical Systems General Electrical Systems	61 10 06 61 13 06	October-06 October-06	E63 E60	Windows Convenience Open When Door is Opened Various Electrical Problems Caused by Water Ingress
General Electrical Systems	61 14 06	October-06	E60/E63	One-Touch Close Inoperative after Door Module Replacement
General Electrical Systems	61 15 06	October-06	E64	Rear Windows Close First, or Anti-trap Activates During Convenience Closing
General Electrical Systems General Electrical Systems	61 20 06 61 22 06	October-06 October-06	E60 E60	Rear Windows Move in Small Increments iDrive Controller Malfunction (Low Version)
General Electrical Systems	61 23 06	October-06	E60	Battery Charger Causes Faults to be Set
General Electrical Systems	61 24 06	October-06	E60	Starts only once following EWS calibration
General Electrical Systems General Electrical Systems	61 26 06 61 27 06	September-06 October-06	E90 E92	Central Electronics Failure, K-CAN bus Fault Codes Stored Replacement CAS3 - Calibration Error Message
General Electrical Systems	61 28 06	May-07	E92	Red ELV Warning in Instrument Cluster (Replaces 1/07)
General Electrical Systems	61 29 06	April-08	E60/E63/E90	CAS / ELV Diagnostics (rpl 10/07)
General Electrical Systems General Electrical Systems	61 31 06 61 32 06	September-07 December-06	X5 E90/91/92	Software Errors Corrected with Progman (update to 5/07) PROGMAN 27.01.00 Sunroof Moves in Small Steps or Interior Lights not Working
General Electrical Systems	61 33 06	December-06	E60/E63/E90	Battery Warning Displayed when Deleting Transport Mode
General Electrical Systems	61 34 06	August-07	E90/91/92	Engine Fails to Start after CAS Replacement (update to 9/06)
General Electrical Systems General Electrical Systems	61 04 07 61 08 07	May-07 August-07	E60/E63 E60/E63	SZL Functions Lock Up after Deleting Transport Mode Electric Steering Lock Inoperative
General Electrical Systems	61 09 07	August-07	E60/E65/E90	OBD Socket Housing Cover Missing
General Electrical Systems	61 12 07	November-07	E90	No Crank after CAS3 Replacement
General Electrical Systems General Electrical Systems	61 13 07 61 14 07	November-07 December-07	E70 (X5) E60/E63	Electronic Malfunction CC Message Caused by Shorted Wiring Battery Discharged KGM FC 93AB MPM Relay Sticking
General Electrical Systems	61 01 08	January-08	E60/E63/E90/E70	CC Message "Increased battery discharge while stationary"
General Electrical Systems	61 02 08	February-08	3 series	Gong Warning Without Visual Check Control Message
General Electrical Systems General Electrical Systems	61 03 08 61 05 08	February-08 May-08	E93 Service Center	Doors Will Not Lock Using Comfort Access Handles TeileClearing for General Electrical Systems
General Electrical Systems	61 05 08	May-08	E90/91/92	Windshield Wiper Parks out of Position
General Electrical Systems	61 06 08	May-08	X5/X6	Sliding Sunroof, Interior Lights, and Rain Sensor Are Inoperative
General Electrical Systems General Electrical Systems	61 07 08 61 09 08	June-08 August-08	E60 1, 3, X5, X6	Rear Window Functional Problems Controller Fault Code A2CB Internal Control Module Fault
General Electrical Systems	61 10 08	August-08	3 Series w/DCT	CAS3 Fault Code A0B1
General Electrical Systems	61 11 08	August-08	E60/61	Steering Wheel or Seat Adjustment Inoperative
General Electrical Systems General Electrical Systems	61 12 08 61 14 08	April-09 September-08	1 & 3 Series E60	Sliding Sunroof, Interior Lights, and Rain Sensor Are Inoperative Intermittently, the Rear Doors Do Not Lock
General Electrical Systems	61 16 08	November-08	3er w CIC & N51	N51 PZEV - JBE Repeat Failures Due to Shorted Fuel Sender Harness
General Electrical Systems	61 17 08	November-08	E83 (X3)	Service Action: Reprogram General Module
General Electrical Systems General Electrical Systems	61 18 08 61 01 09	December-08 March-09	BMW Centers All	Battery Maintenance Requirements Windshield Washer Malfunction
General Electrical Systems	61 02 09	March-09	7 Series (F01)	Engine Does Not Start
General Electrical Systems	61 03 09	May-09	7 Series (F01)	ZGM Fault Code 801C20 (Hex) or 8395808 (Dec)
General Electrical Systems General Electrical Systems	61 05 09 61 06 09	April-09 April-09	1,3,5,6,7,X5/6 F01/02	CC Message "Vehicle Battery! Increased Battery Discharge" After Vehicle Is Stationary Service Action: Program Control Units (Central Gateway Module)
General Electrical Systems	61 07 09	April-09	5,6, E46, E53	One-touch Windows Inoperative After General Module Replacement
General Electrical Systems	61 08 09	May-09	1 series	Rattle Noise from the Washer Fluid Reservoir
General Electrical Systems General Electrical Systems	61 09 09 61 10 09	May-09 May-09	X6 F01/02	Service Action: Check and Replace Battery Erroneous FC 801C05 (Hex), 8395781 (Dec) in ZGM
_ Jilotai Electrical Cystoliis	31 10 00	may 03	101/02	

Category	SIBs (SI B## ## ##)	<u>Date</u>	Application	
General Electrical Systems	61 11 09	June-09	All	Battery Charging and Testing Procedure
General Electrical Systems General Electrical Systems	61 12 09 61 13 09	June-09 July-09	F01/02 1 series	System Analysis: signal fault Diagnostics - Important Information Missing "Year One of the 1" Start/Stop Ring
Ceneral Electrical Cystems	01 10 03	odly 05	1 Series	missing real one of the F Standstop King
01	, 02, 03 , 05, 06, 07, 10, 11 X5 or other m	odels		
Instruments	62 01 06	May-07	E60/E63	Instrument Cluster Needles Vibrate (Replaces 1/07)
Instruments	62 02 06	May-06	E60/E63	Engine Oil Level Menu Option is Displayed After Reprogramming
Instruments Instruments	62 04 06 62 01 07	October-06 January-07	E60/E63 E90/92	Instrument Cluster: Failure of Displays/Functions Warning Chime Inoperative for Check Control and/or Directionals
Instruments	62 02 07	January-07	E60/E63/E92	No Communication or Diagnosis Possible With Instrument Cluster
Instruments	62 03 07 62 06 07	May-07	E90/92	On-Board Computer Functions Cannot Be Displayed (rpl 1/07)
Instruments Instruments	62 07 07	March-07 May-08	BMW Centers E70 (X5)/E71 (X6)	Check Control Messages (With PDF list) TeileClearing (Enhanced Technical Support) for Instrument Cluster
Instruments	62 01 08	May-08	1 Series	Cruise Control Display in Instrument Cluster Increments Incorrectly
Instruments Instruments	62 02 08 62 04 08	August-08 September-08	M3 w/DCT E6x	Instrument Cluster Center Displays Go Blank Instrument Cluster Mileage Display Switches to Kilometers when Key Is Switched
Instruments	62 01 09	April-09	E6x	All Instrument Dials Inoperative and Display in Instrument Cluster Is Bright
Instruments	62 02 09	May-09	M3 w/DCT	Shift Lights on M3 Instrument Cluster Cannot Be Permanently Activated
Instruments	62 03 09	July-09	All	Outside Temperature Display Is Incorrect
	04 07 note to dealer 05 - 09 other models			
Lights Lights	63 02 04 63 02 05	July-04 June-05	E60 E60	Replace Lamp Module Brake Force Display (BFD) Inoperative
Lights	63 03 05	July-05	E60	Eyebrow Lights are Inoperative after Programming
Lights	63 05 05	September-05	E64 Cabrio	Third Brake Light Cracked
Lights Lights	63 06 05 63 01 06	November-05 May-06	E60 Z4	Service Action: Check the Adaptive Headlights for Proper Operation Front Lighting Configuration
Lights	63 05 06	October-06	E60/E63	Automatic Headlamps: Lights Do Not Switch Off
Lights	63 06 06	October-06	E60	LED Flashing On Headlight Switch, No Faults Stored
Lights Lights	63 08 06 63 09 06	October-06 October-06	E60 E60	Lights Flash Briefly When Vehicle Wakes Up; Battery May Become Discharged Brake Lighting Pulsates Intermittently
Lights	63 12 06	October-06	E63	Adaptive Headlamp Does Not Turn
Lights	63 13 06 63 15 06	October-06	E60/E63	Automatic Headlamp System Does Not Switch Off the Lights
Lights Lights	63 15 06 63 16 06	October-06 November-06	E60 E60	Headlamp Leak (Replaces 12/04) 3rd Brake Light Comes Loose From Rear Window
Lights	63 17 06	January-07	E60/63/90	Eyebrow Lights are Inoperative after Programming (Replaces 12/06)
Lights Lights	63 02 07 63 03 07	January-07 February-07	E90/91/92 E90/91/92	Bulb Out Symbol Displayed in BC Daytime Running Lights are Inoperative
Lights	63 04 07	March-07	E60/E63	Fault Code 9CAD in LM
Lights	63 05 07	April-07	X5 (E70)	Rear Turn Signal is Inoperative
Lights Lights	63 06 07 63 09 07	April-07 June-07	E92/93 X5 (E70)	Cornering lights failure Displayed in Check Control Taillight Partially Inoperative
Lights	63 10 07	October-07	E92/93	Headlight Vibrates when Vehicle is in Motion
Lights	63 13 07	August-07	E90/91/92	Headlight Vibrations
Lights Lights	63 15 07 63 16 07	October-07 December-07	E70 (X5) E60/E63	Interior Light Switch Illumination Option Code 08S4 - Variable Light Decoding
Lights	63 01 08	March-08	E63/E64	Side Marker Lamp not Working in Conjunction with Welcome Light
Lights	63 02 08	March-08	E92/93	Rear Bulb Failure
Lights Lights	63 03 08 63 04 08	March-08 June-08	3 Series 1/3/5/6/7/X series	Flashlight Deleted as a Running Change Headlamp Moisture: Fault Diagnostics
Lights	63 05 08	May-08	E60	CC Message Missing/Incorrect when Front Parking Light Faulty
Lights	63 06 08	July-08	X3	Bulb-Out Warning, FC 2F or 3E
Lights Lights	63 07 08 63 08 08	August-08 August-08	E60/E63 X5 (E70)	Adaptive Headlights Intermittently Inoperative (SW fix coming in Oct) Contact Between Inner and Outer Rear Lamps
Lights	63 09 08	August-08	X3	Interior Lamps "Soft ON/OFF" Inoperative
Lights	63 10 08	November-08	1 series, X3	Cracked Third Brake Light (rpl 9/08)
Lights Lights	63 11 08 63 12 08	November-08 January-09	All w/MOST E60/E63	Automatic Headlamps: Adjust Sensitivity Changes to Panel Illumination (58G)
Lights	63 03 09	March-09	7 Series (F01)	High-beam Assistant (FLA): Erratic Operation
Lights Lights	63 04 09 63 06 09	March-09 May-09	7 Series (F01) 3 Series	Headlamp Flashes Several Times, Then Switches Off Front LED Turn Signal Not Working or Malfunctioning
Lights	63 07 09	July-09	5, 6, 7 series	Lights Do Not Switch Off Automatically after replacing light module
	08 09 for X5 (E63 and E70) 07 NU			
Heating and Air Conditioning	64 08 91	October-06	All	Musty Odors
Heating and Air Conditioning Heating and Air Conditioning	64 02 05 64 03 05	August-05 June-08	E64 (Cabrio) E60/E63	Poor Temperature Regulation from Center Vents Air Conditionaing Delayed Startup (Supercedes 4/07 w/new info)
Heating and Air Conditioning	64 04 05	August-07	E60/E63	Air Conditioning Stops Cooling after Long Drive (Replaces 12/06)
Heating and Air Conditioning	64 21 05	May-08	All	Troubleshooting Air Conditioning Compressor Noise (Supercedes Dec 06)
Heating and Air Conditioning Heating and Air Conditioning	64 01 06 64 02 06	January-06 June-06	E60 E60	Blower Motor Stays On with Key Off Water Droplets are Blown from Center Vents with A/C On (Supercedes Jan 06)
Heating and Air Conditioning	64 04 06	May-07	E90	Air Conditioning Does not Cool (Replaces 1/07)
Heating and Air Conditioning Heating and Air Conditioning	64 06 06 64 07 06	May-06 May-07	E90 E90	Front Defroster Performance Poor at Mid-Blower Speeds Air Conditioning System does not Cool (Refrigerant Charge Good) (rpl 6/06)
Heating and Air Conditioning Heating and Air Conditioning	64 09 06	October-06	E90	Air Conditioning System does not Cool (Reingerant Charge Good) (rpi 6/06) Air Conditioning System Blows Warm Air After Long Drive (Replaces 8/06)
Heating and Air Conditioning	64 10 06	July-06	E60/61	Water Droplets Blown from Right Side Center Vents with A/C On
Heating and Air Conditioning Heating and Air Conditioning	64 14 06 64 03 07	November-07 October-07	E60/61 E92	A/C Compressor Noise "Droning, Howling or Ticking" at Low Engine Speed (update to 10/06) Banging Noise from Air Conditioner Compressor (update to 3/07)
Heating and Air Conditioning Heating and Air Conditioning	64 04 07	May-08	All	Heating and Air Conditioning Symptom Diagnosis (update to 1/08)
Heating and Air Conditioning	64 06 07	May-08	E60/E63	Air Conditioning Compressor Does Not Switch On
Heating and Air Conditioning Heating and Air Conditioning	64 08 07 64 10 07	August-07 January-08	All E60/E63	Important Information about Heating and Air Conditioning Air Conditioning Delayed Startup
Heating and Air Conditioning	64 12 07	June-08	3 Series	White Flakes/Powder Coming from the Air Conditioning Vents
Heating and Air Conditioning	64 13 07 64 14 07	February-08	3 Series	CID or IHKA Total Failure Because F61 Blown
Heating and Air Conditioning Heating and Air Conditioning	64 14 07 64 02 08	November-07 June-08	E70 (X5) 1 & 3 Series	Water Leak on Carpet During Air Conditioning Usage Whistling from the Heating/Air Conditioning Unit at Speeds over 50 MPH
Heating and Air Conditioning	64 03 08	August-08	All	TeileClearing for Air Conditioning Systems
Heating and Air Conditioning	64 04 08 64 05 08	September-08	E70 (X5)	Different Delivery Temperature from Each Side of the Rear Compartment Blower
Heating and Air Conditioning Heating and Air Conditioning	64 05 08 64 06 08	October-08 October-08	All E71 (X6)	Damage to the Air Conditioning Control Panel Cold Air Is Leaking from Center Console Area
Heating and Air Conditioning	64 01 09	March-09	E70 (X5)	Whirring Noise from the Auxiliary Water Pump
Heating and Air Conditioning Heating and Air Conditioning	64 02 09 64 03 09	May-09 June-09	F01/02 F01/02	Rear Air Conditioning is Automatically Reactivated After Sleep Cycle Heating and Air Conditioning Conversions Available in ISTA/P
	04 00 03		1 3 1/02	
	07 09 for (X5)			
Audio, Navigation, Monitors, Alarms, SF	65 06 04	July-04	E60/E63	Consumption Set to mpg UK instead of mpg US
Audio, Navigation, Monitors, Alarms, SF	65 10 04	January-05	E60/E63	Audio Stays On
Audio, Navigation, Monitors, Alarms, SF	65 01 05	June-05	E90	Radio Seek/Scan Inoperative

Authors	Category	SIBs (SI B## ## ##)	<u>Date</u>	<u>Application</u>	<u>Title</u>
Andre Margines Norman, 2010. CO 1010. April March Margines Norman, 2010. CO 1010. Andre Margin					
Math Margian Anthony Alemn, 50 19 18 18 18 18 18 18 18					
March March American March American March March March American March Mar					
March Marc					
According to Company Annum Annum Allow 10					
According Approximate Ap					
According to Company Agriculture According to C					
Auch Norgiver. Notes, Almers 9					
Auch Norgani, Alexanol. 2007. 100 100					
Auto, Nacytima Notine, Asime, 50 10.20 1					
### Adult Norphich Monthins, Admin. ## ## ## ## ## ## ## ## ## ## ## ## ##	Audio, Navigation, Monitors, Alarms, SF				
Auch Norgania Notatina, Assemble 50 60 60 60 60 60 60 60					
Appendix					
Aced, Northigner, Northern, Ammer, 3					
Auch Norgisch, Morten, Alema, 59 Auch N		65 28 05			
Auch Neuglapho Martin, Allemin, 65 Auch Rosignion, Martin, Allemin, 65 Auch Rosignion, Martin, Allemin, 67 Auch Rosignion, Martin, 67 Auch Rosignion, Martin, Allemin, 67 Auch Rosignion, Martin, 67 Auch Rosignion, Martin, Allemin, 67 Auch Rosignion, Martin, 78 Auch Rosignion, Martin, Allemin, 67 Au					
Auch Natigation, Marcine, Allerin, 3					
Auch Neughion Martines, Alema, 65 40 00 00				E60/E63/E90	
Auch Margian, Morton, Alarm. B					
Auch Navigleto, Martino, Alamm, B 66 10 68 Ago 68 ESGEREES Navigation, Martino, Alamm, B 66 10 68 Coccool 68 ESGEREES Action Navigation, Martino, Alamm, B 66 10 68 Coccool 68 ESGEREES Coccool 68 ESGEREES Action Navigation, Martino, Alamm, B 66 10 68 Coccool 68 ESGEREES Cocc					
Auth Marginor, Morron, Adems ST 61 60 September 40 Septem					
Auch, Narginion, Moratine, Alarme, 51 Auto, Narginion, Moratine, Alarm					
Auch Nergelin, Morron, Amer. 51 63 50 66 Compose 66 65 20 66 Compose 67 65 20 66 Compose 67 65 20 66 Compose 67 65 20 66 Compose 68					
Auch Noughor, Montro, Adems, 15 63 20 60 Combert 60 63 20 60 Combert 60 63 20 60 Combert 60 64 20 60 Combert 60 65 20 60 Combert 60 C					
Auch Nergorius Montes, Alams, 51 Auch N				E60/E63/E90	CCC Disclaimer Screen Disappears Automatically after 10 Seconds
Audio, Novigolion, Montres, Alarmin, 51 Audio, Novigolion, Montres, Alarmin,					
Audio, Narigotino, Montrion, Allamin, Sil 4.05 30 0.0 Jan. 20 December 68 E. 50 0.0 Jan. 20 Respective from the Audio, Selection in 14 Montrion, Manner, Sil 4.05 30 0.0 December 68 E. 50 0.0 May 77 E. 50 E. 50 E. 50 C.					
Audio, Nargolino, Monton, Alarms, 5					
Audio, Newgorino, Mortions, Asterns, 5					
Audo, Nargistich, Montin, Alemin, 5					
Judo S. Neglegion Mortino, Aleman, 51 65 40 60 December 69 E00ESSEE0 COC. ALÉAN H. Logis Integral of the Device Connected Auto. Neglegion, Mortino, Aleman, 51					
Auto, Nesignion, Montons, Aurens, 51 Auto, Nesignion, Montons, Aurens	Audio, Navigation, Monitors, Alarms, SF		December-06	E60/E63/E90	CCC: AUX-IN Loud Hissing if no Device Connected
Audo, Navigation, Membra, Aumans, St.					
Audio Averagement Members American American American Audio Averagement Audio Audio Audio Averagement Audio Aud					
Audo, Navegation, Montions, Alarms, S1 Auto,					
Audo, Navigation, Mentero, Alarma, 51 400, Navig					
Auto, Navigation, Montens, Alams, 5 6 07 07 March-07 Auto, Navigation, Montens, Alams, 5 6 07 07 March-07 Auto, Navigation, Montens, Alams, 5 6 07 07 March-07 Auto, Navigation, Montens, Alams, 5 6 08 10 07 January-08 Auto, Navigation, Montens, Alams, 5 6 08 10 07 May-07 Auto, Navigation, Montens, Alams, 5 6 08 10 07 August-07 Auto, Navigation, Montens, Alams, 5 6 08 20 07 August-07 Auto, Navigation, Montens, Alams, 5 6 08 20 07 August-07 Auto, Navigation, Montens, Alams, 5 6 08 20 07 August-07 Auto, Navigation, Montens, Alams, 5 6 08 20 07 August-07 Auto, Navigation, Montens, Alams, 5 6 08 20 07 August-07 Auto, Navigation, Montens, Alams, 5 6 08 20 07 November 07 Auto, Navigation, Montens, Alams, 5 6 08 20 07 December 07 Auto, Navigation, Montens, Alams, 5 6 08 20 07 September 07 Auto, Navigation, Montens, Alams, 5 6 08 20 07 December 07 Auto, Navigation					
Audo, Navigation, Mortions, Alamm. 51 Audo, Navigation,					
Audo, Navigation, Monitors, Alarms, Sf Alaris, Marigation, Monitors, Alarms, Sf Alaris, Marigation, Monitors, Alarms, Sf B 59 07 Mayes 67 Audo, Navigation, Monitors, Alarms, Sf B 50 207 August-07 August-08 August-					
Audio, Navigation, Monitors, Alarms, S1 400, Navigation, Monitors, Alarms, S1 402, Navigation, Monitors, Alarms, S1 402, Navigation, Monitors, Alarms, S1 403, Navigation, Monitors, Alarms, S1 404, Navigation, Monitors, Alarms, S1 405, Navigation, Monitors, Ala					
Audo, Navigation, Montrion, Alarma, SF 65 2 07 August-07 E00ESSE-090 E20 CCC OT Feet not Updated When OD Is Swepperd					
Audo, Nivigition, Moriton, Alarms, \$1 63 207 August-07 E60ESS-80FEEZ CC C D*Text not Updated When CD is Swapped Audo, Nivigition, Moriton, Alarms, \$1 63 24 07 August-07 E60ESS-80FEEZ CC C D*Text not Updated When CD is Swapped Audo, Nivigition, Moriton, Alarms, \$1 63 24 07 August-07 E60ESS-80FEEZ CCC C D*Text not Updated When CD is Swapped Audo, Nivigition, Moriton, Alarms, \$1 63 24 07 August-07 E60ESS-80FEEZ CCC D*Text not Updated When CD is Swapped Audo, Nivigition, Moriton, Alarms, \$1 63 24 07 August-07 E60ESS-80FEEZ CCC D*Text not Updated When CD is Swapped Audo, Nivigition, Moriton, Alarms, \$1 63 24 07 August-07 E60ESS-80FEEZ CCC D*Text not Updated When CD is Swapped Audo, Nivigition, Moriton, Alarms, \$1 63 20 07 Cochebr-07 E60ESS-80FEEZ CCC D*Text not Updated When CD is Swapped Audo, Nivigition, Moriton, Alarms, \$1 63 30 07 August-08 Aug					
Audio, Navigation, Montrion, Alarms, \$F 65 24 07 Augisa-107 EEDESS-8500EEZ CCC Navigation Displays Incomed Verlace Position Audio, Navigation, Montrion, Alarms, \$F 65 26 07 Augisa-107 EEDESS-8500EEZ CCC Navigation Montrion, Alarms, \$F 65 26 07 Augisa-107 EEDESS-8500EEZ CCC Navigation Montrion, Alarms, \$F 65 26 07 Augisa-107 EEDESS-8500EEZ CCC Navigation Montrion, Alarms, \$F 65 26 07 Augisa-107 Corbor-07 C					
Audio, Nivigistion, Monitors, Alarms, \$5 65 26 07 November 07 E00/ESS/E00/E02 CCC: Volume Differences between CPU AND A Programming CAJO, Nivigistion, Monitors, Alarms, \$1 65 20 07 December-07 September-07 Septemb					
Audio, Navigation, Montinos, Alarms, 51 65 20 07 December-07 September-07 September-07 September-09 EBOERSSE00/ESQ Adaption, Montinos, Alarms, 51 65 20 07 September-07 EBOERSSE00/ESQ Care		65 24 07	August-07	E60/E63/E90/E92	CCC Navigation Map DVD not Detected
Audio, Navigation, Mortions, Alarms, SF 65.27 of September-07					
Audio, Navigation, Montroins, Alarms, Sf 65 20 07 September-07 E60E53/E90E9252 CCC. Radio Diso Servicing to PM Mode of Switching to PM Mode					
Audio, Navigation, Morniors, Alarms, SF					
Audio, Navigation, Morniors, Alarms, \$F 65 32 07 December-07 X5 (E70) Audio, Navigation, Morniors, Alarms, \$F 65 34 07 November-07 E90919/29/39 Service Action, Program the MULP2-High Control Module Audio, Navigation, Morniors, Alarms, \$F 65 36 07 December-07 X5 (E70) Service Action, Program the MULP2-High Control Module Audio, Navigation, Morniors, Alarms, \$F 65 36 07 January-08 E80E53 E80 (E80E53 E80 (E80E53 E80) E80E53 E80E					
Audio, Navigation, Montions, Alarms, SF 65 33 07 November-07 November-08 November-09 November-08 November-08 November-08 November-08 November-09 November-08 Nov		05.00.05	D 1 00	· · - · · - · ·	
Audio, Navigation, Moritors, Alarms, SF 65 56 07 December-07 Audio, Navigation, Moritors, Alarms, SF 65 36 07 January-08 E80E83 Audio, Navigation, Moritors, Alarms, SF 65 37 07 November-07 E83 No Audio Output After Turring the Ignation On Date Display is Cleared (pt 12/07) Audio, Navigation, Moritors, Alarms, SF 65 30 07 December-07 June-09 E80E83/E80E92/E70 CCC Loss of Audio and CID Blanks Out (pt 07/08) Audio, Navigation, Moritors, Alarms, SF 65 40 07 June-09 Audio, Navigation, Moritors, Alarms, SF 65 10 08 May-08 April-08 Audio, Navigation, Moritors, Alarms, SF 65 06 08 April-08 April-08 Audio, Navigation, Moritors, Alarms, SF 65 06 08 April-08 Audio, Navigation, Moritors, Alarms, SF 65 06 08 April-08 Audio, Navigation, Moritors, Alarms, SF 65 06 08 April-08 Audio, Navigation, Moritors, Alarms, SF 65 07 08 April-08 Audio, Navigation, Moritors, Alarms, SF 65 07 08 April-08 Audio, Navigation, Moritors, Alarms, SF 65 07 08 April-08 Audio, Navigation, Moritors, Alarms, SF 65 07 08 April-08 Audio, Navigation, Moritors, Alarms, SF 65 07 08 March-09 Audio, Navigation, Moritors, Alarms, SF 65 07 08 March-09 Audio, Navigation, Moritors, Alarms, SF 65 10 08 May-08 Audio, Navigation, Moritors, Alarms, SF 65 10 08 May-08 Audio, Navigation, Moritors, Alarms, SF 65 10 08 May-08 Audio, Navigation, Moritors, Alarms, SF 65 10 08 May-08 Audio, Navigation, Moritors, Alarms, SF 65 10 08 May-08 Audio, Navigation, Moritors, Alarms, SF 65 10 08 May-08 Audio, Navigation, Moritors, Alarms, SF 65 10 08 May-08 Audio, Navigation, Moritors, Alarms, SF 65 10 08 May-08 Audio, Navigation, Moritors, Alarms, SF 65 10 08 May-08 Audio, Navigation, Moritors, Alarms, SF 65 10 08 May-08 Audio, Navigation, Moritors, Alarms, SF 65 10 08 May-08 Audio, Navigation, Moritors, Alarms, SF 65 10 08 May-08 Audio, Navigation, Moritors, Alarms, SF 65 00 08 March-09 Audio,				, ,	
Audio, Navigation, Monitors, Alarms, SF 65 8 607 January-08 E98 Radio Turns Off After 8 Minutes and Time and Date Display is Cleared (pt 12/07) Audio, Navigation, Monitors, Alarms, SF 65 9 07 December-07 December-07 December-07 December-07 December-08 E98 December-08 December-09 December-08 December-09					
Audio, Navigation, Montiors, Alarms, \$f 63 90 77 December 97 December 98 Dec					
Audio, Navigation, Montiors, Alarms, \$ 65 30 97 Decembe-07 E00FE3XE-90F63ZE70 CCC Loss of Audio and CID Blanks Out (rg) 10708)					
Audio, Navigation, Moritors, Alarms, \$f 65 d 20 f August-08 All wAlarm Alarm Triggers Unexpectedly - Troubleshooting	Audio, Navigation, Monitors, Alarms, SF			E60/E63/E90/E92/E70	CCC Navigation Not Working -September 24, 2007 to October 29, 2007
Audio, Navigation, Monitors, Alarms, Sf 65 00 08 August-08 Al wgK-1 (208) Audio, Navigation, Monitors, Alarms, Sf 65 00 08 August-08 August-08 Al wgK-1 (208) Audio, Navigation, Monitors, Alarms, Sf 65 00 08 April-08 April-08 August-08 Augus					
Audio, Navigation, Monitors, Alarms, SF					
Audio, Navigation, Monitors, Alarms, SF 65 06 48 April-08 April-08 T Series SIRUS Radio Station List is Not Displayed in the RSE Monitor				All w/6FL (USB)	iPod Classic Doesn't Get Charged through USB Connection
Audio, Navigation, Monitors, Alarms, \$F 65 06 08 February-09 Audio, Navigation, Monitors, Alarms, \$F 65 07 08 April-08 April-08 3 series LSB Device Is Not Detacted Audio Volume is Briefly Muted or Reduced (4/08) Audio, Navigation, Monitors, Alarms, \$F 65 08 08 May-08 3 series LSB Device Is Not Detacted Audio, Navigation, Monitors, Alarms, \$F 65 10 08 May-08 1 & 3 Series Audio, Navigation, Monitors, Alarms, \$F 65 11 08 May-08 1 & 3 Series Audio, Navigation, Monitors, Alarms, \$F 65 11 08 May-08 Audio, Navigation, Monitors, Alarms, \$F 65 11 08 May-08 Audio, Navigation, Monitors, Alarms, \$F 65 11 08 May-08 Audio, Navigation, Monitors, Alarms, \$F 65 16 08 Audio, Navigation, Monitors, Alarms, \$F 65 10 08 Audio, Navigation, Monitors, Alarms, \$F 65 20 08 November-08 Audio, Navigation, Monitors, Alarms, \$F 65 20 08 November-08 Audio, Navigation, Monitors, Alarms, \$F 65 20 08 November-08 Audio, Navigation, Monitors, Alarms, \$F 65 20 08 November-08 Audio, Navigation, Monitors, Alarms, \$F 65 20 08 November-08 Audio, Navigation, Monitors, Alarms, \$F 65 20 08 November-08 Audio, Navigation, Monitors, Alarms, \$F 65 20 08 March-09 Audio, Navigation, Monitors, Alarms, \$F 65 20 08 March-09 Audio, Navigation, Monitors, Alarms, \$F 65 20 08 March-09 Audio, Navigation, Monitors, Alarms, \$F 65 20 08 March-09 Audio, Navigation, Monitors, Alarms, \$F 65 20 08 March-09 Audio, Navig					
Audio, Navigation, Monitors, Alarms, \$f 65 06 08 April-08 April-08 April-08 April-08 April-08 April-08 April-08 April-08 Audio, Navigation, Monitors, Alarms, \$f 65 08 08 May-08 April-08 Audio, Navigation, Monitors, Alarms, \$f 65 09 08 March-09 X6/X5 (E70) Anti-theft Alarm System Triggers a False Alarm rpl 11/08) Audio, Navigation, Monitors, Alarms, \$f 65 10 08 May-08 All wifer Audio, Navigation, Monitors, Alarms, \$f 65 11 08 May-08 All wifer Audio, Navigation, Monitors, Alarms, \$f 65 11 08 May-08 All wifer Audio, Navigation, Monitors, Alarms, \$f 65 11 08 May-08 All wifer Audio, Navigation, Monitors, Alarms, \$f 65 11 08 May-08 All wifer Audio, Navigation, Monitors, Alarms, \$f 65 11 08 Audio, Navigation, Monitors, Alarms, \$f 65 11 08 Audio, Navigation, Monitors, Alarms, \$f 65 16 08 September-08 E33 (X3) Audio, Navigation, Monitors, Alarms, \$f 65 16 08 September-08 E60/63 Audio, Navigation, Monitors, Alarms, \$f 65 18 08 September-08 E60/63 Audio, Navigation, Monitors, Alarms, \$f 65 18 08 September-08 E60/63 Audio, Navigation, Monitors, Alarms, \$f 65 19 08 July-09 E60/E90/E93 (X3) Audio, Navigation, Monitors, Alarms, \$f 65 20 08 November-08 E33 Audio, Navigation, Monitors, Alarms, \$f 65 20 08 November-08 E33 Audio, Navigation, Monitors, Alarms, \$f 65 20 08 November-08 E33 Audio, Navigation, Monitors, Alarms, \$f 65 20 08 November-08 E33 Audio, Navigation, Monitors, Alarms, \$f 65 20 08 November-08 Audio, Navigation, Monitors, Alarms, \$f 65 20 08 November-08 Audio, Navigation, Monitors, Alarms, \$f 65 20 08 November-08 Audio, Navigation, Monitors, Alarms, \$f 65 20 08 March-09 Audio, Navigation, Monitors, Alarms, \$f 65 00 09 Au					
Audio, Navigation, Monitors, Alarms, SF 65 08 08 May-08 3 series Fault Code "E190" stored in the RAD2_GW Audio, Navigation, Monitors, Alarms, SF 65 10 08 May-08 1 & 3 Series RAD2: Intermittently No Audio after Check Control Message Audio, Navigation, Monitors, Alarms, SF 65 11 08 May-08 Audio, Navigation, Monitors, Alarms, SF 65 11 08 May-08 Audio, Navigation, Monitors, Alarms, SF 65 12 08 June-08 E60 SRS Warring Lamp Illuminated, but No Fault Codes Stored Audio, Navigation, Monitors, Alarms, SF 65 15 08 June-08 September-08 E30 (33) Aibag Warring Lamp Illuminated, EC A1 Audio, Navigation, Monitors, Alarms, SF 65 17 08 December-08 E60 (20) E60					
Audio, Navigation, Monitors, Alarms, \$ 65 09 08 March-09					
Audio, Navigation, Monitors, Alarms, SF 65 10 08 May-08 Al wiGFL iPod Classic is Discharged after an Extended Period of Inactivity Audio, Navigation, Monitors, Alarms, SF 65 11 08 June-08 E60 SRS Warring Lamp Illuminated, but No Fault Codes Stored Stored Classic is Discharged after an Extended Period of Inactivity Audio, Navigation, Monitors, Alarms, SF 65 15 08 June-09 1 Series Volume of Warring Gong too Quiet (9/08) Audio, Navigation, Monitors, Alarms, SF 65 16 08 September-08 E83 (X3) Airbag Warring Lamp Illuminated, EC A1 CD Changer is Inoperative; Magazine is Jammed Teile Clearing for Car Information Computer (CIC) Audio, Navigation, Monitors, Alarms, SF 65 18 08 September-08 My09 1 & 3 series Side (Monitors, Alarms, SF 65 18 08 September-08 My09 1 & 3 series Side (Monitors, Alarms, SF 65 18 08 September-08 My09 1 & 3 series Side (Monitors, Alarms, SF 65 18 08 September-08 My09 1 & 3 series Side (Monitors, Alarms, SF 65 20 08 November-08 E93 Airbag Warring Illuminated, EC 9402 Audio, Navigation, Monitors, Alarms, SF 65 20 08 November-08 E93 Airbag Warring Illuminated, EC 9402 Audio, Navigation, Monitors, Alarms, SF 65 24 08 November-08 M3/M5 Audio, Navigation, Monitors, Alarms, SF 65 24 08 December-08 M3/M5 Audio, Navigation, Monitors, Alarms, SF 65 27 08 February-09 1,3,5 series Loss of Navigation OFS Position Audio, Navigation, Monitors, Alarms, SF 65 02 09 January-09 1,3,6 ser X5,X6 Entertainment and Communication Systems are Inoperative Incorrect Message in the USB Audio Interface Diagnosis Audio, Navigation, Monitors, Alarms, SF 65 05 09 January-09 1,3,6 ser (Monitors) Alarms, SF 65 05 09 January-09 1,3,7 series (F01) Side View Camera Has Blurred Image Audio, Navigation, Monitors, Alarms, SF 65 06 09 March-09 1,3,7 series Side View Camera Has Blurred Image Audio, Navigation, Monitors, Alarms, SF 65 10 09 May-09 1,3,7 series Satellite Radio: Channel List May Be Empty or Channels Are Missing Audio, Navigation, Monitors, Alarms, SF 65 10 09 March-09 1,3,3 series Satellite Radio: Channel List May Be Empty					
Audio, Navigation, Monitors, Alarms, SF					
Audio, Navigation, Monitors, Alarms, SF 65 14 08 October-08 June-09 X5 (E70) Controller Scrolling Function Not Responsive Audio, Navigation, Monitors, Alarms, SF 65 16 08 June-09 1 Series Volume of Warning Gong too Quilet (9/08) Audio, Navigation, Monitors, Alarms, SF 65 16 08 September-08 E83 (X3) Airbag Warning Lamp Illuminated, FC A1 Audio, Navigation, Monitors, Alarms, SF 65 18 08 September-08 E80/63 CD Charger Is Inoperative; Magazine Is Jammed Audio, Navigation, Monitors, Alarms, SF 65 19 08 September-08 MY99 1 & 3 series Teile/Clearing for Car Information Computer (CIC) Audio, Navigation, Monitors, Alarms, SF 65 20 08 November-08 1 & 3 Series Interference Noises and/or Reception Varies in Certain Areas Audio, Navigation, Monitors, Alarms, SF 65 22 08 November-08 1 series Loss of Navigation GPS Position Audio, Navigation, Monitors, Alarms, SF 65 24 08 December-08 M3/M5 Audio System Is Intermittently Inoperative Audio, Navigation, Monitors, Alarms, SF 65 00 09 January-09 1,3,6 ser X5,76 Incorrect Message in the USB Audio Interface Diagnosis Audio, Navigation, Monito		65 11 08			
Audio, Navigation, Monitors, Alarms, \$ 65 15 08 June-09 1 Series Volume of Warning Gong too Quiet (9/08) Audio, Navigation, Monitors, Alarms, SF 65 16 08 September-08 E83 (X3) Airbag Warning Lamp Illuminated, FC A1 Audio, Navigation, Monitors, Alarms, SF 65 17 08 December-08 E60/63 CD Changer Is Inoperative; Magazine Is Jammed Audio, Navigation, Monitors, Alarms, SF 65 18 08 September-08 MY09 1 & 3 series Audio, Navigation, Monitors, Alarms, SF 65 20 08 November-08 Recall Campaign 08V-384: Modify Seat Occupancy Detection Mat (6/09) Audio, Navigation, Monitors, Alarms, SF 65 21 08 November-08 E93 Airbag Warning Illuminated, FC 9402 Audio, Navigation, Monitors, Alarms, SF 65 22 08 November-08 E93 Airbag Warning Illuminated, FC 9402 Audio, Navigation, Monitors, Alarms, SF 65 24 08 December-08 M3/M5 Audio System Is Intermittently Inoperative Audio, Navigation, Monitors, Alarms, SF 65 27 08 February-09 1,3,5 es er Sc,X6 Entertainment and Communication Systems are Inoperative Audio, Navigation, Monitors, Alarms, SF 65 02 09 January-09 1 Series <td< td=""><td></td><td></td><td></td><td></td><td></td></td<>					
Audio, Navigation, Monitors, Alarms, SF 65 16 08 September-08 E83 (X3) Airbag Warning Lamp Illuminated, FC A1 Audio, Navigation, Monitors, Alarms, SF 65 17 08 December-08 E60/63 CD Changer Is Inoperative; Magazine; Monitors and Illuminated, FC A1 Audio, Navigation, Monitors, Alarms, SF 65 18 08 September-08 MY09 1 & 3 series Audio, Navigation, Monitors, Alarms, SF 65 19 08 July-09 E60/E90/E83 (X3) Audio, Navigation, Monitors, Alarms, SF 65 20 08 November-08 1 & 3 Series Audio, Navigation, Monitors, Alarms, SF 65 22 08 November-08 1 series Loss of Navigation GPS Position Audio, Navigation, Monitors, Alarms, SF 65 24 08 December-08 M3/M5 Audio System Is Intermittently Inoperative Audio, Navigation, Monitors, Alarms, SF 65 24 08 December-08 M3/M5 Audio System Is Intermittently Inoperative Audio, Navigation, Monitors, Alarms, SF 65 01 09 January-09 1,3,6 ser Incorrect Message in the USB Audio Interface Diagnosis Audio, Navigation, Monitors, Alarms, SF 65 02 09 January-09 1 Series Audio Interference Noises in All Modes When Vehicle Is in Motion					
Audio, Navigation, Monitors, Alarms, \$F 65 18 08 July-09 E60/E90/E83 (X3) Audio, Navigation, Monitors, Alarms, \$F 65 19 08 July-09 E60/E90/E83 (X3) Audio, Navigation, Monitors, Alarms, \$F 65 20 08 November-08 I 8 3 Series Audio, Navigation, Monitors, Alarms, \$F 65 21 08 November-08 I series Audio, Navigation, Monitors, Alarms, \$F 65 22 08 November-08 I series Audio, Navigation, Monitors, Alarms, \$F 65 22 08 November-08 I series Audio, Navigation, Monitors, Alarms, \$F 65 22 08 November-08 I series Audio, Navigation, Monitors, Alarms, \$F 65 22 08 November-08 I series Audio, Navigation, Monitors, Alarms, \$F 65 27 08 February-09 I 3,3,5 ser Audio, Navigation, Monitors, Alarms, \$F 65 00 09 January-09 I 3 Series Audio, Navigation, Monitors, Alarms, \$F 65 00 09 January-09 I 3 Series Audio, Navigation, Monitors, Alarms, \$F 65 00 09 January-09 I 3 Series Audio, Navigation, Monitors, Alarms, \$F 65 00 09 January-09 I 3 Series Audio, Navigation, Monitors, Alarms, \$F 65 00 09 January-09 I 3 Series Audio, Navigation, Monitors, Alarms, \$F 65 00 09 January-09 I 3 Series Audio, Navigation, Monitors, Alarms, \$F 65 00 09 January-09 I 3 Series Audio, Navigation, Monitors, Alarms, \$F 65 00 09 January-09 I 3 Series Audio, Navigation, Monitors, Alarms, \$F 65 00 09 January-09 I 3 Series Audio, Navigation, Monitors, Alarms, \$F 65 00 09 February-09 I 3 Series Audio, Navigation, Monitors, Alarms, \$F 65 00 09 February-09 I 3 Series Audio, Navigation, Monitors, Alarms, \$F 65 00 09 February-09 I 3 Series Audio, Navigation, Monitors, Alarms, \$F 65 00 09 March-09 I 3 Series Audio, Navigation, Monitors, Alarms, \$F 65 00 09 March-09 I 3 Series Audio, Navigation, Monitors, Alarms, \$F 65 10 09 May-09 I 3 Series Audio, Navigation, Monitors, Alarms, \$F 65 10 09 May-09 I 3 Series Audio, Navigation, Monitors, Alarms, \$F 65 10 09 May-09 I 3 Series Audio, Navigation, Monitors, Alarms, \$F 65 10 09 May-09 I 3 Series Audio, Navigation, Monitors, Alarms, \$F 65 10 09 May-09 I 3 Series Audio, Navigation, Monitors, Alarms, \$F 65 10 09 May-09 I 3 Series Audio,					
Audio, Navigation, Monitors, Alarms, \$\frac{65}{19} 08\$ November-08 November-08 1 & 3 Series Interference Noises and/or Reception Varies in Certain Areas Audio, Navigation, Monitors, Alarms, Sf 65 20 8 November-08 E 93 Airbag Warning Illuminated, FC 9402 Audio, Navigation, Monitors, Alarms, Sf 65 20 8 November-08 I series Loss of Navigation GPS Position Audio, Navigation, Monitors, Alarms, Sf 65 24 08 December-08 M3/M5 Audio System Is Intermittently Inoperative Audio, Navigation, Monitors, Alarms, Sf 65 27 08 February-09 1,3,6 ser X5,X6 Audio, Navigation, Monitors, Alarms, Sf 65 02 09 January-09 1,36 ser Audio, Navigation, Monitors, Alarms, Sf 65 02 09 January-09 1 Series Audio Interference Noises in All Modes When Vehicle Is in Motion Audio, Navigation, Monitors, Alarms, Sf 65 05 09 July-09 All w/CIC Navigation, Monitors, Alarms, Sf 65 06 09 February-09 5, X5, X6 ESI Audio, Navigation, Monitors, Alarms, Sf 65 06 09 February-09 5, X5, X6 Ustrasonic Passeger Compartment Motion Detector Triggers False Alarm Audio, Navigation, Monitors, Alarms, Sf 65 10 09 March-09 X5, X6 Ustrasonic Passeger Compartment Motion Detector Triggers False Alarm Audio, Navigation, Monitors, Alarms, Sf 65 10 09 May-09 1,3,7 series Satellite Radio: Channel List May Be Empty or Channels Are Missing Audio, Navigation, Monitors, Alarms, Sf 65 12 09 March-09 X5, X6 Incorrect Test Plan for CID FC A48B Power Supply	Audio, Navigation, Monitors, Alarms, SF			E60/63	
Audio, Navigation, Monitors, Alarms, Sf 65 20 08 November-08 1 & 3 Series Interference Noises and/or Reception Varies in Certain Areas Airbag Warning Illuminated, FC 9402 Air					
Audio, Navigation, Monitors, Alarms, Sf 65 22 08 November-08 1 series Loss of Navigation GPS Position Audio, Navigation, Monitors, Alarms, Sf 65 22 08 November-08 1 series Loss of Navigation GPS Position Audio, Navigation, Monitors, Alarms, Sf 65 24 08 December-08 M3/M5 Audio System Is Intermittently Inoperative Audio, Navigation, Monitors, Alarms, Sf 65 27 08 February-09 1,3,5,6 ser X5,X6 Entertainment and Communication Systems are Inoperative Audio, Navigation, Monitors, Alarms, Sf 65 01 09 January-09 1,3,6 ser Incorrect Message in the USB Audio Interface Diagnosis Audio, Navigation, Monitors, Alarms, Sf 65 02 09 January-09 1 Series Audio Interference Noises in All Modes When Vehicle Is in Motion Audio, Navigation, Monitors, Alarms, Sf 65 05 09 July-09 All w/CIC Navigation, Monitors, Alarms, Sf 65 05 09 July-09 All w/CIC Navigation, Monitors, Alarms, Sf 65 06 09 February-09 5, X5, X6 LSI CID Is Blank, No Audio, CHAMP Resets and Is Then Inoperative Audio, Navigation, Monitors, Alarms, Sf 65 10 09 May-09 1,3,7 series Vehicle Position Is Missing or Incorrect On the Navigation Map Audio, Navigation, Monitors, Alarms, Sf 65 12 09 June-09 1,3,7 series Satellite Radio: Channel List May Be Empty or Channels Are Missing Audio, Navigation, Monitors, Alarms, Sf 65 12 09 June-09 X5, X6 Incorrect Test Plan for CID FC A48B Power Supply					
Audio, Navigation, Monitors, Alarms, SF 65 24 08 February-09 1,3,5,6 ser XS,X6 Entertainment and Communication Systems are Inoperative Audio, Navigation, Monitors, Alarms, SF 65 01 09 January-09 1,3,6 ser Incorrect Message in the USB Audio Interface Diagnosis Audio, Navigation, Monitors, Alarms, SF 65 02 09 January-09 1 Series Audio Interference Noises in All Modes When Vehicle Is in Motion Audio, Navigation, Monitors, Alarms, SF 65 03 09 March-09 7 Series (F01) Audio, Navigation, Monitors, Alarms, SF 65 06 09 July-09 All w/CIC Navigation, Monitors, Alarms, SF 65 06 09 February-09 5, XS, X6 LSI CID Is Blank, No Audio, CHAMP Resets and Is Then Inoperative Audio, Navigation, Monitors, Alarms, SF 65 08 09 March-09 X5, X6 Ultrasonic Passenger Compartment Motion Detector Triggers False Alarm Audio, Navigation, Monitors, Alarms, SF 65 10 09 May-09 1,3,7 series Vehicle Position Is Missing or Incorrect On the Navigation Map Audio, Navigation, Monitors, Alarms, SF 65 12 09 March-09 X5, X6 Incorrect Test Plan for CID FC A48B Power Supply	Audio, Navigation, Monitors, Alarms, SF	65 21 08	November-08	E93	Airbag Warning Illuminated, FC 9402
Audio, Navigation, Monitors, Alarms, Sf 65 07 08 January-09 1,3,5,6 ser X5,X6 Incorrect Message in the USB Audio Interface Diagnosis Audio, Navigation, Monitors, Alarms, Sf 65 07 09 January-09 1,3,6 ser Incorrect Message in the USB Audio Interface Diagnosis Audio, Navigation, Monitors, Alarms, Sf 65 07 09 January-09 1 Series Audio Interference Noises in All Modes When Vehicle Is in Motion Audio, Navigation, Monitors, Alarms, Sf 65 07 09 July-09 All w/ClC Navigation, Monitors, Alarms, Sf 65 07 09 July-09 All w/ClC Navigation, Monitors, Alarms, Sf 65 08 09 February-09 5, X5, X6 LSI ClD Is Blank, No Audio, CHAMP Resets and Is Then Inoperative Audio, Navigation, Monitors, Alarms, Sf 65 08 09 March-09 X5, X6 Ultrasonic Passenger Compartment Motion Detector Triggers False Alarm Audio, Navigation, Monitors, Alarms, Sf 65 10 09 May-09 1,3,7 series Vehicle Position Is Missing or Incorrect On the Navigation Map Audio, Navigation, Monitors, Alarms, Sf 65 12 09 June-09 1,3 series Satellite Radio: Channel List May Be Empty or Channels Are Missing Audio, Navigation, Monitors, Alarms, Se 65 13 09 March-09 X5, X6 Incorrect Test Plan for CID FC A48B Power Supply					
Audio, Navigation, Monitors, Alarms, Sf 65 01 09 January-09 1,3,6 ser Incorrect Message in the USB Audio Interface Diagnosis Audio, Navigation, Monitors, Alarms, Sf 65 02 09 January-09 1 Series (FCI) Side View Camera Has Blurred Hange Audio, Navigation, Monitors, Alarms, Sf 65 05 09 July-09 All w/CIC Navigation, Monitors, Alarms, Sf 65 06 09 February-09 5, X5, X6 LSI CID Is Blank, No Audio, CHAMP Resets and Is Then Inoperative Audio, Navigation, Monitors, Alarms, Sf 65 08 09 March-09 X5, X6 Ultrasonic Passenger Compartment Motion Detector Triggers False Alarm Audio, Navigation, Monitors, Alarms, \$ 65 10 09 May-09 1,3,7 series Vehicle Position Is Missing or Incorrect On the Navigation Map Audio, Navigation, Monitors, Alarms, \$ 65 11 09 May-09 1,3 series Satellite Radio: Channel List May Be Empty or Channels Are Missing Audio, Navigation, Monitors, Alarms, \$ 65 12 09 June-09 X5, X6 Incorrect Test Plan for CID FC A48B Power Supply					
Audio, Navigation, Monitors, Alarms, \$F 65 03 09 March-09 7 Series (F01) Side View Camera Has Blurred Image Audio, Navigation, Monitors, Alarms, \$F 65 05 09 July-09 All w/ClC Navigation System Road Map (rpl 3/09) Audio, Navigation, Monitors, Alarms, \$F 65 06 09 February-09 5, X5, X6 LSI CID Is Blank, No Audio, CHAMP Resets and Is Then Inoperative Audio, Navigation, Monitors, Alarms, \$F 65 08 09 March-09 X5, X6 Ultrasonic Passenger Compartment Motion Detector Triggers False Alarm Audio, Navigation, Monitors, Alarms, \$F 65 10 09 May-09 1,3,7 series Vehicle Position Is Missing or Incorrect On the Navigation Map Audio, Navigation, Monitors, Alarms, \$F 65 10 09 May-09 1,3,7 series Satellite Radio: Channel List May Be Empty or Channels Are Missing Audio, Navigation, Monitors, Alarms, \$F 65 12 09 June-09 1,3 series RAD2: Audio Is Intermittently Inoperative (rpl 4/09) Audio, Navigation, Monitors, Alarms, \$F 65 13 09 March-09 X5, X6 Incorrect Test Plan for CID FC A48B Power Supply	Audio, Navigation, Monitors, Alarms, SF	65 01 09	January-09	1,3,6 ser	Incorrect Message in the USB Audio Interface Diagnosis
Audio, Navigation, Monitors, Alarms, \$ 65 05 09					
Audio, Navigation, Monitors, Alarms, Sf 65 06 09 February-09 5, X5, X6 LSI CID is Blank, No Audio, CHAMP Resets and Is Then Inoperative X5, X6 Ultrasonic Passenger Compartment Motion Detector Triggers False Alarm Audio, Navigation, Monitors, Alarms, \$ 65 10 09 May-09 1,3,7 series Vehicle Position is Missing or Incorrect On the Navigation Map Audio, Navigation, Monitors, Alarms, \$ 65 11 09 May-09 1,3,7 series Satellite Radio: Channel List May Be Empty or Channels Are Missing Audio, Navigation, Monitors, Alarms, \$ 65 12 09 June-09 1, 3 series RAD2: Audio is Intermittently Inoperative (rpl 4/09) Audio, Navigation, Monitors, Alarms, \$ 65 13 09 March-09 X5, X6 Incorrect Test Plan for CID FC A48B Power Supply					
Audio, Navigation, Monitors, Alarms, Sf 65 08 09 March-09 X5, X6 Ultrasonic Passenger Compartment Motion Detector Triggers False Alarm Audio, Navigation, Monitors, Alarms, \$ 65 10 09 May-09 1,3,7 series Vehicle Position Is Missing or Incorrect On the Navigation Map Audio, Navigation, Monitors, Alarms, \$ 65 11 09 May-09 1,3 resident Audio, Navigation, Monitors, Alarms, \$ 65 12 09 June-09 1,3 series RAD2: Audio, Navigation, Monitors, Alarms, \$ 65 13 09 March-09 X5, X6 Incorrect Test Plan for CID FC A48B Power Supply					
Audio, Navigation, Monitors, Alarms, \(\) 65 11 09 May-09 1,3,7 series Satellite Radio: Channel List May Be Empty or Channels Are Missing Audio, Navigation, Monitors, Alarms, \(\) 65 12 09 June-09 1, 3 series RAD2: Audio Is Intermittently Inoperative (rpl 4/09) Audio, Navigation, Monitors, Alarms, \(\) 65 13 09 March-09 X5, X6 Incorrect Test Plan for CID FC A48B Power Supply					
Audio, Navigation, Monitors, Alarms, \$ 65 12 09 June-09 1, 3 series RAD2: Audio Is Intermittently Inoperative (rpl 4/09) Audio, Navigation, Monitors, Alarms, \$ 65 13 09 March-09 X5, X6 Incorrect Test Plan for CID FC A48B Power Supply					
Audio, Navigation, Monitors, Alarms, \$ 65 13 09 March-09 X5, X6 Incorrect Test Plan for CID FC A48B Power Supply					
Audio, Navigation, Monitors, Alarms, \$ 65 14 09 April-09 3 series Active Head Restraint Cannot Be Locked Back into Position	Audio, Navigation, Monitors, Alarms, \$	65 13 09	March-09	X5, X6	Incorrect Test Plan for CID FC A48B Power Supply
	Audio, Navigation, Monitors, Alarms, \$	65 14 09	Apríl-09	3 series	Active Head Restraint Cannot Be Locked Back into Position

			Complied and edited	u by cobladav
Category	SIBs (SI B## ## ##)	<u>Date</u>	<u>Application</u>	<u>Title</u>
Audio, Navigation, Monitors, Alarms,		June-09	X5, X6	DWA Siren Too Quiet When Locking and Unlocking (rpl 4/09)
Audio, Navigation, Monitors, Alarms,		June-09	1, 3 series	RAD2: Audio and/or Radio Display Is Intermittently Inoperative
Audio, Navigation, Monitors, Alarms,		May-09	E60/61	Service Action: HD® Radio Activation
		June-09	E65/66	ISTA/P Prompts to Replace CDC
Audio, Navigation, Monitors, Alarms,				
Audio, Navigation, Monitors, Alarms,		June-09	X5	Airbag Warning Lamp Illuminated, FC 93C6
Audio, Navigation, Monitors, Alarms,		June-09	All w/CIC	Artist and Song Title are Not Displayed
Audio, Navigation, Monitors, Alarms,	65 23 09	July-09	1, 3 series	RAD2: Audio Volume Fluctuates
01, 11, 1	4, 20 other model, 05, 09, 10, 12, 13, 29, 38,	40 NU,		
Distance Systems, Cruise Control, Rem	n - 01 other model		E65	
Distance Systems, Cruise Control, Rem	n 66 01 04	March-08	X3	315MHz Remote Control Range Is Inadequate or Inoperative
Distance Systems, Cruise Control, Rem	n 66 03 05	November-05	E60/E63	PDC and Gong Volume Cannot be Adjusted
Distance Systems, Cruise Control, Rem	n 66 01 06	February-06	E90	PDC Button not Installed (Supercedes Feb 06 with added info)
Distance Systems, Cruise Control, Rem	n 66 04 06	March-07	E60/E63	Night Vision Malfunctions and Parts Replacement (update to 11/06)
Distance Systems, Cruise Control, Rem	n 66 05 06	September-06	E61	Vehicle Does Not Start
Distance Systems, Cruise Control, Rem		December-06	All	Remote Control Key Not Working
Distance Systems, Cruise Control, Rem		March-07	All	Comfort Access: Replacement ID Transmitter Initialization
Distance Systems, Cruise Control, Rem		September-07	E60/E63	Unexpected Lane Departure Warning
Distance Systems, Cruise Control, Rem		October-07	ALL	Universal Garage Door Opener Cannot be Programmed
Distance Systems, Cruise Control, Rem		February-08	E91	PDC Gong volume low
		i ebidaiy-oo	Lai	1 DC Gorig volume low
Distance Systems, Cruise Control, Rem		March-08	X5 (E70)	Seal Must Be Replaced when Rear View Camera Is Removed
Distance Systems, Cruise Control, Rem				
Distance Systems, Cruise Control, Rem		May-08	1 Series	PDC and Warning Gong Volume too Low
Distance Systems, Cruise Control, Rem		October-08	E61	Remote Control Malfunction or Radio Reception Problem
Distance Systems, Cruise Control, Rem		January-09	E63/E64 M6	PDC Malfunction
Distance Systems, Cruise Control, Rem		March-09	3 Series	PDC Ultrasonic Sensor(s) Become Discolored
Distance Systems, Cruise Control, Re		April-09	F01/02	Windows or Sunroof Do Not Open with Remote Control
Distance Systems, Cruise Control, Re		April-09	F01/02	Night Vision: Pedestrian Recognition Is Intermittently Inoperative
Distance Systems, Cruise Control, Re	66 05 09	April-09	F01/02	Night Vision System Is Intermittently Inoperative
Distance Systems, Cruise Control, Re	66 06 09	April-09	F01/02	Side View Camera Has Blurred Image
Distance Systems, Cruise Control, Re	66 07 09	April-09	F01/02	Erroneous Fault Code Entries in the TRSVC Module
Distance Systems, Cruise Control, Re		June-09	X5 (E70)	Failure of Remote Control Locking
			• •	
	03, 06 for other model 02 other model			
Vehicle Tools	71 01 07	September-07	W/Sunroof	Sunroof Emergency Operation Tool Eliminated
Vehicle Tools	71 01 08	March-08	3/5/6/Z series	Combination Wrench Eliminated from the Vehicle Tool Kit
Safety Restraint Systems	72 05 04	June-04	E60/E63	Various "Self-Test" Faults Stored in "Byteflight" Modules
Safety Restraint Systems	72 02 05	August-06	E60/E65/E90	Passenger Airbag Status Lamp Goes ON/OFF During Driving (Replaces 1/06)
Safety Restraint Systems	72 03 05	June-05	E64 (Cabrio)	Check Control Message "Rollover Protection Fault"
Safety Restraint Systems	72 09 05	November-05	E64 (Cabrio)	Service Action: Reprogram Control Modules for Backrest Lock Microswitch
Safety Restraint Systems	72 02 06	June-06	ALL	Airbag Warning Lamp for OC3 Seat Mat Fault (Supercedes Mar 06 w/new parts info)
Safety Restraint Systems	72 03 06	January-06	E64 (Cabrio)	Airbag Warning Lamp Illuminated for Backrest Microswitch
Safety Restraint Systems	72 04 06	January-06	È90	Rear Belt Tensioners Deploy in Accident
Safety Restraint Systems	72 05 06	February-06	E60	Airbag Warning Illuminated, FC 9B2D in SFZ
Safety Restraint Systems	72 08 06	April-06	E90	OC3 Occupancy Status does not Change
Safety Restraint Systems	72 09 06	August-06	E90	Airbag Warning Lamp, FC93EB (Update to Apr -06)
Safety Restraint Systems	72 10 06	November-06	E90	Airbag Warning Lamp Illuminates - No Fault Codes (Replaces Apr 06)
Safety Restraint Systems	72 18 06	October-06	E60	Various Telegram Errors in Satellites
Safety Restraint Systems	72 19 06	October-06	E63	Various Fault Memory Entries in the SBE
Safety Restraint Systems	72 20 06	October-06	E60	SBSL/SBSR FC 9845/98C5, implausible crash severity
Safety Restraint Systems	72 24 06	October-06	E60	Rear Side Airbags Come Activated
Safety Restraint Systems	72 25 06	October-06	E60	FC 96CA: Passenger Thorax Airbag Resistance too Great
Safety Restraint Systems	72 26 06	October-06	E60	SGM FC 9413 "Signal Lamp Airbag Deactivation"
Safety Restraint Systems	72 28 06	December-06	E92	Seatbelt Assistant "hand" Portion Breaks Off
Safety Restraint Systems	72 29 06	December-06	E60/E63/E65	DIS Test Plan Error While Performing SIM/SGM Self Test
Safety Restraint Systems	72 01 07	January-07	E90/E91	Airbag Warning Lamp Illuminated, FC 93C1/93C3
Safety Restraint Systems	72 03 07	August-07	E92	Seat Belt Assistant Pinch Protection (updates 3/07)
Safety Restraint Systems	72 04 07	May-07	E63/64	Recall Campaign 07V-178: Replace the Seat Occupancy Detection Mat
Safety Restraint Systems	72 05 07	April-07	E92	Seat Belt Assistant Malfunction
Safety Restraint Systems	72 01 08	May-08	E92	Passenger Seat Belt Assistant Extends Unexpectedly
Safety Restraint Systems	72 01 09	March-09	F01/02	Front Seat Belt Electric Motor Driven Reel Activates Unexpectedly
Safety Restraint Systems	72 02 09	Z4	E89	Service Action: Belt Tensioner Harnesses
	07 other med-1			
	-07 other model			
Communication Systems	84 14 01	November-06	E60/E63	Telephone Installation on New Vehicles Replaces Mar 05)
Communication Systems	84 01 03	December-05	E60/E63	CPT9000 Telephone (Supercedes Aug 05 w/new info)
Communication Systems Communication Systems	B840103E60Telephone	P/O 84 01 03	E60/E63	E60/E63 TCU Wiring Diagram
Communication Systems	84 15 03	March-08	E60/E63	BMW Assist Initialization (now using GSM Rpl 11/06)
Communication Systems Communication Systems	B841503Diagnosis	P/O 85 15 03	E60/E63	Troubleshooting Guide (Flowchart)
Communication Systems Communication Systems	84 214 04	September-05	E60/E63	Linked Sequence calls Fail on Bluetooth (REPLACED BY 84 18 05)
Communication Systems Communication Systems	84 214 04 84 02 04	May-05	E60/E63	Navigation Map DVD for Vehicles with CCC
Communication Systems	84 03 04 84 10 04	July-04	E60	MFL Button Dials "911", or Last Number Dialed
Communication Systems	84 10 04	July-04	E60	CCC Navigation Retrofit Kit
Communication Systems	B841004Installer	P/O 84 10 04	E60	Installation Instructions
Communication Systems	B841004SalesBulletin	P/O 84 10 04	E60	Product Planning MY 04 5 Series
Communication Systems	84 12 04	September-07	E60/E63	Diagnosis and Repair of the CCC (updates 2/06)
Communication Systems	84 12 04 Attachment	September-07	E60/E63	DVD Screws attachment
Communication Systems	84 13 04	November-07	E60/E63	BMW Assist with Integrated Bluetooth (Rpl Mar 07)
Communication Systems	B841304BluetoothDiagnosis	P/O 84 13 04	E60/E63	Diagnostic Instructions for Bluetooth Telephone Systems
Communication Systems	B841304BluetoothUserManuallBus.	P/O 84 13 04	E60/E63	Bluetooth Users Manual for Business Phone
Communication Systems	B841304BluetoothUserManualE60E63	P/O 84 13 04	E60/E63	Bluetooth Users Manual for CPT9000 and Bluetooth
Communication Systems	84 14 04	October-04	E60/E63	Service Action: Activate SVS (Voice Recognition System)
Communication Systems	B841404Q&A	P/O 84 14 04	E60/E63	FAQ
Communication Systems	84 01 05	July-05	E60/E63	Service Action: Reactivate TCUs for specified Production models that were accidently deactivated
Communication Systems	84 04 05	January-07	E60/E63	Nav system missing or incorrect data (Replaces April 05)
Communication Systems	84 07 05	June-05	E60/E63	Motorola v710 Handset Phonebook does not download
Communication Systems	84 08 05	April-07	E60 /E90	CID switches between BMW banner and blank screen (Rpl 3/06 - adds E90 & new procedure)
Communication Systems	84 09 05	June-05	E60/E63	CCC NAV places of interest (POIs)
Communication Systems	B800905POICategories	P/O 84 09 05	E60/E63	PDF of categories and sub categories
Communication Systems	B800905POI_ICONS	P/O 84 09 05	E60/E63	PDF of ICON symbols
Communication Systems	84 10 05	May-06	E60/E63/E90	Nav Displays incorrect Vehicle Position (Supercedes Mar 06) - Replaced with 65 23 07
Communication Systems	84 11 05	June-05	E60/E63	CCC CD/DVD disc does not eject
Communication Systems	84 12 05	April-06	E60/E63	DVD Drive makes clicking noise (Supercedes Aug 05 w/E90)
Communication Systems	84 13 05	May-07	E60/E63/E90	Bluetooth Phone call may still be displayed as active after the call has ended (Rpl 3/07 - adds E90)
Communication Systems	84 14 05	August-08	All	Retrofitting a Telematics Control Unit (TCU) with Bluetooth® Technology (update to 9/07)
Communication Systems	84 14 05 Attachment	September-07	All	Special Inst for E6x
Communication Systems	84 18 05	September-05	E60/E63	Linked Sequence calls Fail on Bluetooth and CPT9000 Handsets
Communication Systems	84 19 05	September-05	E90	Teleservice does not place call for CBS due
Communication Systems	84 24 05	August-06	E60/E63/E90	CCC Voice Input System Incorrectly States Speed Limit in "km" (Supercedes Nov 05)

Category	SIBs (SI B## ## ##)	<u>Date</u>	Application	<u>Title</u>
Communication Systems	84 25 05	January-06	E90	Software error in the Telematics Control Unit (TCU). (Supercedes Dec 05)
Communication Systems	84 02 06	January-06	All	Hands free Bluetooth® Phone Call May be Lost if a Call Waiting Call is Received
Communication Systems	84 03 06	March-07	All	Enhanced Support for CCC Car Communication Computer (Supercedes Dec 06)
Communication Systems	84 04 06 84 05 06	July-06	All All	Service Action: Reactivation of Telematics Control Unit (TCU) (Replace Mar 06)
Communication Systems Communication Systems	84 05 06 84 06 06	March-07 March-06	All	Diagnosis of Bluetooth® Handset Related Complaints (Rpl Mar 06) Information Displayed in the BMW Assist Menu is Incorrect or Unknown
Communication Systems Communication Systems	84 08 06	March-06	All	CCC Navigation is Inoperative at Low Ambient Temperatures
Communication Systems	84 09 06	October-07	All	Bluetooth® Inoperative, TCU FC# A379 or 79 (update to 04/07)
Communication Systems	84 10 06	August-07	E60/E63/E90	BMW Assist or Bluetooth® Inoperative, TCU FC# A379 (rpl 4/06)
Communication Systems	84 14 06	May-07	E60/E63/E90	Service Action: Reactivation of Telematics Control Unit (TCU) - (superceded Dec 06)
Communication Systems	84 15 06	May-06	E60/E63/E90	CCC Navigation Address Book Shows Duplicate Entries after Programming
Communication Systems	84 18 06	June-06	E60/E63/E90	Low Bluetooth Signal is Displayed in the Handset or the Bluetooth® Connection is Lost
Communication Systems	84 20 06	September-06	E60/E63/E90	CCC Navigation Stuck on "Accept" Screen(Superedes Jun 06)
Communication Systems	84 23 06	May-07	E60/E63/E90	Service Action: Telematics Control Unit (TCU) - MOST-bus Vehicles Supercedes Dec 06)
Communication Systems	84 25 06	January-09	E60/E63/E90/E65	NAD Check, Recovery or Deactivation Procedure (MOST-Bus vehicles) (rpl 6/08)
Communication Systems	84 26 06	July-08	E60/E63/E90/E65	Cannot Enable BMW Assist Services (Supercedes Aug 06)
Communication Systems	84 27 06	July-08	E60/E63/E90/E65	BMW Assist Inactive Warning Message Displayed (Supercedes Aug 06)
Communication Systems	84 48 06	October-06	E60/E63	CPT9000 (V60s) Telephone Switches to Silent Mode when Connected to Vehicle
Communication Systems	84 49 06	October-07	E60/E63	Vehicle Dials BMW Assist on its Own (update to 10/06)
Communication Systems	84 50 06	October-06	E60/E63	CPT9000 Handset Phone does not Load into Vehicles
Communication Systems	84 51 06	October-06	E60/E63	The BMW Assist "Embedded" Phone Rings Erroneously in the Vehicle
Communication Systems	84 58 06	November-06	E60/E63/E90/E92	Real Time Traffic Information w/PDF attachment (Updated in Nov 06)
Communication Systems	84 59 06	June-09	3 Series	CCC Telephone Address Book Not in Alphabetical Order (rpl 10/06)
Communication Systems	84 61 06	March-07	E60/E63/E90/E92	CCC Navigation System Pop-up Arrow Display Missing During Route Guidance (rpl 10/06)
Communication Systems	84 62 06	July-08	E60/E63/E90/E92	Progman Displays 'The TEL Control Module is Malfunctioning' on the Final Report
Communication Systems	84 01 07	January-07	E60/E63/E90/E92	CCC SVS: Letter and Number Inputs by Voice are Misinterpreted
Communication Systems	84 02 07	March-07	E60/E63/E90/E92	Service Action: Activation of Telematics Control Unit (TCU)
Communication Systems	84 04 07	March-07	E60/E63/E90/E92	Bluetooth® Handsets No Longer Pairs to the Vehicle
Communication Systems	84 05 07	August-07		2 Checking NAD Signal Strength for BMW Assist
Communication Systems Communication Systems	84 06 07 84 07 07	March-07 July-08	E90 E60/E63/E90	Call Cannot be Answered if the Voice Recognition System (SVS) is Active NAD was Found to be Faulty when Performing SI B84 22 05 (Reactivation of BMW Assist Services)
Communication Systems Communication Systems	84 07 07 84 08 07	July-06 June-09	E60/E63/X5/Z4	Service Action: Activation of Telematics Control Unit (TCU) (rpl 8/07)
Communication Systems	84 09 07	July-07	E60/E63/E90	Echo on Landline Side of Phone Call
Communication Systems	84 11 07	April-08	E60/E90	Service Action: Replace the Hands-Free Charging Electronics (MULF2-High) rpl 7/07
Communication Systems	84 12 07	July-07	E60/E63/E90/E92	Voice Only Call, No Data Transmitted When Placing a BMW Assist Call
Communication Systems	84 13 07	July-07	E60/E63/E90/E92	BMW Assist Location (GPS) Unknown or Inaccurate, When Placing a BMW Assist Call
Communication Systems	84 16 07	September-07	E60/E63/E90/E92	Erroneous SOS Inactive Warning Message (rpl 7/07)
Communication Systems	84 17 07	July-08	E60/E63/E90/E92	SOS Inactive Warning Message, No Communication with TCU (rpl 09/07)
Communication Systems	84 18 07	June-09	E60/E63/E90/E92	Enable Services Status Bar Does NOT Progress (rpl 8/07)
Communication Systems	84 19 07	October-07	E60/E63/E90/E92	One Way Audio when Using a Bluetooth Enabled Handset
Communication Systems	84 20 07	October-08	All w/TCU	Upgrading BMW Assist to Support New Bluetooth Handsets (rpl 11/07)
Communication Systems	84 21 07	November-07	All w/TCU	Diagnosis When an Unapproved Handset is Paired to a Vehicle
Communication Systems	84 01 08	June-08	3/5/6/7/X series	Pairing between the iPhone and the Vehicle Fails
Communication Systems	84 02 08	March-08	All w/TCU	Service Action: Initialize BMW Assist Services (SC VPC on 3/3/08)
Communication Systems	84 03 08	November-08	X3	Echo and Poor Voice Quality on the Landline Side of a Call (rpl 05/08)
Communication Systems	84 04 08 84 05 08	June-08 September-08	E60 E60/E90/E83	Service Action: Update BMW Assist Services Service Action: Reactivation of Telematics Control Unit (TCU)
Communication Systems Communication Systems	84 06 08	September-08	3 Series	CIC: Unable to Select an Address via the Contact Book
Communication Systems	84 07 08	September-08	1/3/5/6 series	Echo and Reverberation on the Landline during a Hands-free Call
Communication Systems	84 08 08	September-08	1/3/5/6/X series	BMW Assist Menu Item
Communication Systems	84 09 08	October-08	1/3 series	Service Due CC Message Appears Before Handover Inspection
Communication Systems	84 11 08	January-09	All	BMW Assist Inoperative in Certain Areas (rpl 10/08)
Communication Systems	84 12 08	June-09	All	TCU Symptom Diagnosis (rpl 11/08)
Communication Systems	84 13 08	December-08	Z4	Poor Voice Quality on the Receiving End When Placing a Telephone Call
Communication Systems	84 02 09	February-09	All	Telephone - Incomplete Contact List Available in Vehicle
Communication Systems	84 03 09	February-09	All	Telephone Contacts Cannot Be Deleted from the CIC
Communication Systems	84 04 09	June-09	All	The Landside Person Finds the Caller Speaking from an iPhone 3G Hard to Understand (rpl 3/9)
Communication Systems	84 06 09	May-09	All	Telephone: Humming or Pulsing Noise Coming from the Vehicle Loudspeakers
Communication Systems	84 08 09	May-09	1, 3, 5, 6, 7 series	Telephone: Poor Voice Quality at Landside End
Communication Systems	84 09 09	June-09	1, 3, 5, 6, 7, X5/6	BMW Assist Services - Vehicle Position Incorrect
Communication Systems	84 10 09	June-09	All	BMW Assist " MyInfo" Troubleshooting Tips

01, 03, 10, other models or minor

Rev 20 published

NOTE: Text in Maroon represents new data or updated since previous edition (SIB_List_rev_19, published 8 April 2009)
Red = Safety recall notice
Bold = Service Action or Recall campaigns
Another Service Bulletin resource ---> Checkout periodically to see if they keep current
This link seems to have been closed to non-subscribers sometime in January 2007

No Longer available free http://www.alldata.com/tsb/BMW/index-post.html