
Status report

Date / time: 01.11.2005 / 13:06
Model series: E60
Vehicle ident. no.: WBANC92090B891731
Vehicle data status: E060-05-06-510
Target data status: E060-05-09-530

Following ctrl units have failed to respond or have responded incorrectly.

TEL/ULF	must be reprogrammed <i>Part no., progr. ECU:</i> 6972692 (is) 6979766 (should)
GW	must be reprogrammed <i>Part no., progr. ECU:</i> 6967606 (is) 6983876 (should)
CCC-ASK	must be reprogrammed <i>Part no., progr. ECU:</i> 6953823 (is) 6977342 (should)
CCC-ANT	must be reprogrammed <i>Part no., progr. ECU:</i> 6955217 (is) 6971519 (should)
BO	must be reprogrammed <i>Part no., progr. ECU:</i> 6966353 (is) 6981599 (should)
CCC-A	must be reprogrammed <i>Part no., progr. ECU:</i> 6974256 (is) 6987744 (should)
DME/DDE	must be reprogrammed <i>Part no., progr. ECU:</i> 7798419 (is) 7799764 (should)
PDC	must be reprogrammed <i>Part no., progr. ECU:</i> 6954007 (is) 6978232 (should)
LM	must be reprogrammed <i>Part no., progr. ECU:</i> 6962722 (is) 6983537 (should)
KOMBI	must be reprogrammed <i>Part no., progr. ECU:</i> 6974577 (is) 6983154 (should)
KBM	must be reprogrammed <i>Part no., progr. ECU:</i> 6974310 (is) 6978713 (should)
IHKA	must be reprogrammed <i>Part no., progr. ECU:</i> 6950634 (is) 6978435 (should)