

Status report

Date / time: 27.01.2006 / 08:16
Model series: E63
Vehicle ID number: WBAEH73425B193184
Vehicle data status: E060-05-03-520
Target data status: E060-05-09-535

Following ctrl mod.s have failed to respond or have responded incorr..

TEL/ULF	must be reprogrammed <i>Part no., progr. ctrl mod.:</i> 6972697 (is) 6982068 (should)
AMP	must be reprogrammed <i>Part no., progr. ctrl mod.:</i> 6973618 (is) 6974723 (should)
CID	must be replaced <i>Part no., progr. ctrl mod.:</i> 6945660 (is) 6985868 (should)
SGM-SIM/ACSM	must be reprogrammed <i>Part no., progr. ctrl mod.:</i> 6962704 (is) 6975687 (should)
GW	must be reprogrammed <i>Part no., progr. ctrl mod.:</i> 6967606 (is) 6983876 (should)
HUD	must be reprogrammed <i>Part no., progr. ctrl mod.:</i> 6963886 (is) 6980897 (should)
CCC-ASK	must be reprogrammed <i>Part no., progr. ctrl mod.:</i> 6953837 (is) 6977346 (should)
CCC-ANT	must be reprogrammed <i>Part no., progr. ctrl mod.:</i> 6955217 (is) 6971519 (should)
BO	must be reprogrammed <i>Part no., progr. ctrl mod.:</i> 6966352 (is) 6981598 (should)
CCC-A	must be reprogrammed <i>Part no., progr. ctrl mod.:</i> 6974252 (is) 6987740 (should)
ARS	must be reprogrammed <i>Part no., progr. ctrl mod.:</i> 6769964 (is)