



Dealer Operator / General Manager	Sales New Vehicles	Sales Used Vehicles	Business Manager (F&I)	Service	Parts & Accessories	Administration
Date: 04/07 Bulletin # 65 04 07 Replaces		Source: Aftersales Business Development & Marketing Name: Elijah Bernard Title: Accessory Development Manager – Electronics Phone: (201) 307-4239				



# Aftersales Business Development & Marketing BMW Dealer Bulletin

## Subject: iPod Interface Cable for BMW vehicles equipped with Option SA 6FL (USB/ iPod Interface)



### General Information:

Aftersales is pleased to announce that the iPod Interface Cable for SA 6FL (USB/iPod Interface) will be included as part of the factory option.

**For vehicles equipped with option SA6FL, all BMW centers are now required to order the cable (Part #61 12 0 422 099) from their respective PDC and provide to the customer when the vehicle is first placed into service.**

### Parts Information:

**Part# 61 12 0 422 099**

For information in regards to compatible iPods or other devices please refer to **SI B 65 08 07**

### Warranty Information

The QC1/PDI payment to the dealer that submits the original retail delivery registration will automatically be increased by \$50 when the vehicle is equipped with option code SA 6FL. You need to take no additional action to receive this payment.

## **BMW Company Vehicles**


Reimbursement for performing the QC1/PDI on BMW company vehicles must still be requested by submitting a claim through DCSnet using the Spot Delivery codes as listed below:

Defect Code: 11 99 99 77 BV  
Labor Operation: 00 00 012  
Flat Rate Units: Refer to KSD for the flat rate units  
Sublet: \$50 (only when the vehicle is equipped with option SA 6FL)  
Sublet Code: 4

BMW Company vehicles delivered to field personnel may have already received a full QC1/PDI at the Vehicle Distribution Center (VDC) which serves your region. This should be evident upon arrival at your center by the absence of the usual protective seat and door panel covers and battery main disconnect cable, correct wipers already installed, the Monroney label is not affixed to the window, etc. VDC's affix a small orange-colored label onto the center console near the transmission selector lever which reads "QC1 already done at VDC!" If this label is found, remove it prior to delivery to the employee. Please verify that the QC1 has already been performed at a VDC by contacting your regional Distribution Manager with the chassis number.

The iPod Interface Cable should have been provided by the VDC with these vehicles when equipped with option SA 6FL.

Best regards,



Alan E. Harris  
Vice President  
Aftersales



Greg Marks  
Manager  
Aftersales Business  
Development & Marketing