



This Service Information bulletin supersedes S.I. B62 01 06 **dated January 2007**.

NEW designates changes to this revision

SUBJECT

Instrument Cluster Needles Vibrate

MODEL

E60, E61 (5 Series), E63, E64 (6 Series)

Vehicles produced up to February 27, 2007.

SITUATION

The speedometer and rev counter needles vibrate when the engine is at idle.

CAUSE

Instrument cluster software

NEW CORRECTION

Program the complete vehicle per SI B09 05 01 (Coding, Individualization, Programming), Procedure B, using **Progman V25.00.00** or higher.

NEW WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty.

Defect Code:	Refer to KSD
Labor Operation:	Refer to KSD
Labor Allowance	Refer to KSD

[Copyright © 2007 BMW of North America, LLC]