



---

**SUBJECT****Defect Code for Programming Prior to Accessory Retrofit****MODEL**

All

**GENERAL INFORMATION**

Software update programming is sometimes required as part of an electronic accessory installation. When connecting to Progman to perform "Retrofit Coding", the Status Report will indicate if a software update is required. This software update must be performed before the "Retrofit coding" can be carried out.

**A software update to prepare the vehicle for the "Retrofit Coding" of an accessory is covered under the New Vehicle Limited Warranty and must be claimed using defect code 72 60 93 02 00.**

Any other Progman programming and recoding of the vehicle software specifically associated with the installation of the accessory should be included in the customer pay installation charge. See Parts Information Bulletin 65 12 04.

For additional information concerning warranty claims for software update programming (Progman), refer to [SI B01 03 06](#).

**WARRANTY INFORMATION**

Covered under the terms of the BMW New Vehicle Limited Warranty.

**Software update that is performed as a result of an accessory retrofit:**

**Defect Code** **72 60 93 02 00**

Refer to the latest KSD version for appropriate labor allowances.

The warranty claim must include in the "Comments" section a clear reason for the programming work for example, "Software update for satellite radio retrofit".

All claims must be supported by copies of the Measures Plan and Final Reports produced at each stage of the programming process. These documents are to be printed and attached to the customers work order.