BMW Recommended *Bluetooth*® Mobile Phones

While *Bluetooth* wireless technology is a global standard, there are a variety of profiles that manufacturers can choose to implement in their *Bluetooth* devices. In certain cases, the BMW hands-free system and the *Bluetooth* mobile phone do not share the necessary profiles to work together as a hands-free system. For this reason, not all available *Bluetooth* phones are compatible with the BMW hands-free system. In the chart featured to the right, you will find a list of mobile phones[1] that have passed compatibility testing with the BMW hands-free system.

Carrier	Phone
Cingular	Blackberry 8700 [7,8] Motorola RAZR V3 Motorola Blk RAZR V3 Motorola V551 [3] Motorola V600 [3,5] Nokia 6310/6310i [3,5] Sony Ericsson T610/T616 [3,5] Sony Ericsson T637 [3,5] Sony Ericsson T68/T68i [3,5] Siemens S56 [3,5] Siemens S66 [3,4]
Sprint PCS	Sony Ericsson T608 [5] Treo 650 [6]
T Mobile	Motorola V3RAZR Motorola V330 [3,5] Motorola V600 [3,5] Sony Ericsson T610/T616 [3,5] Sony Ericsson T68/T68i [3,5]
Verizon Wireless	Motorola RAZR V3c Motorola E815 [3] Motorola V710 [2,3]

[1]This list is provided for reference only. The mobile phones listed here have passed compatibility tests as of the date of testing and meet or exceed minimum standards established by BMW. The list is not a warranty for phone performance or functionality. BMW makes no guaranteed or warrantees as to the performance of each phone while connected to your BMW via Bluetooth ® Wireless Technology. Furthermore, software releases by BMW, the phone supplier or the wireless carrier dated after testing might alter compatibility results. While many phones are offered with Bluetooth ® Wireless Technology, not all phones support the necessary profiles to work with your BMW. BMW does not guarantee availability or functionality with all wireless carriers. Functions such as synchronizing the address book and transferring a call into or out of the vehicle may function differently from phone to phone.

[2]The Motorola V710 mobile phone requires software 8700_01.40.0R to operate with the BMW hands-free system. See your authorized Verizon Wireless retailer for details.

[3]Optional docking cradle available – Please visit your BMW center for complete details on available cradles.

[4]This phone only works on BMWs produced March 2005 or later, April 2005 and later on Z4 and X5 Models, September 2005 and later on 7 Series.

[5]Prevously available.

[6]The Treo 650 is compatable after updating it with software versoin 1.12. Download this update to your PC at http://www.palmone.com/us/support/sprintup05/ and then hot sync to your Treo 650. Update support is also provided at Sprint retail stores. Only phone numbers stored as Speed Dial entries will be accessible from your BW. Your BMW will not be able to access phone numbers stored as Contacts in your PalmOne Treo 650.

[7]Only entries in the Address Book will be accessible from your BMW. SIM Phone Book entries should be copied to the Address Book in order to be accessed from your BMW.

[8]The Cingular Blackberry 8700 requires software SW V4.1.0.194 to operate with the BMW hands-free system. See your authorized Cingular dealer for details.