E60 - Encoding/programming US car phone

Encoding

The TCU (Telematic Control Unit) must be recoded for the following cases:

- Exchange of TCU

- Retrofit Motorola Phoenix V60i mobile phone and eject box

- Activation or deactivation of BMW Service telematic services

- Exchange of M-ASK (Multi-audio system controller)

- Exchange of CCC (Car Communication Computer)

Important: After replacing the TCU (Telematic Control Unit), perform encoding/ programming.

- Perform flash programming using OPPS/OPS (optical testing and programming system/optical programming system) as standard on the new TCU (Telematic Control Unit).

- Programming time will be longer if programming is performed using the OBD interface (on-board diagnosis).