This is the ISTA coolant bleed process.




VIN C365307
Vehicle 5'/E60/SEDAN/528i/N52/AUTO/US/LL/2009/09
KL 15: --
KL 30: --
Operations
Vehicle information
Vehicle management
Service plan
Favourites
Workshop/ Operating fluids
Measuring devices
Repair/ Maintenance
Troubleshooting
Service functions
Software update
Control Unit Replacement
Vehicle modification
Product Structure
Text Search
Main groups
0 Maintenance and general data
11 Engine
12 Engine electrical system
13 fuel system
16 Fuel supply
17 cooling system
18 Exhaust system
21 clutch
22 Engine and gearbox suspension
23 Manual transmission
24 Automatic transmission
25 Gearshift
Selected structure elements
Hits:
Filter: Default
Undo all
Undo
Filters
Start search
Activate Windows
Go to Settings to activate Windows.
PAGE 1 OF 1
0 WORDS
150%
Type here to search
1:57 PM
2/19/2021


VIN C365307
Vehicle 5'/E60/SEDAN/528i/N52/AUTO/US/LL/2009/09
KL 15: --
KL 30: --
Operations
Vehicle information
Vehicle management
Service plan
Favourites
Workshop/ Operating fluids
Measuring devices
Repair/ Maintenance
Troubleshooting
Service functions
Software update
Control Unit Replacement
Vehicle modification
Service Functions
Layer 0
Power train
Chassis and suspension
Body
Maintenance and pre-delivery check
Vehicle information
BMW Group Mobile Service
Selected structure elements
Hits:
Filter: Default
Undo all
Undo
Filters
Start search
Activate Windows
Go to Settings to activate Windows.
PAGE 1 OF 2
0 WORDS
150%
Type here to search
1:58 PM
2/19/2021


ISTA+
VIN C365307
Vehicle 5'/E60/SEDAN/528i/N52/AUTO/US/LL/2009/09
KL 15: --
KL 30: --
Operations
Vehicle information
Vehicle management
Service plan
Favourites
Workshop/ Operating fluids
Measuring devices
Repair/ Maintenance
Troubleshooting
Service functions
Software update
Control Unit Replacement
Vehicle modification
Service Functions
Layer 1
Activating the suction jet pump transfer function
CAS
Engine electronics
Transmission control
Selected structure elements
Layer 1:
Power train
Hits:
Filter: Default


ISTA+
VIN C365307
Vehicle 5'/E60/SEDAN/528i/N52/AUTO/US/LL/2009/09
KL 15: --
KL 30: --
Operations
Vehicle information
Vehicle management
Service plan
Favourites
Workshop/ Operating fluids
Measuring devices
Repair/ Maintenance
Troubleshooting
Service functions
Software update
Control Unit Replacement
Vehicle modification
Service Functions
Layer 2
Adjustment functions
Cooling system
Fuel grade
OBD Readiness Codes
Test runs
Selected structure elements
Layer 1:
Power train
Layer 2:
Engine electronics
Hits:
Filter: Default


ISTA+
VIN C365307
Vehicle 5'/E60/SEDAN/528i/N52/AUTO/US/LL/2009/09
KL 15: --
KL 30: --
Operations
Vehicle information
Vehicle management
Service plan
Favourites
Workshop/ Operating fluids
Measuring devices
Repair/ Maintenance
Troubleshooting
Service functions
Software update
Control Unit Replacement
Vehicle modification
Service Functions
Layer 3
Ventilation, cooling system
Selected structure elements
Layer 1:
Power train
Layer 2:
Engine electronics
Layer 3:
Cooling system
Hits:
Filter: Default


ISTA+
VIN C365307
Vehicle 5'/E60/SEDAN/528i/N52/AUTO/US/LL/2009/09
KL 15: --
KL 30: --
Operations
Vehicle information
Vehicle management
Service plan
Favourites
Workshop/ Operating fluids
Measuring devices
Repair/ Maintenance
Troubleshooting
Service functions
Software update
Control Unit Replacement
Vehicle modification
Service Functions
Layer 4
Ventilation, cooling system
Selected structure elements
Layer 1:
Power train
Layer 2:
Engine electronics
Layer 3:
Cooling system
Layer 4:
Ventilation, cooling system
Hits:
Filter: Default


ISTA+
VIN C365307
Vehicle 5'/E60/SEDAN/528i/N52/AUTO/US/LL/2009/09
KL 15: --
KL 30: --
Operations
Vehicle information
Vehicle management
Service plan
Favourites
Workshop/ Operating fluids
Measuring devices
Hit list
Test plan
Programming plan
Flat Rate No
Type
Title
State
Ventilation, cooling system
ABL
Cooling system ventilation
FUB
Electric coolant pump
Hits: 2 / 2
Filter: Default
not called
performed
minimized
canceled
suspected
Activate Windows
Go to Settings to activate Windows.
Type here to search
2:02 PM
2/19/2021


ISTA+
VIN C365307
Vehicle 5'/E60/SEDAN/528i/N52/AUTO/US/LL/2009/09
KL 15: --
KL 30: --
Operations
Vehicle information
Vehicle management
Service plan
Favourites
Workshop/ Operating fluids
Measuring devices
Hit list
Test plan
Programming plan
Flat Rate No
Type
Title
State
Ventilation, cooling system
ABL
Cooling system ventilation
FUB
Electric coolant pump
Hits: 2 / 2
Filter: Default
not called
performed
minimized
canceled
suspected
Activate Windows
Go to Settings to activate Windows.
Type here to search
2:02 PM
2/19/2021


VIN C365307
Vehicle 5'/E60/SEDAN/528i/N52/AUTO/US/LL/2009/09
KL 15: --
KL 30: --
Operations
Vehicle information
Vehicle management
Service plan
Favourites
Workshop/ Operating fluids
Measuring devices
Hit list
Test plan
Programming plan
Flat Rate No
Type
Title
State
Ventilation, cooling system
ABL
Cooling system ventilation
FUB
Electric coolant pump
Hits: 2 / 2
Filter: Default
not called
performed
minimized
canceled
suspected
Back
Filters
Show completely
Display
ISTA+
ABL-DIT-B1214_NG6KME - Cooling system ventilation
Procedure
Functional Description
1. Switch on ignition.
2. Switch on low-beam headlight (preventing vehicle from going to sleep)
3. Both temperature selectors set to maximum
4. Press AUTO button of air conditioning system
Important! Not applicable for E90
5. Blower output to minimum
(do not switch off completely!)
6. Fully depress the accelerator pedal for 10 seconds
Do not start engine!
Bleeding of the cooling system is not activated.
Continue immediately after 5.
Functional description, see Vehicle Technology Diagnosis (VTD):
110304085
Hit next


ISTA+
VIN C365307 Vehicle 5'/E60/SEDAN/528i/N52/AUTO/US/LL/2009/09 KL 15: -- KL 30: --
ABL-DIT-B1214_NG6KME - Cooling system ventilation
Procedure
Functional Description
The bleeding procedure takes about 12 minutes
Current coolant pump speed:
224.0rpm
Remaining time:
4 min 42 s
Press Next to terminate
Functional description, see Vehicle Technology Diagnosis (VTD):
110304085
Activate Windows
Go to Settings to activate Windows.
PAGE 6 OF 7 0 WORDS
Type here to search
2:13 PM
2/19/2021


ISTA+
VIN C365307 Vehicle 5'/E60/SEDAN/528i/N52/AUTO/US/LL/2009/09 KL 15: -- KL 30: --
ABL-DIT-B1214_NG6KME - Cooling system ventilation
Procedure
Functional Description
Service function finished
Functional description, see Vehicle Technology Diagnosis (VTD):
110304085
Activate Windows
Go to Settings to activate Windows.
PAGE 7 OF 7 0 WORDS
Type here to search
2:18 PM
2/19/2021