Screenshot


167
Vehicle 5'/E60/SEDAN/530xi/N52/AUTO/US/LL/2010/03
KL 15: --
KL 30: --
Vehicle information
Vehicle management
Service plan
Favourites
Workshop/ Operating fluids
Measuring devices
Troubleshooting
Service functions
Software update
Control Unit Replacement
Vehicle modification
Fault pattern
Function Structure
Component Structure
NED
Text Search
SAE fault code input
Terminal 15: -
Terminal 3
Description
Mileage
Existent
Class
DSC: Transfer case: Malfunction 0 No
DSC: Brake-fluid level too low 0 yes
DSC: Interface, instrument cluster 0 yes
EKPS: Control current too low 524280 No
LM: Dipped beam, left, faulty 524280 No
LM: Sidelight, front left, faulty 524280 yes
LM: Sidelight, front right, faulty 524280 yes
LM: Front fog lamp, left, faulty 524280 yes
LM: Front fog lamp, right, faulty 524280 No
LM: Turn indicator, rear left, faulty 524280 No
LM: Brake light, left, faulty 524280 yes
LM: Brake light, right, faulty 524280 No
Status
Remaining programming
of fault memories: 76 / 76
No. fault patterns: 3
Filter: Default
Delete fault memory
Filter fault memory
Delete filter
Show completely
Calculate test plan
Warning
Available
Action necessary
Being prepared
Cannot be used