

BMW Bluetooth Preparation Compatibility Matrix

Brand	Model	Software	Option 644 (Bluetooth phone preparation)		Option 633 (Bluetooth phone preparation with telematics ability)		Additional Information				
			E39, E46, E53, E83, E85	E60/61, E63/64, E87, E90	E46, E53, E83, E85	E60/61, E63/64, E87, E90	SIA	HF	PhB	SMS	
Ericsson	T39m	R3A022	09/02-...					✓	✓	✓	✓
	T68	R7A005	(09/02-...)					✓	✓	✓	✓
Motorola	V525	OB.09.1DR_VA	06/04-...	06/04-...	09/04-...			✓	✓	✓	
	V600	OB.08.9FR	03/03-...	06/04-...				✓	✓	✓	
		OB.08.A2R_VA			09/04-...			✓	✓	✓	
		OB.09.1DR_A	03/03-...		09/04-...	03/05-...		✓	✓	✓	
		OB.09.1FR_A			09/04-...			✓	✓	✓	
		OB.09.1FR_AV			09/04-...			✓	✓	✓	
		OB.09.37R	03/03-...		09/04-...	03/05-...		✓	✓	✓	
		OB.09.38R	12/04-...	12/04-...	03/05-...	03/05-...		✓	✓	✓	
		OB.09.56R			03/05-...	03/05-...		✓	✓	✓	✓
		RAZR V3	OE.40.3CR	(12/04-...)		(03/05-...)			✓	✓	
		V635	08.48.04R	12/04-...		(03/05-...)			✓	✓	
	Nokia	6310	v4.20	09/02-...					✓	✓	✓
		v5.01	03/03-...					✓	✓	✓	✓
6310i		v4.80	(03/03-...)	(07/03-...)	(03/05-...)			✓	✓	✓	✓
		v5.22	03/03-...	07/03-...	09/04-...			✓	✓	✓	✓
		v5.50	06/04-...	03/04-...				✓	✓	✓	✓
		v5.51	06/04-...	03/04-...	09/04-01/05			✓	✓	✓	✓
		v5.52	(12/04-...)	12/04-...	03/05-...	03/05-...		✓	✓	✓	✓
		v5.60	(12/04-...)					✓	✓	✓	✓
		8910	v4.02	03/03-...					✓	✓	✓
		8910i	v4.46	03/03-...					✓	✓	✓
		v05.21	12/04-...	03/05-...	03/05-...			✓	✓	✓	
	7280	v03.22	12/04-...					✓	✓	✓	

	Tested & approved	SIA	Snap-in adaptor
	Tested & not compatible	HF	Hands-free
	Limited compatibility	PhB	Phone book transfer
	Not tested	SMS	Display text messages

Notes:

If the software level of the handsfree kit (JLH) or flash programming status of the MULF is not shown as compatible with particular handset software level, replacement cannot be reimbursed via warranty in this context.
 On option 644, the SMS display function is only available on the following models: E39, E46, E53, E83, E85. On option 633, the SMS function is not a feature of the system.
 BMW recommend that an approved mobile phone is always used in conjunction with a snap-in adaptor. If an adaptor is not available from BMW, it is still possible to use the hands-free functions, but it is not recommended.

BMW Bluetooth Preparation Compatibility Matrix

Brand	Model	Software	Option 644 (Bluetooth phone preparation)		Option 633 (Bluetooth phone preparation with telematics ability)		Additional Information					
			E39, E46, E53, E83, E85	E60/61, E63/64, E87, E90	E46, E53, E83, E85	E60/61, E63/64, E87, E90	SIA	HF	PhB	SMS		
Siemens	S55	10		07/03-...				✓	✓	✓	✓	
		12		07/03-...				✓	✓	✓	✓	
		16	06/03-...	07/03-...	09/04-...			✓	✓	✓	✓	
		20	(11/02-...)	07/03-...	(09/04-...)			✓	✓	✓	✓	
		91	12/04-...	12/04-...	01/05-...			✓	✓	✓	✓	
	S65	12	12/04-...	12/04-...	03/05-...		03/05-...	✓	✓	✓	✓	
		16	12/04-...	12/04-...	01/05-...		03/05-...	✓	✓	✓	✓	
			25	12/04-...	12/04-...	03/05-...		03/05-...	✓	✓	✓	✓
		Sony Ericsson	T610	R1A081	09/02-...	07/03-...				✓	✓	✓
R1L013				09/02-...	07/03-...				✓	✓	✓	✓
R4C003	09/02-...			07/03-...	09/04-...				✓	✓	✓	✓
R6C005	09/02-...			07/03-...	09/04-...				✓	✓	✓	✓
T630	R4C003		09/02-...	07/03-...	09/04-...		03/05-...	✓	✓	✓	✓	
	R4E002		09/02-...	07/03-...				✓	✓	✓	✓	
	R6C005		03/04-...	09/04-...	09/04-...		03/05-...	✓	✓	✓	✓	
	R7A011		12/04-...				03/05-...	✓	✓	✓	✓	
Z600	R2E004	09/02-...						✓	✓	✓		
	R5B001	09/02-...						✓	✓	✓		
	R6C005	09/02-...	07/03-...					✓	✓	✓		

	Tested & approved	SIA	Snap-in adaptor
	Tested & not compatible	HF	Hands-free
	Limited compatibility	PhB	Phone book transfer
	Not tested	SMS	Display text messages

Notes:

If the software level of the handsfree kit (JLFF) or flash programming status of the MULF is not shown as compatible with particular handset software level, replacement cannot be reimbursed via warranty in this context.
 On option 644, the SMS display function is only available on the following models: E39, E46, E53, E83, E85. On option 633, the SMS function is not a feature of the system.
 BMW recommend that an approved mobile phone is always used in conjunction with a snap-in adaptor. If an adaptor is not available from BMW, it is still possible to use the hands-free functions, but it is not recommended.