

CX02203 Notes

- No TPMS sensors installed in wheels
- Rear door cards without main sun shades
- Rear cargo elastic (passenger side) is an eye sore
- Oil filter housing gaskets weep a little oil
- Thermostat and H2O pump have unknown lifespan remaining
- Rear glass doesn't release
- OEM struts are tired and ride quality isn't great on the H&R springs
- Engine and transmission splash shields not installed (engine splash doesn't fit with M5 front end, transmission shield is missing)
- Passenger side long splash shield is missing some material
- M5 fender liners have wear from rubbing at lock to lock
- Battery isn't at 100% strength