

**COMPILED AND EDITED BY COBRADAV - COURTESY OF [knightsfortheroundel.com](http://knightsfortheroundel.com)**

<u>Category</u>	<u>SIBs (SI B## ## ##)</u>	<u>Date</u>	<u>Application</u>	<u>Title</u>
Maintenance and General Hints	00 04 02	July-05	All	BMW Group Technical Hotline
Maintenance and General Hints	00 06 03	November-03	All	General info on TIS Website
Maintenance and General Hints	00 01 05	June-06	All	New Vehicle Preparation and Maintenance Requirements (Supercedes Jan 06)
Maintenance and General Hints	B000105ATT_VehChk	P/O 00 01 05	525/530	Quality Certification Form
Maintenance and General Hints	00 02 06	March-07	All	New Vehicle Preparation and Maintenance Requirements (MY07) (Replece 11/06)
Maintenance and General Hints	00 01 07	March-07	E60	New Vehicle Preparation and Maintenance Requirements
<b>Maintenance and General Hints</b>	<b>00 03 07</b>	<b>August-07</b>	<b>ALL</b>	<b>PuMA Enhancements for TeileClearing Process</b>
Warranty	01 02 03	September-03	BMW Centers	BMW Maintenance Program 4 Years - 50,000 Miles
<b>Warranty</b>	<b>01 02 04</b>	<b>November-06</b>	<b>BMW Centers</b>	<b>BMW Tire Center Target Satisfaction Program</b>
Warranty	01 06 05	March-05	BMW Centers	BMW Maintenance Program 2005 Laminated Reference Chart and Mouse Pad
Warranty	B010605Attachment.	P/O 01 06 05	BMW Centers	Chart of Warranty Codes/Services
Warranty	01 07 05	March-05	BMW Centers	Warranty Claims Processing – "Overnight Payments"
Warranty	01 10 05	August-05	BMW Centers	TCU ESN Registration via DCSnet
Warranty	B011005Attachment.	P/O 01 10 05	BMW Centers	FAQ's for TCU Claims
<b>Warranty</b>	<b>01 01 06</b>	<b>June-07</b>	<b>BMW Centers</b>	<b>BMW Warranty Policy and Procedures Manual – Updates from 01/01/05 through 12/21/06</b>
Warranty	B010106Attachment	P/O 01 01 06	BMW Centers	BMW Warranty Policy and Procedures Manual – Updates from 01/01/05 through 12/21/05 rev notes
Warranty	01 02 06	February-06	BMW Centers	BMW Electronic Archiving System (EAS) Evaluation and Certification
Warranty	B010206EAS_Flowchart.	February-06	BMW Centers	EAS Flowchart
Warranty	01 03 06	February-07	BMW Centers	Warranty Claims for Software Update Programming (Progman) (Replace NOV 06)
Warranty	01 04 06	April-06	BMW Centers	Reasons for Vehicle Update Programming Reminder Magnet
Warranty	01 09 06	February-07	BMW Centers	Defect Code for Programming Prior to Accessory Retrofit (Supercedes 12/06)
Warranty	01 03 07	June-07	BMW Centers	New Pricing Plan and Program Enhancements - Maintenance Program Upgrade
After Sales Business Development	02 01 05	October-05	All	BMW Assist changes for September 2005
After Sales Business Development	B020105KeyBenefitChart	P/O 02 01 05	All	BMW Assist - Key Benefits
After Sales Business Development	02 01 06	February-06	All	Updated DCSnet Vehicle History Inquiry Information on BMW Assist™ (Supercedes Jan 06)
After Sales Business Development	02 02 06	November-06	All	BMW Assist™ Service Extension Incentive Program (Supercedes 02/06)
After Sales Business Development	02 01 07	February-07	All	Mobile Assistance Program
	no 07 yet			
Tools and Equipment	04 02 05	January-05	E60/E63	Zero-Coded Cover
Tools and Equipment	04 04 05	January-05	E60	Antenna Knife
Tools and Equipment	04 07 05	April-05	N52 Engine	N52 Special Tools
Tools and Equipment	04 08 05	February-05	E60/E63	Aluminum Body Tools
Tools and Equipment	04 13 05	March-05	E61	Tailgate Support
Tools and Equipment	04 14 05	April-05	E60/E63	CD Eject Tool
Tools and Equipment	04 15 05	May-05	E90	DME Test Cable
Tools and Equipment	04 29 05	November-05	E60/E63	AC Sprayer Wand
Tools and Equipment	04 02 06	January-06	M - S85 engine	Backlash Gauge
	thru - 21 no value			
Information Systems	05 01 05 end	September-05	All	Teleservice Changing a Customer's Preferred Home Dealer
General	07 02 96	June-06	BMW Centers	CD42: Updated DISplus & GT1 Software (Supercedes June, Oct 05, Dec 05 & Mar 06)
General	07 03 02	June-04	BMW Centers	Optical Testing & Programming System - OPPS
General	07 05 02	June-05	BMW Centers	Online Update
General	07 02 04	November-04	BMW Centers	Optical Programming System - OPS
General	07 01 05	December-05	BMW Centers	Software Service Station r2 (SSSR2)
General	07 01 06	August-06	BMW Centers	Next Generation Workshop Technology – iBase Server Readiness Project
General	07 03 06	October-06	BMW Centers	Next Generation Workshop Technology 3G
General	07 04 06	January-07	BMW Centers	Use Agreement for 3G Workshop Technology
General	07 01 07	March-07	BMW Centers	DIS V49 Corrections Based on Diagnosis Feedback
General	B070107_Feedback PDF	March-07	BMW Centers	B070107Diagnosis_Feedback_Corrected_DIS_V49.
General	07 03 07	June-07	BMW Centers	DIS V50 Corrections Based on Diagnosis Feedback
General	B070307_Feedback PDF			
General	07 04 07	June-07	BMW Centers	DIS V51 Corrections Based on Diagnosis Feedback (September 2007 Release)
General	07 05 07	June-07	BMW Centers	DIS V50 Release Notes
<b>General</b>	<b>07 06 07</b>	<b>August-07</b>	<b>BMW Centers</b>	<b>Diagnosis Process</b>
<b>General</b>	<b>07 08 07</b>	<b>August-07</b>	<b>BMW Centers</b>	<b>DIS V51 Release Notes</b>
<b>General</b>	<b>07 10 07</b>	<b>October-07</b>	<b>BMW Centers</b>	<b>Importance of Using the Most Current Diagnostic / Programming Software</b>
	end			
Programming/Coding Explanations	09 03 98	May-06	E60/E63/E90	Car & Key Memory (Updated date with additional E90 info Supercedes Nov 05)
Programming/Coding Explanations	B090398_Att5_CKM_E0	P/O 09 03 98	E60/E63	PDF of car and Key memory settings
Programming/Coding Explanations	09 05 01	March-06	E60/E63	CIP General Info (Supercedes Dec 05)

Category	SIBs (SI B## ## ##)	Date	Application	Title
Programming/Coding Explanations	Att3_CBSCheck	P/O 09 05 01	E60/E63	Condition Based Service Plausibility Check
Programming/Coding Explanations	Att4_CBSCorrct	P/O 09 05 01	E60/E63	Condition Based Service Adjustments based on previous service
Programming/Coding Explanations	ProgCoding	P/O 09 05 01	E60/E63	Detailed Description of programming and coding using CIPs
Programming/Coding Explanations		09 07 02	E65	CIP 7.0
Programming/Coding Explanations		09 01 04	BMW Centers	Programming Manager
Programming/Coding Explanations		09 01 05	All	CIP 17.0 Release Notes
Programming/Coding Explanations		09 02 05	All	OBD Replacement Cables for GTI/DISplus Diagnostic Heads
Programming/Coding Explanations		09 03 05	E90	Personal Profile (Replaces 8/05)
Programming/Coding Explanations		09 04 05	All	CIP 18.0 release notes
Programming/Coding Explanations		09 05 05	E60 w/o NAV	After Programming, CIP shows MASK-H to be replaced
Programming/Coding Explanations		09 06 05	E60/E63	CIP Shows IHKA (Automatic heating & AC) to be Replaced
Programming/Coding Explanations		09 07 05	All	CIP 19.0 and 19.1 release notes
<b>Programming/Coding Explanations</b>	<b>09 08 05</b>	<b>October-05</b>	<b>E64 Cabrio</b>	<b>Service Action: Correction to Integration Level</b>
Programming/Coding Explanations	09 09 05	November-05	BMW Centers	CIP: Report Recurring Irregularities
Programming/Coding Explanations	09 11 05	October-06	E60/E63/E90	CCC Fails to Program with CIP 19.x (Supercedes Dec 05, Feb 06, May 06, Aug 06)
Programming/Coding Explanations	09 01 06	February-06	E90	JBE Fails to Program (supercedes Jan 06)
Programming/Coding Explanations	09 02 06	January-06	E90	Replacement FZD Not Accepted by CIP/PROGMAN
Programming/Coding Explanations	09 03 06	January-06	All	Deciphering and Troubleshooting the Vehicle Order
Programming/Coding Explanations	09 05 06	January-06	E60/E63/E90	Release Notes Progman V20.0 and V20.0.1
Programming/Coding Explanations	09 06 06	February-06	E90	RAD2 Cannot be Programmed after Programming Abort (Supercedes Jan 06 - Online 20.02.00)
Programming/Coding Explanations	09 07 06	January-06	E90/x drives	DSC Cannot be Encoded
Programming/Coding Explanations	09 08 06	February-06	E90	DWA LED on Rearview Mirror Cannot be Activated
Programming/Coding Explanations	09 09 06	March-06	All	Release Notes Progman 21.0
Programming/Coding Explanations	09 10 06	May-06	All	Release Notes Progman V21.02 and V21.02.01
Programming/Coding Explanations	09 11 06	May-06	E60	Replacement SZL Not Accepted by Progman
Programming/Coding Explanations	09 13 06	June-06	All	Release Notes Progman V22.0 and V22.0.1
Programming/Coding Explanations	09 14 06	July-06	E60/E63/E90	Maintenance Interval Retrofit is Not Used in US Market Vehicles
Programming/Coding Explanations	09 15 06	July-06	E90	Personal Profile Settings for Alarm System Missing
Programming/Coding Explanations	09 16 06	August-06	E60/E63/E90	Release Notes Progman V22.1 and V22.1.1 and V22.1.2
Programming/Coding Explanations	09 17 06	December-06	ALL	Vehicle Order (VO) Cannot be Adapted Using CIP
Programming/Coding Explanations	09 20 06	October-06	E90	Daytime Running Lamps Switched On after Update with Progman V23
Programming/Coding Explanations	09 21 06	October-06	E90	Satellite Radio Inoperable after Programming with Progman V23 - Need 23.01.03
Programming/Coding Explanations	09 22 06	October-06	E60/E63/E90	Coding Function for Headunit Available in Progman V23
Programming/Coding Explanations	09 01 07	January-07	E60/E63/E90	CCC: Programming or Coding Fails with Progman V24
Programming/Coding Explanations	09 02 07	May-07	All w/CCC	CCC: Enabling Code (FSC) Required for Voice Recognition System( Rpl March '07
Programming/Coding Explanations	B090207Attachment.	P/O 09 02 07	BMW Centers	B090207Parts_Info_V1_1
Programming/Coding Explanations	09 03 07	June-07	E92	FRM Fails Coding
<b>Programming/Coding Explanations</b>	<b>09 04 07</b>	<b>August-07</b>	<b>ALL w/CCC</b>	<b>Programming Failure Due to CD or DVD in Drives</b>
<b>Programming/Coding Explanations</b>	<b>09 05 07</b>	<b>September-07</b>	<b>E90</b>	<b>CAS2 Programming with Special Measure not Possible</b>
	end			
Engine System	11 08 98	June-06	All	BMW Engine Oils (Includes Annual Change Coverage) (Supercedes Oct 05)
Engine System	11 04 03	February-07	E60	Recurring Noise Complaints From Mechanical Alternator Belt Tensioners (Replaces 7/05)
Engine System	11 02 05	January-06	E60/E63	N62 - Rough Idle, Misfire faults after cold start (Supercedes May 05)
Engine System	11 03 05	June-05	E60/E63	N62 and N62TU Valve Cover and Valve Cover Gasket Replacement
Engine System	11 05 05	December-06	E60	N52 Engine Runs Poorly with Camshaft Sensor and VANOS Faults (Supercedes Novr 06)
Engine System	11 07 05	July-05	E60/E63	N62 and N62TU Water Pump Replacement - corrects installation procedure
Engine System	11 09 05	April-06	E60/E63	Non-Return Valve Parts Found In Engine Oil Filter During Engine Oil Service Supercedes Dec 05)
Engine System	11 10 05	February-06	E60 (M5)	Service Action: S85 Replace VANOS High Pressure Line (Supercedes Jan 06 )
Engine System	11 01 06	March-06	M5/M6	S85 Engine Oil Level and Oil Service Information
Engine System	11 02 06	December-06	E60	NG6 Engines - Front and Rear Radial Crankshaft Seal Replacement
<b>Engine System</b>	<b>11 03 06</b>	<b>June-06</b>	<b>All w/N62 Engine</b>	<b>Voluntary Emissions Recall 06E-A02: N62 - Crankcase Ventilation Valves Replacement</b>
Engine System	11 04 06	June-06	All	Engine, Transmission, or Clutch Related Complaints
Engine System	11 06 06	June-06	M54/M54TU	Head Bolt Threads Pulling Out of Block During Engine Reassembly
Engine System	11 07 06	October-06	All w/N62 Engine	N62 Engine - Rough Idle at Operating Temperature
Engine System	11 13 06	November-06	E90/E92 w N54	N54 Engine Compression and Cylinder Leakage Test Procedures
<b>Engine System</b>	<b>11 01 07</b>	<b>June-07</b>	<b>All with N62 (4.4)</b>	<b>N62 Crankcase Ventilation System – Cold Climate Conditions (rpl 4/07)</b>
<b>Engine System</b>	<b>11 05 07</b>	<b>April-07</b>	<b>All S85 (V10)</b>	<b>Service Action: Replace Front Crankshaft Radial Seal</b>
Engine System	11 09 07	July-07	All N52 Engine	Intermittent Hydraulic Valve Adjuster (HVA) "Ticking" or "Rattling" Noises
<b>Engine System</b>	<b>11 12 07</b>	<b>October-07</b>	<b>N62/N62TU</b>	<b>N62 and N62TU Engine Replacement (after an engine has been replaced)</b>
	<b>06 - Alpina B7</b>			
Engine Electrical System	12 01 99	June-06	All	High Performance Platinum Spark Plug/Spark Plug Application Chart
Engine Electrical System	12 01 04	October-04	N62 in E60	E60 with N62: DME Reprogramming
<b>Engine Electrical System</b>	<b>12 03 04</b>	<b>September-04</b>	<b>M54 in E60</b>	<b>Voluntary Emissions Recall Campaign 04E-A02: Emission Readiness Codes Not Completely S</b>
<b>Engine Electrical System</b>	<b>12 04 04</b>	<b>July-04</b>	<b>E60/E63</b>	<b>Safety Recall Campaign 04V-344: DME Replacement on N62/N73 Engines</b>
<b>Engine Electrical System</b>	<b>12 05 04</b>	<b>October-05</b>	<b>E60/E63</b>	<b>Voluntary Emissions Recall 04E-A04: Reprogram DME for Oxygen Sensor Diagnostics on E53,</b>
Engine Electrical System	12 09 04	August-06	All	Special DME Programming - Shipping Procedure (Replaces 12/04)
Engine Electrical System	12 10 04	December-04	M54 in E60	Intermittent Hesitation While Driving or Intermittent Crank, No Start Situation

Category	SIBs (SI B## ## ##)	Date	Application	Title
Engine Electrical System	12 01 05	June-06	N52 in E60	High Perf Iridium spark Plugs (Supercedes May 05)
Engine Electrical System	12 03 05	September-05	N62 in E60/E63	CBS Oil Message
Engine Electrical System	12 04 05	July-07	N52 in E60	Check Engine light or engine overheats (Supercedes Mar 06)
Engine Electrical System	12 06 05	June-05	N52 in E60	DME FC CDA7 CAN Message
Engine Electrical System	12 08 05	July-05	E60	Oxygen Sensor
Engine Electrical System	12 11 05	January-06	N62 in E60/E63	Service Action: Reprogramming for Incorrect Oil Service (Supercedes August 05)
Engine Electrical System	12 15 05	November-05	N62 in E60/E63	Map Thermostat faults (Supercedes Sept 05 with new info)
Engine Electrical System	12 16 05	September-05	E60	Mixture is too Lean, Fault codes 2882, 2883
Engine Electrical System	12 17 05	September-05	E60	Engine Power drops at 4000 RPM
Engine Electrical System	12 19 05	October-05	N52 in E60/E90	Service Action: Reprogram for OBD Diagnostic
Engine Electrical System	12 20 05	October-05	E60/E63	Loss of Power while decelerating & turning or coming to stop
Engine Electrical System	12 25 05	December-05	E90	CBS Oil formula (different but similar to E60/63)
Engine Electrical System	12 27 05	April-07	E60/E63	N62TU (4.8L) Pinging and Surging (Supercedes Jul 06)
Engine Electrical System	12 29 05	March-06	M5	S85 Engine Diagnosis Test Plan Updates (Supercedes Dec 05 - minor change)
Engine Electrical System	12 03 06	February-06	E60/M52	Loss of Power or Intermittent Crank, No Start Situation
Engine Electrical System	12 04 06	February-06	E60/M52	DMTL Diagnosis Test Plan Error
Engine Electrical System	12 06 06	April-07	E60/E90/N52	Voluntary Emissions Recall 06E-A01: N52 - Reprogramming Vehicle for OBD Diagnostic (Super
Engine Electrical System	12 07 06	January-07	E60/E90/N52	Service Engine Soon Light Illuminated: FC 2EF4 Map Thermostat (Replaces 5/06)
Engine Electrical System	12 10 06	September-06	E60/E90/N52	Service Engine Soon Lamp Illuminated: FC 2C2D, 2C3D, 2C2E, 2C3E
Engine Electrical System	12 12 06	April-07	E60/E63/N62TU	N62TU - Diagnosis for DME FC 2A90 (Supercedes Dec 06)
Engine Electrical System	12 16 06	September-06	E90/E92 w N54	E90, E92 with N54 - Diagnostic for DME FC 29F1/29F2
Engine Electrical System	12 18 06	November-06	Ms	Voluntary Emissions Recall 06E-A04: S85 - DME Reprogramming for OBD Monitoring
Engine Electrical System	12 19 06	October-06	E60/E63/E90	Check Gas Cap Warning with DME FC 2A17 – DMTL, System Error
Engine Electrical System	12 25 06	November-06	All	Fuel Quality Determination (Supercedes August 06)
Engine Electrical System	12 27 06	November-06	E60/N62	DME Fault Codes 278B and 278D
Engine Electrical System	12 28 06	October-06	E60	DME Fault Code 27CD
Engine Electrical System	12 29 06	November-06	E60/M54	DME Fault Codes 2896, 2877, 2766
Engine Electrical System	12 33 06	October-06	E60/E63	Various Complaints Caused by Defective Oil Level Sensor - Diagnostic Hints
Engine Electrical System	12 34 06	October-06	E60/M54	E60, M54 - Various Oxygen Sensor FC's Caused by Defective Transmission Harness
Engine Electrical System	12 38 06	October-06	E90	MSV70 - DME, FC 29DA Segment Adaptation
Engine Electrical System	12 40 06	October-06	E60	MS45.1 – Various O2 Sensor Faults Stored in DME
Engine Electrical System	12 42 06	November-06	E60	E60, MS45.1 – DME FC 28A2 and FC 2783
Engine Electrical System	12 43 06	October-06	E60/E63	N62 DME ME9.2.1 Engine Difficult to Restart at Operating Temperatures
Engine Electrical System	12 46 06	November-06	E90/E92 w N54	N54 – Slight Bucking is Felt During Acceleration With a Cold Engine
Engine Electrical System	12 47 06	November-06	E60/E63	Break Out Box Overlay Identification
Engine Electrical System	12 49 06	April-07	E60/M54	DME MS45 - FC28B2, 28AA, 28AC; Internal RAM Faults (Rpl 11/06)
Engine Electrical System	12 50 06	November-06	E60/E63/E90	OBD II Fault Codes List in TIS
Engine Electrical System	12 51 06	December-06	E92	MSD80 N54 Engine Diagnostic Test Plans Inoperative
Engine Electrical System	12 54 06	December-06	E90/92	N54 CBS4 Oil Service Indicates 25,000 Miles
Engine Electrical System	12 55 06	January-07	E90/92	E90, E92 with N54 - Diagnostic for DME FC 29DC/2FBF (Replaces 12/06)
Engine Electrical System	12 58 06	January-07	E90	Service Action: Replace the Alternator
Engine Electrical System	12 05 07	February-07	E60/E90	Erroneous Low Oil Level Warning Message While Driving
Engine Electrical System	12 06 07	September-07	E90/E92	Voluntary Emissions Recall 06E-A01: N52/M54/M56 - Reprogramming Vehicle (DME) for OBD Di
Engine Electrical System	12 09 07	May-07	M5/M6	Service Engine Soon Light Illuminated: S85 - Various VANOS Related Faults Stored
Engine Electrical System	12 10 07	July-07	E60/E63/N62TU	Service Action: N62TU - Retrofit Engine Compartment Ground Cables
Engine Electrical System	12 11 07	July-07	E60/E63/N62TU	N62TU: EDK Throttle Faults - Diagnostic
Engine Electrical System	12 15 07	October-07	3 Series	N52K - Loss of Power
<b>Fuel Systems</b>	<b>13 01 04</b>	<b>July-04</b>	<b>E60/E63 (V8)</b>	<b>Recall Campaign 04V- 303: Retaining Clip Retrofit for the Fuel Line Quick Release Coupling</b>
Fuel Systems	B130104Q&A	P/O 13 01 04	E60/E63 (V8)	Q&A
Fuel Systems	13 01 06	September-06	All	Alcohol Fuel Blends in BMW Vehicles (replaces March 06)
Fuel Systems	13 02 06	September-06	All	TOP TIER Detergent Gasoline in BMW Vehicles (Replaces 03/06)
Fuel Systems	13 03 06	May-06	All	Fuel Pump Failure after Refueling with Ethanol Fuel Blend
Fuel Systems	13 04 06	August-06	All	Alcohol Detection Procedure
Fuel Systems	13 05 06	September-06	All	BMW Group Fuel System Cleaner Plus (Supercedes Aug 06)
Fuel Systems	13 06 06	November-06	E90/E92	High Precision Injection (HPI) Information and Service Procedures
Fuel Systems	13 07 06	November-06	ALL	Gasoline Quality & Detergent Additives - Customer Information Brochure
Fuel Systems	13 01 07	April-07	ALL/ex turbo	Fuel Injection and Induction System Cleaning
Fuel Supply	16 02 05	March-05	E60/E63	Fuel Tank Difficult to Refuel
Fuel Supply	16 01 06	September-06	E90	Fuel Level Sensor Repair Procedure w/N54
Fuel Supply	16 03 06	October-06	E90	Vehicle is Difficult to Refuel
Fuel Supply	16 06 06	October-06	E60	Humming/Buzzing Noise from Center Dash Area When Accelerator is Depressed
Fuel Supply	16 08 06	February-07	E90	N51 PZEV - Erroneous Fuel Gauge Reading (Replaces 12/06)
Fuel Supply	16 01 07	August-07	All	Testing Evaporative Systems for Leaks

- 02 other models

Cooling Systems	17 01 07	October-07	ALL	BMW Long-Term Antifreeze/Coolant: Maintenance, Repairs and Replacement Requirements
-----------------	----------	------------	-----	---

Category	SIBs (SI B## ## ##)	Date	Application	Title
Clutch	21 02 06 <b>07 for Z4</b>	October-06	E60 (M5) Z4	S85 - SMG Transmission Faults 4FA0, 4F80 and Clutch is Damaged
<b>Drive Shaft</b>	<b>26 01 06</b>	<b>June-07</b>	<b>E65/E66</b>	<b>Noise from Driveshaft Area (Rpl 06/06)</b>
Manual Transmission	23 01 05	November-05	E60/M5	E60 M5 - CAN Communication Fault FFFF
Manual Transmission	23 01 06	February-06	M Cars	SMG III: Fault Code 5101 Analyze Hydraulic Sensor (Supercedes Jan 06)
Manual Transmission	23 02 06	January-06	SMG Tranny	Towing Vehicles with SMG Transmissions
Manual Transmission	23 03 06	April-07	M Cars	Getrag SMG Transmission Repair & Replacement Information (SMG II and III) (Rpl 02/06)
Manual Transmission	23 04 06	April-06	E60/E63	ZF SMG FC 4F6F - Hydraulic Pump Failure (Supercedes Mar 06)
Manual Transmission	23 07 06	February-07	M Cars	M5, M6 with SMG III; FC 4F42/4F43 - Hydraulic Unit Faults (Replaces 12/06)
Manual Transmission	23 08 06	January-07	All SMG Cars	SMG - Service Functions Performed after Drivetrain Repairs
Manual Transmission	23 09 06	January-07	All non M SMG	ZF SMG - Replacement Parts Availability
<b>Manual Transmission</b>	<b>23 01 07</b>	<b>August-07</b>	<b>S85 M5</b>	<b>Service Action: Replace SMG Hydraulic Unit Electric Motor on M5 Vehicles (rpl 7/07)</b>
	- 06 other model			
Automatic Transmission	24 08 03	November-04	E60	EGS Fault 4F6A
<b>Automatic Transmission</b>	<b>24 02 05</b>	<b>April-06</b>	<b>E60</b>	<b>Service Action: Replace Mechatronic Adapter (Supercedes May 05</b>
Automatic Transmission	24 03 05	February-07	E60/E63	Harsh 2-1 Downshift (Replaces 6/05)
<b>Automatic Transmission</b>	<b>24 06 05</b>	<b>November-05</b>	<b>E60/E63</b>	<b>Safety Recall Campaign 05V-504: Parking Lock Guide Plate</b>
Automatic Transmission	B240605CustomerLetter	P/O 24 06 05	E60/E63	Recall Letter
Automatic Transmission	B240605Q&A.	P/O 24 06 05	E60/E63	Q&A
Automatic Transmission	24 06 06	October-06	E90	A Slight Bump is Felt Shortly after the Vehicle Comes to a Stop (Supercedes Aug 06)
Automatic Transmission	24 11 06	October-06	E92	E92; N54 with 6HP16 - Diagnosis for EGS FC 511B
Automatic Transmission	24 04 07	April-07	E90/E91/E92	ZF 6HP19TU in Failsafe Mode with Fault 4F8D Stored
Automatic Transmission	24 09 07	April-07	E90/E91/E92	The Service Engine Soon Light is on and EGS Fault CF1C Stored
Automatic Transmission	24 10 07	April-07	E60/3 Series	The Transmission is in "Failsafe" mode with EGS Fault CF33 Stored
Automatic Transmission	24 11 07	April-07	3 Series	GM6 - 6L46R Transmission Adaptations and Terminology (info only)
Automatic Transmission	24 13 07	June-07	All STEP Equipped	Various Complaints Due to Poor Connection at Transmission Connector
<b>Automatic Transmission</b>	<b>24 19 07</b>	<b>September-07</b>	<b>E60</b>	<b>Drive Position "D" Cannot be Engaged</b>
<b>Automatic Transmission</b>	<b>24 21 07</b>	<b>October-07</b>	<b>3 Series</b>	<b>Diagnosis - DME Fault CDB4: No Message (transmission data 3, 3B1)</b>
<b>Gear Shift Mechanism</b>	<b>25 01 07</b>	<b>January-07</b>	<b>E90</b>	<b>Service Action: Gear Shift Knob Replacement</b>
	14 - 18 other models			
Front Axle	31 02 04	August-04	All	Rattling Noise From Front or Rear Axle
<b>Front Axle</b>	<b>31 02 06</b>	<b>June-06</b>	<b>E60/E63</b>	<b>Recall Campaign 06V-187 : Front Axle Control Arm and Tension Strut Fasteners</b>
<b>Front Axle</b>	<b>31 03 06</b>	<b>November-06</b>	<b>E90</b>	<b>Recall Campaign 06V-400: Check Tightening Torque of Front Axle Control Arms and Tie Rods</b>
	no 07 yet			
Steering and Wheel Alignment	32 01 05	July-05	E60	Power Steering Assist Enhancement
Steering and Wheel Alignment	32 04 05	June-05	E60	Steering Column Comfort Exit Feature
Steering and Wheel Alignment	32 07 05	September-05	E60/E63	Active Front Steering, Noise Fault Code 613E
Steering and Wheel Alignment	32 13 05	October-05	E60/E63	Active Front Steering, Fault Code 6141
Steering and Wheel Alignment	32 14 05	October-05	E60/E63	Active Front Steering Sensitivity
<b>Steering and Wheel Alignment</b>	<b>32 01 06</b>	<b>February-06</b>	<b>E90</b>	<b>Service Action: Install Clip for Power Steering Line</b>
Steering and Wheel Alignment	32 04 06	February-06	E60/E63	AFS Programming
Steering and Wheel Alignment	32 05 06	March-06	E90	Steering Wheel Offset
Steering and Wheel Alignment	32 06 06	March-06	E60/E63	Steering Angle Sensor Adjustment
Steering and Wheel Alignment	32 07 06	April-06	E90/91	Steering Column Clicking Noise
Steering and Wheel Alignment	32 04 07	July-07	ALL	TeileClearing ( Enhanced Technical Support) for Steering Systems
Rear Axle	33 01 06	April-06	E60 (M5)	Grating Noise from Differential During Slow Cornering
<b>Rear Axle</b>	<b>33 02 06</b>	<b>September-06</b>	<b>E60/E63/E65</b>	<b>Recall Campaign 06V-277: Inspect Rear Shock Absorbers (Supercedes Aug 06)</b>
<b>Rear Axle</b>	<b>33 01 07</b>	<b>October-07</b>	<b>E60 - M5</b>	<b>E60 M5 Howling Noise from Rear Axle Area</b>
	no 07 yet			
Brakes	34 06 05	July-05	E90	DSC MK60E5 Fault Codes: 5DB6, 5DC6, 5E30, 5D8F
Brakes	34 02 06	March-06	E60/E63	Brake Squeals
<b>Brakes</b>	<b>34 04 06</b>	<b>April-07</b>	<b>E60/E63/E90</b>	<b>DSC Warning - Various SZL FCs Stored (Supercedes Jun 06)-Changed to e90 only??</b>
<b>Brakes</b>	<b>34 05 06</b>	<b>September-06</b>	<b>E60/E63</b>	<b>Service Action: Replace SZL Optical Element (Made Svc Action)</b>
	01-03 07 - for X5			

<u>Category</u>	<u>SIBs (SI B## ## ##)</u>	<u>Date</u>	<u>Application</u>	<u>Title</u>
Wheels and Tires	36 01 04	August-05	BMW Center	Hunter GSP97BMW Wheel Balancer - Features and Operator Training
Wheels and Tires	36 02 05	July-05	E60	Noise and/or Vibration Caused by Irregular Tire Wear
Wheels and Tires	36 04 05	October-05	E60	Erroneous Flat Tire Monitor Warning
Wheels and Tires	36 05 05	June-05	All	Tire Pressure Monitoring Systems (TPMS)
Wheels and Tires	36 06 05	May-05	E60	Wheels - Different between X models and regular models
Wheels and Tires	36 04 06	April-06	E60	Nitrogen Inflated Tires
Wheels and Tires	36 02 07	September-07	3 Series	Service Action: Reprogram the Control Module for the Tire Pressure Monitoring System (RDC)
Wheels and Tires	36 02 07	September-07	All	Flat Tire Monitor System (FTM) Diagnosis
	no 07 yet			
Suspension	37 02 05	August-05	E60/E63	Anti-Roll Stabilization Noise
Suspension	37 01 06	March-06	E61	Chafed Ride Height Sensor Cable
	no 07 yet			
Body	41 01 05	May-05	E60/E63	Structural Aluminum Repair Precautions
Body	41 05 06	February-06	E60/E63	Trunk Lid Opens Too Fast/Slow
	Z4			
<b>Body Equipment</b>	<b>51 13 04</b>	<b>August-07</b>	<b>E60/E63</b>	<b>Rattling Noise from Center Display (Replaces 06/07)</b>
Body Equipment	51 02 05	February-07	E60	Squeaking Noise from Door Frame area While Driving (Replaces 12/06)
Body Equipment	51 04 05	June-05	E60/E61 (xi, xiT)	Incorrect or Missing Floor Mats (deliveries before May 16, 05)
Body Equipment	51 08 05	July-05	E60/E63	Door Mirror Glass Discolored after Programming
Body Equipment	51 17 05	July-05	E60	Replacement Windshield - VIN Window in Wrong Position
Body Equipment	51 30 05	October-05	E90	Cracking or Ticking Noise from Lower B-Pillar
Body Equipment	51 31 05	March-06	E90	Center Console Heats Up In Knee Contact Area (Supercedes Nov 05)
Body Equipment	51 32 05	October-05	E90	Clicking Noise from Upper B-pillar Trim
Body Equipment	51 33 05	October-05	E90	Water Ingress from A/C Blower Housing
Body Equipment	51 37 05	December-05	E90	The cup holder jams when retracted
Body Equipment	51 10 06	May-07	E60	Anti-trap is Activated when Raising the Front Window (rpl 2/06)
Body Equipment	51 14 06	August-06	E90	Outside Door Handles Hanging up in the Pulled Position
Body Equipment	51 18 06	May-07	E9x series	Interior Door Grab Handle Finish Peeling (rpl 8/06)
Body Equipment	51 24 06	November-06	E61	Luggage Compartment Roller Cover Malfunction
Body Equipment	51 27 06	January-07	E92	Rattle Noise from B-Pillar Trim
<b>Body Equipment</b>	<b>51 06 07</b>	<b>March-07</b>	<b>E60 - M5</b>	<b>Service Action: Replace Underbody Panel</b>
Body Equipment	51 08 07	March-07	E90/E91/E92	Erroneous Trunk Lid Open Check Control Message
Body Equipment	51 10 07	April-07	E90/E92/E93	Rear Window will not Fully Defrost
<b>Body Equipment</b>	<b>51 12 07</b>	<b>May-07</b>	<b>E93</b>	<b>Service Action: Install Luggage Compartment Labels</b>
Body Equipment	51 14 07	June-07	E93	Center Console Lock Inoperative
Body Equipment	51 16 07	July-07	E93	Rear Roundel Emblem Comes Loose
Body Equipment	51 17 07	July-07	E93	Rear Window(s) Inoperative
<b>Body Equipment</b>	<b>51 19 07</b>	<b>September-07</b>	<b>E90</b>	<b>Doors will not Unlock Using the Key Fob or Central Locking Button</b>
<b>Body Equipment</b>	<b>51 22 07</b>	<b>September-07</b>	<b>E91</b>	<b>Creaking Noise from the C-Pillar Area</b>
	end			
<b>Seats</b>	<b>52 02 04</b>	<b>April-05</b>	<b>E60/E63</b>	<b>Recall Campaign 04V-575: Modification of the Front Seat Heater Circuit</b>
<b>Seats</b>	<b>52 05 04</b>	<b>August-07</b>	<b>E93</b>	<b>Lumbar Support Inoperative</b>
	01, 02, 04-07 all X5			
Special Roofs	54 03 05	July-05	E64 (Cabrio)	Convertible Top will not Lower
Special Roofs	54 13 06	May-06	E60	SHD Coding Error - Progman V21.1
Special Roofs	54 17 06	November-06	E64 (Cabrio)	Convertible Top Does Not Completely Open or Close
Special Roofs	54 01 07	July-07	E93	Service Action: Replace Roof Shell Trim Strips (rpl 4/07)
Special Roofs	54 02 07	April-07	E93	RHT Opens but Trunk Lid will not Close
Special Roofs	54 03 07	April-07	E93	Convenience Open/Close Function
Special Roofs	54 06 07	July-07	E93	Roof Shell 1 Slams Down on the Cowl when Closing the RHT (rpl 5/07)
Special Roofs	54 08 07	May-07	E93	RHT Statuses Reversed in DIS/GT1
Special Roofs	54 09 07	June-07	E93	RHT Status Request Supplement
Special Roofs	54 10 07	August-07	E93	RHT Stops Opening in the Stacked/Extended Position
<b>Special Roofs</b>	<b>54 11 07</b>	<b>September-07</b>	<b>E93</b>	<b>Headliner is Loose in the C-pillar Area</b>
<b>Special Roofs</b>	<b>54 12 07</b>	<b>September-07</b>	<b>E93</b>	<b>Rattle from the Front Latch of the RHT</b>
	end			
General Electrical Systems	61 07 88	December-06	All	Battery Maintenance Requirements (Replaces 10/06)
General Electrical Systems	61 08 00	June-07	All	Closed-Circuit Current Measurement (Replaces 1/07 - new cars)
General Electrical Systems	61 15 02	February-06	E60/E63	MOST Bus Diagnosis (Supercedes July 04 with new diagnostics & models)
General Electrical Systems	B611502F_Description.	P/O 61 15 02	E60/E63	MOST Bus Diagnosis Description
General Electrical Systems	B611502ChartsA&B.	P/O 61 15 02	E60/E63	MOST Bus Diagnosis Troubleshooting Chart

Category	SIBs (SI B## ## ##)	Date	Application	Title
General Electrical Systems	61 03 03	January-06	E60/E63	CAN/Bytflight Bus Diagnostics (Supercedes June 05 - Adds E61 & E91)
General Electrical Systems	61 13 02	December-05	E65	CIP 16.0 - 2002 MY Electrical complaints (Supercedes April 05 w/new info)
General Electrical Systems	61 14 03	September-07	E60/E63	CIP Updates (CIP 27.00.00) - (Supercedes Apr 07 - 25.01.00)
General Electrical Systems	61 01 04	June-05	E65	CIP 17.01 - MY02-05 various complaints
General Electrical Systems	61 01 04	September-06	E65	Various Complaints Caused by Software Errors (21.02.01) (Supercedes Mar 06 / CIP 20.00)
General Electrical Systems	61 01 05	December-05	E60/E63	Special Survey for CAS related problems (Supercedes Apr 05 - Survey completed)
General Electrical Systems	61 03 05	September-07	E90	CIP 27.00.00 - Software errors corrected with PROGMAN (Rpl 25.01.00 4/07)
General Electrical Systems	61 06 05	September-05	E60	High Drain Battery Message in CIP (N52 Engine)
General Electrical Systems	61 07 05	January-06	E60/E63	PDC Light Flashing after SZM Replacement (Supercedes info in August 05)
General Electrical Systems	61 08 05	August-05	E90	Roof Functions Center Causes Various System Malfunctions
General Electrical Systems	61 09 05	August-05	E90	Remote Key Sticks In/Falls Out of CAS Holder
General Electrical Systems	61 10 05	August-05	E90	Various Electrical Problems
General Electrical Systems	61 11 05	October-05	E60	Battery Safety Terminal
General Electrical Systems	61 12 05	November-05	E60/E63	Dead Battery by MPM
General Electrical Systems	61 13 05	June-07	E60/E63	Dead Battery - Perform Energy Diagnosis (rpl 12/05)
General Electrical Systems	61 01 06	February-06	E90	Trunk Opens without Request
General Electrical Systems	61 02 06	February-06	E60/E63/E90	Key Falls Out of, or Gets Stuck in Key Holder (Supercedes 2/06 adding models)
General Electrical Systems	61 04 06	February-06	ALL	Exiting a Vehicle that is Double-Locked from the Outside
General Electrical Systems	61 06 06	May-06	E90	Junction Box Pin Assignment Change
General Electrical Systems	61 07 06	August-06	E60/E63/E90	No Crank, No Start, CAS FC A111
General Electrical Systems	61 10 06	October-06	E63	Windows Convenience Open When Door is Opened
General Electrical Systems	61 13 06	October-06	E60	Various Electrical Problems Caused by Water Ingress
General Electrical Systems	61 14 06	October-06	E60/E63	One-Touch Close Inoperative after Door Module Replacement
General Electrical Systems	61 15 06	October-06	E64	Rear Windows Close First, or Anti-trap Activates During Convenience Closing
General Electrical Systems	61 20 06	October-06	E60	Rear Windows Move in Small Increments
General Electrical Systems	61 22 06	October-06	E60	iDrive Controller Malfunction (Low Version)
General Electrical Systems	61 23 06	October-06	E60	Battery Charger Causes Faults to be Set
General Electrical Systems	61 24 06	October-06	E60	Starts only once following EWS calibration
General Electrical Systems	61 26 06	September-06	E90	Central Electronics Failure, K-CAN bus Fault Codes Stored
General Electrical Systems	61 27 06	October-06	E92	Replacement CAS3 - Calibration Error Message
General Electrical Systems	61 28 06	May-07	E92	Red ELV Warning in Instrument Cluster (Replaces 1/07)
General Electrical Systems	61 29 06	November-06	E60/E63/E90	CAS / ELV Diagnostics
General Electrical Systems	61 31 06	May-07	X5	Software Errors Corrected with Progman (Rpl Apr/07) PROGMAN 25.01.00
General Electrical Systems	61 32 06	December-06	E90/91/92	Sunroof Moves in Small Steps or Interior Lights not Working
General Electrical Systems	61 33 06	December-06	E60/E63/E90	Battery Warning Displayed when Deleting Transport Mode
General Electrical Systems	61 34 06	December-06	E90/91/92	Engine Fails to Start after CAS Replacement
General Electrical Systems	61 04 07	May-07	E60/E63	SZL Functions Lock Up after Deleting Transport Mode
General Electrical Systems	61 08 07	August-07	E60/E63	Electric Steering Lock Inoperative
General Electrical Systems	61 09 07	August-07	E60/E65/E90	OBD Socket Housing Cover Missing

end

Instruments	62 01 06	May-07	E60/E63	Instrument Cluster Needles Vibrate (Replaces 1/07)
Instruments	62 02 06	May-06	E60/E63	Engine Oil Level Menu Option is Displayed After Reprogramming
Instruments	62 04 06	October-06	E60/E63	Instrument Cluster: Failure of Displays/Functions
Instruments	62 01 07	January-07	E90/92	Warning Chime Inoperative for Check Control and/or Directionals
Instruments	62 02 07	January-07	E60/E63/E92	No Communication or Diagnosis Possible With Instrument Cluster
Instruments	62 03 07	May-07	E90/92	On-Board Computer Functions Cannot Be Displayed (rpl 1/07)
Instruments	62 06 07	March-07	BMW Centers	Check Control Messages (With PDF list)

04 07 note to dealer  
05 - 09 other models

Lights	63 02 04	July-04	E60	Replace Lamp Module
Lights	63 02 05	June-05	E60	Brake Force Display (BFD) Inoperative
Lights	63 03 05	July-05	E60	Eyebrow Lights are Inoperative after Programming
Lights	63 05 05	September-05	E64 Cabrio	Third Brake Light Cracked
Lights	63 06 05	November-05	E60	<b>Service Action: Check the Adaptive Headlights for Proper Operation</b>
Lights	63 01 06	May-06	Z4	Front Lighting Configuration
Lights	63 05 06	October-06	E60/E63	Automatic Headlamps: Lights Do Not Switch Off
Lights	63 06 06	October-06	E60	LED Flashing On Headlight Switch, No Faults Stored
Lights	63 08 06	October-06	E60	Lights Flash Briefly When Vehicle Wakes Up; Battery May Become Discharged
Lights	63 09 06	October-06	E60	Brake Lighting Pulsates Intermittently
Lights	63 12 06	October-06	E63	Adaptive Headlamp Does Not Turn
Lights	63 13 06	October-06	E60/E63	Automatic Headlamp System Does Not Switch Off the Lights
Lights	63 15 06	October-06	E60	Headlamp Leak (Replaces 12/04)
Lights	63 16 06	November-06	E60	3rd Brake Light Comes Loose From Rear Window
Lights	63 17 06	January-07	E60/63/90	Eyebrow Lights are Inoperative after Programming (Replaces 12/06)
Lights	63 02 07	January-07	E90/91/92	Bulb Out Symbol Displayed in BC
Lights	63 03 07	February-07	E90/91/92	Daytime Running Lights are Inoperative

Category	SIBs (SI B## ## ##)	Date	Application	Title
Lights	63 04 07	March-07	E60/E63	Fault Code 9CAD in LM
Lights	63 06 07	April-07	E92/93	Cornering lights failure Displayed in Check Control
Lights	63 13 07	August-07	E90/91/92	Headlight Vibrations
	08 09 for X5			
Heating and Air Conditioning	64 08 91	October-06	All	Musty Odors
Heating and Air Conditioning	64 02 05	August-05	E64 (Cabrio)	Poor Temperature Regulation from Center Vents
Heating and Air Conditioning	64 03 05	April-07	E60/E63	Air Conditioning Delayed Startup (Supercedes Jan 06 w/new info)
Heating and Air Conditioning	64 04 05	August-07	E60/E63	Air Conditioning Stops Cooling after Long Drive (Replaces 12/06)
Heating and Air Conditioning	64 21 05	July-06	All	Troubleshooting Air Conditioning Compressor Noise (Supercedes Dec 06)
Heating and Air Conditioning	64 01 06	January-06	E60	Blower Motor Stays On with Key Off
Heating and Air Conditioning	64 02 06	June-06	E60	Water Droplets are Blown from Center Vents with A/C On (Supercedes Jan 06)
Heating and Air Conditioning	64 04 06	May-07	E90	Air Conditioning Does not Cool (Replaces 1/07)
Heating and Air Conditioning	64 06 06	May-06	E90	Front Defroster Performance Poor at Mid-Blower Speeds
Heating and Air Conditioning	64 07 06	May-07	E90	Air Conditioning System does not Cool (Refrigerant Charge Good) (rpl 6/06)
Heating and Air Conditioning	64 09 06	October-06	E90	Air Conditioning System Blows Warm Air After Long Drive (Replaces 8/06)
Heating and Air Conditioning	64 10 06	July-06	E60/61	Water Droplets Blown from Right Side Center Vents with A/C On
Heating and Air Conditioning	64 14 06	October-06	E60/61	A/C Compressor Noise "Droning, Howling or Ticking" at Low Engine Speed
Heating and Air Conditioning	64 03 07	March-07	E92	Banging Noise from Air Conditioner Compressor
Heating and Air Conditioning	64 04 07	April-07	3 Series	Heating and Air Conditioning Symptom Diagnosis
Heating and Air Conditioning	64 06 07	June-07	E60/E63	Air Conditioning Compressor Does Not Switch On
Heating and Air Conditioning	64 08 07	August-07	All	Important Information about Heating and Air Conditioning
Heating and Air Conditioning	64 10 07	August-07	E60/E63	Air Conditioning Delayed Startup
Heating and Air Conditioning	64 12 07	September-07	3 Series	White Flakes/Powder Coming from the Air Conditioning Vents
	07 09 for (X5)			
Sounds System, Cruise, Alarms, Monitors	65 06 04	July-04	E60/E63	Consumption Set to mpg UK instead of mpg US
Sounds System, Cruise, Alarms, Monitors	65 10 04	January-05	E60/E63	Audio Stays On
Sounds System, Cruise, Alarms, Monitors	65 01 05	June-05	E90	Radio Seek/Scan Inoperative
Sounds System, Cruise, Alarms, Monitors	65 02 05	April-06	E60/E63/E90	SIRIUS Satellite Radio - General Info (Supercedes May 05 - Added E90)
Sounds System, Cruise, Alarms, Monitors	65 06 05	July-05	E60/E63	CID Fault Analysis Guide
Sounds System, Cruise, Alarms, Monitors	65 07 05	April-06	E90	MOST Bus is Inoperative or Central Information Display has Reduced Brightness (Jul 05)
Sounds System, Cruise, Alarms, Monitors	65 08 05	October-05	E90	Temperature Display in RAD2 Shows Dashes
Sounds System, Cruise, Alarms, Monitors	65 09 05	February-06	E60/E63/E90	No Audio Sound in any Mode (Supercedes Aug 05 with new info)
Sounds System, Cruise, Alarms, Monitors	65 10 05	August-06	E60/E63/E90	CCC: Loss of all Audio (Supercedes Aug 05 - add E90)
Sounds System, Cruise, Alarms, Monitors	65 16 05	September-05	E60/E63/E90	RDS Function Causes Confusing Station Names when in "All stations" Screen
Sounds System, Cruise, Alarms, Monitors	65 18 05	January-06	E60/E63/E90	MP3 Compatibility Overview (Supercedes October 2006)
Sounds System, Cruise, Alarms, Monitors	B651805MP3_Compatibility_Chart	P/O 65 18 05	E60/E63/E90	MP3 Compatibility Chart
Sounds System, Cruise, Alarms, Monitors	65 19 05	October-05	E60	Weather Band Available on Multi Audio System Controller
Sounds System, Cruise, Alarms, Monitors	65 20 05	January-06	E90	RAD2 - CD Mode Malfunctions (In-Dash CD skips or does not play - Business Radio)
Sounds System, Cruise, Alarms, Monitors	65 21 05	March-07	E63/E64	SIRIUS Satellite Radio Cuts Out in Certain Geographic Areas (May 06 -)
Sounds System, Cruise, Alarms, Monitors	65 22 05	November-05	E60	'Favorites' Function is Selectable in the Entertainment Menu
Sounds System, Cruise, Alarms, Monitors	65 23 05	November-05	E60	Disclaimer Screen Disappears Automatically after 10 Seconds
Sounds System, Cruise, Alarms, Monitors	65 24 05	October-05	E60/E63/E90	Static Between Words on AM Radio
Sounds System, Cruise, Alarms, Monitors	65 25 05	August-07	E60/E63	HD-Radio™. Functionality and Diagnosis (Supercedes Mar 07)
Sounds System, Cruise, Alarms, Monitors	65 26 05	March-06	E60/E63/E90	Audio Switches off Briefly when Listening to FM Stations (Supercedes Jan 06 w/new info)
Sounds System, Cruise, Alarms, Monitors	65 27 05	November-05	E60/E63/E90	CID Screen Image Not Displayed Correctly Since CCC Replacement
Sounds System, Cruise, Alarms, Monitors	65 28 05	March-06	E60/E63/E90	CCC: Radio Station Preset List Intermittently Empty (Supercedes Nov 05)
Sounds System, Cruise, Alarms, Monitors	65 30 05	March-06	E60/E63/E90	CCC: MP3 CD Playback Not Available (Supercedes Jan 06- minor changes)
Sounds System, Cruise, Alarms, Monitors	65 32 05	March-07	E60/E63/E90	CCC: CD/CDC Track Counter Advances After Mute Selected( Replaces 1/07)
Sounds System, Cruise, Alarms, Monitors	65 02 06	March-06	E60/E63/E90	CCC: Loss of Audio in All Modes (Supercedes Feb 06)
Sounds System, Cruise, Alarms, Monitors	65 04 06	March-06	E60/E63/E90	KL-R Stays On After Ignition Off – Comfort Access Only
Sounds System, Cruise, Alarms, Monitors	65 05 06	April-06	E60/E63/E90	CCC: CD Drive Errors
Sounds System, Cruise, Alarms, Monitors	65 06 06	April-06	E60/E63/E90	Various Problems with CCC Following Replacement
Sounds System, Cruise, Alarms, Monitors	65 08 06	September-06	E60/E63/E90	CCC with Top HiFi Loses Surround Sound after Navigation Announcement (Supercedes May 06)
Sounds System, Cruise, Alarms, Monitors	65 10 06	May-06	E60/E63/E90	New Audio-Test-CD for Diagnosing a Faulty CD/Audio-DVD Drive or Media
Sounds System, Cruise, Alarms, Monitors	65 12 06	June-07	E60/E63/E90	Popping/Crackling Noise from Audio System (rpl 12/06)
Sounds System, Cruise, Alarms, Monitors	65 16 06	September-06	E60/E63	CCC: Acoustic Warning Gong Sounds at Times, No CC Message
Sounds System, Cruise, Alarms, Monitors	65 18 06	October-06	E63/E64	DWA (Theft Deterant System) Causes Excessive Closed Circuit Current Draw
Sounds System, Cruise, Alarms, Monitors	65 25 06	June-07	ALL w / CCC	Enhanced Technical Support for Audio System (Replaces 3/07)
Sounds System, Cruise, Alarms, Monitors	65 26 06	October-06	E60/E63/E90	CCC Disclaimer Screen Disappears Automatically after 10 Seconds
Sounds System, Cruise, Alarms, Monitors	65 27 06	October-06	E60/E63/E90	CCC Does Not Play All MP3 Formats
Sounds System, Cruise, Alarms, Monitors	65 28 06	October-06	E60/E63/E90	CCC Radio Station RDS Information Missing After Programming
Sounds System, Cruise, Alarms, Monitors	65 29 06	April-07	E60/E63/E90	CCC Next Entertainment Source Not Selectable Via MFL (rpl 10/06)
Sounds System, Cruise, Alarms, Monitors	65 33 06	December-06	E60/E63/E90	CD Changer is Inoperative; Magazine is Jammed or Broken
Sounds System, Cruise, Alarms, Monitors	65 35 06	June-07	E60	Poor Radio Reception in FM Mode (rpl 12/06)
Sounds System, Cruise, Alarms, Monitors	65 36 06	August-07	E60	Poor Radio Reception in AM Mode (rpl 6/07)
Sounds System, Cruise, Alarms, Monitors	65 37 06	December-06	E60	RDS Function
Sounds System, Cruise, Alarms, Monitors	65 43 06	May-07	E60/E63/E90	CCC: High Frequency Noises from the DVD drive (rpl 12/06)
Sounds System, Cruise, Alarms, Monitors	65 44 06	December-06	E60/E63/E90	CCC: AUX-IN Loud Hissing if no Device Connected

Category	SIBs (SI B## ## ##)	Date	Application	Title
Sounds System, Cruise, Alarms, Monitors	65 45 06	December-06	E60/E63/E90	CCC: Poor Radio Reception after Software Update
Sounds System, Cruise, Alarms, Monitors	65 46 06	May-07	E60/E63/E90	CCC: Radio Continues to Play after Ignition off (rpl 12/06)
Sounds System, Cruise, Alarms, Monitors	65 48 06	December-06	E60/E63/E90	SIRIUS Satellite Radio Is No Longer Accessible
Sounds System, Cruise, Alarms, Monitors	65 03 07	April-07	E60/E63/E90	CCC: Slow Response from System when using Controller (Rpl Jan 07)
Sounds System, Cruise, Alarms, Monitors	65 04 07	January-07	E90/91	SDARS Sirius Radio is Inoperative After Programming
Sounds System, Cruise, Alarms, Monitors	65 06 07	March-07	All CCC equipped	CCC Symptom Troubleshooting
Sounds System, Cruise, Alarms, Monitors	65 07 07	April-07	E60/E63/E90/E92	SDARS SIRIUS Radio is Intermittently Inoperative
Sounds System, Cruise, Alarms, Monitors	65 08 07	May-07	E60/E63/E90/E92	USB Audio Interface
Sounds System, Cruise, Alarms, Monitors	65 18 07	July-07	E64 Cabrio	Radio or Speakers Inoperative
Sounds System, Cruise, Alarms, Moni	65 22 07	August-07	E60/E63/E90/E92	CCC CD Text not Updated When CD is Swapped
Sounds System, Cruise, Alarms, Moni	65 23 07	August-07	E60/E63/E90/E92	CCC Navigation Displays Incorrect Vehicle Position
Sounds System, Cruise, Alarms, Moni	65 24 07	August-07	E60/E63/E90/E92	CCC Navigation Map DVD not Detected
Sounds System, Cruise, Alarms, Moni	65 26 07	August-07	E60/E63/E90/E92	CCC: Volume Differences between CD/AUX and FM after Programming
Sounds System, Cruise, Alarms, Moni	65 28 07	September-07	E60/E63/E90/E92	CCC: Radio Does Not Resume With Previously Selected Station
Sounds System, Cruise, Alarms, Moni	65 33 07	October-07	E90/91/92/93/E70	iPod Mode is Switching to FM Mode
Sounds System, Cruise, Alarms, Moni	65 31 07	September-07	E60/E70	CHAMP: Intermittently No Audio Output in FM Mode Only After Restart
	11 07 for X5			
Remote Control Systems	- 01 other model		E65	
Remote Control Systems	66 03 05	November-05	E60/E63	PDC and Gong Volume Cannot be Adjusted
Remote Control Systems	66 01 06	February-06	E90	PDC Button not Installed (Supercedes Feb 06 with added info)
Remote Control Systems	66 04 06	November-06	E60/E63	Night Vision Malfunctions and Parts Replacement
Remote Control Systems	66 05 06	September-06	E61	Vehicle Does Not Start
Remote Control Systems	66 07 06	December-06	All	Remote Control Key Not Working
Remote Control Systems	66 02 07	March-07	All	Comfort Access: Replacement ID Transmitter Initialization
Remote Control Systems	66 04 07	September-07	E60/E63	Unexpected Lane Departure Warning
Safety Restraint Systems	72 05 04	June-04	E60/E63	Various "Self-Test" Faults Stored in "Byteflight" Modules
Safety Restraint Systems	72 02 05	August-06	E60/E65/E90	Passenger Airbag Status Lamp Goes ON/OFF During Driving (Replaces 1/06)
Safety Restraint Systems	72 03 05	June-05	E64 (Cabrio)	Check Control Message "Rollover Protection Fault"
Safety Restraint Systems	72 09 05	November-05	E64 (Cabrio)	Service Action: Reprogram Control Modules for Backrest Lock Microswitch
Safety Restraint Systems	72 02 06	June-06	ALL	Airbag Warning Lamp for OC3 Seat Mat Fault (Supercedes Mar 06 w/new parts info)
Safety Restraint Systems	72 03 06	January-06	E64 (Cabrio)	Airbag Warning Lamp Illuminated for Backrest Microswitch
Safety Restraint Systems	72 04 06	January-06	E90	Rear Belt Tensioners Deploy in Accident
Safety Restraint Systems	72 05 06	February-06	E60	Airbag Warning Illuminated, FC 9B2D in SFZ
Safety Restraint Systems	72 08 06	April-06	E90	OC3 Occupancy Status does not Change
Safety Restraint Systems	72 09 06	August-06	E90	Airbag Warning Lamp, FC93EB (Update to Apr -06)
Safety Restraint Systems	72 10 06	November-06	E90	Airbag Warning Lamp Illuminates - No Fault Codes (Replaces Apr 06)
Safety Restraint Systems	72 18 06	October-06	E60	Various Telegram Errors in Satellites
Safety Restraint Systems	72 19 06	October-06	E63	Various Fault Memory Entries in the SBE
Safety Restraint Systems	72 20 06	October-06	E60	SBSL/SBSR FC 9845/98C5, implausible crash severity
Safety Restraint Systems	72 24 06	October-06	E60	Rear Side Airbags Come Activated
Safety Restraint Systems	72 25 06	October-06	E60	FC 96CA: Passenger Thorax Airbag Resistance too Great
Safety Restraint Systems	72 26 06	October-06	E60	SGM FC 9413 "Signal Lamp Airbag Deactivation"
Safety Restraint Systems	72 28 06	December-06	E92	Seatbelt Assistant "hand" Portion Breaks Off
Safety Restraint Systems	72 29 06	December-06	E60/E63/E65	DIS Test Plan Error While Performing SIM/SGM Self Test
Safety Restraint Systems	72 01 07	January-07	E90/E91	Airbag Warning Lamp Illuminated, FC 93C1/93C3
Safety Restraint Systems	72 03 07	March-07	E92	Seat Belt Assistant Pinch Protection
Safety Restraint Systems	72 04 07	May-07	E63/64	Recall Campaign 07V-178: Replace the Seat Occupancy Detection Mat
Safety Restraint Systems	72 05 07	April-07	E92	Seat Belt Assistant Malfunction
	-07 other model			
Phone, Navigation systems	84 14 01	November-06	E60/E63	Telephone Installation on New Vehicles Replaces Mar 05)
Phone, Navigation systems	84 01 03	December-05	E60/E63	CPT9000 Telephone (Supercedes Aug 05 w/new info)
Phone, Navigation systems	B840103E60Telephone	P/O 84 01 03	E60/E63	E60/E63 TCU Wiring Diagram
Phone, Navigation systems	84 15 03	November-06	E60/E63	BMW Assist Initialization (Replaces Feb 06)
Phone, Navigation systems	B841503Diagnosis	P/O 85 15 03	E60/E63	Troubleshooting Guide (Flowchart)
Phone, Navigation systems	84 214 04	September-05	E60/E63	Linked Sequence calls Fail on Bluetooth (REPLACED BY 84 18 05)
Phone, Navigation systems	84 02 04	May-05	E60/E63	Navigation Map DVD for Vehicles with CCC
Phone, Navigation systems	84 03 04	July-04	E60	MFL Button Dials "911", or Last Number Dialed
Phone, Navigation systems	84 10 04	July-04	E60	CCC Navigation Retrofit Kit
Phone, Navigation systems	B841004Installer	P/O 84 10 04	E60	Installation Instructions
Phone, Navigation systems	B841004SalesBulletin	P/O 84 10 04	E60	Product Planning MY 04 5 Series
Phone, Navigation systems	84 12 04	February-06	E60/E63	Diagnosis and Repair of the CCC (Supercedes Nov 05)
Phone, Navigation systems	84 13 04	March-07	E60/E63	BMW Assist with Integrated Bluetooth (Rpl Jun 05)
Phone, Navigation systems	B841304BluetoothDiagnosis	P/O 84 13 04	E60/E63	Diagnostic Instructions for Bluetooth Telephone Systems
Phone, Navigation systems	B841304BluetoothUserManualBus.	P/O 84 13 04	E60/E63	Bluetooth Users Manual for Business Phone
Phone, Navigation systems	B841304BluetoothUserManualE60E63	P/O 84 13 04	E60/E63	Bluetooth Users Manual for CPT9000 and Bluetooth



Category	SIBs (SI B## ## ##)	Date	Application	Title
<b>Phone, Navigation systems</b>	<b>84 14 04</b>	<b>October-04</b>	<b>E60/E63</b>	<b>Service Action: Activate SVS (Voice Recognition System)</b>
Phone, Navigation systems	B841404Q&A	P/O 84 14 04	E60/E63	FAQ
<b>Phone, Navigation systems</b>	<b>84 01 05</b>	<b>July-05</b>	<b>E60/E63</b>	<b>Service Action: Reactivate TCUs for specified Production models that were accidentally deactivated</b>
Phone, Navigation systems	84 04 05	January-07	E60/E63	Nav system missing or incorrect data (Replaces April 05)
Phone, Navigation systems	84 07 05	June-05	E60/E63	Motorola v710 Handset Phonebook does not download
Phone, Navigation systems	84 08 05	April-07	E60 /E90	CID switches between BMW banner and blank screen (Rpl 3/06 - adds E90 & new procedure)
Phone, Navigation systems	84 09 05	June-05	E60/E63	CCC NAV places of interest (POIs)
Phone, Navigation systems	B800905POICategories	P/O 84 09 05	E60/E63	PDF of categories and sub categories
Phone, Navigation systems	B800905POI_ICONS	P/O 84 09 05	E60/E63	PDF of ICON symbols
<b>Phone, Navigation systems</b>	<b>84 10 05</b>	<b>May-06</b>	<b>E60/E63/E90</b>	<b>Nav Displays incorrect Vehicle Position (Supersedes Mar 06) - Replaced with 65 23 07</b>
Phone, Navigation systems	84 11 05	June-05	E60/E63	CCC CD/DVD disc does not eject
Phone, Navigation systems	84 12 05	April-06	E60/E63	DVD Drive makes clicking noise (Supersedes Aug 05 w/E90)
Phone, Navigation systems	84 13 05	May-07	E60/E63/E90	Bluetooth Phone call may still be displayed as active after the call has ended (Rpl 3/07 - adds E90)
Phone, Navigation systems	84 14 05	November-05	X5/Z4	Retrofit TCU
Phone, Navigation systems	84 18 05	September-05	E60/E63	Linked Sequence calls Fail on Bluetooth and CPT9000 Handsets
Phone, Navigation systems	84 19 05	September-05	E90	Teleservice does not place call for CBS due
Phone, Navigation systems	84 24 05	August-06	E60/E63/E90	CCC Voice Input System Incorrectly States Speed Limit in "km" (Supersedes Nov 05)
Phone, Navigation systems	84 25 05	January-06	E90	Software error in the Telematics Control Unit (TCU). (Supersedes Dec 05)
Phone, Navigation systems	84 02 06	January-06	All	Hands free Bluetooth® Phone Call May be Lost if a Call Waiting Call is Received
Phone, Navigation systems	84 03 06	March-07	All	Enhanced Support for CCC Car Communication Computer (Supersedes Dec 06)
<b>Phone, Navigation systems</b>	<b>84 04 06</b>	<b>July-06</b>	<b>All</b>	<b>Service Action: Reactivation of Telematics Control Unit (TCU) (Replace Mar 06)</b>
Phone, Navigation systems	84 05 06	March-07	All	Diagnosis of Bluetooth® Handset Related Complaints (Rpl Mar 06)
Phone, Navigation systems	84 06 06	March-06	All	Information Displayed in the BMW Assist Menu is Incorrect or Unknown
Phone, Navigation systems	84 08 06	March-06	All	CCC Navigation is Inoperative at Low Ambient Temperatures
Phone, Navigation systems	84 09 06	April-07	All	Bluetooth® Inoperative, TCU FC# A379 or 79 (Rpl Apr 06)
<b>Phone, Navigation systems</b>	<b>84 10 06</b>	<b>August-07</b>	<b>E60/E63/E90</b>	<b>BMW Assist or Bluetooth® Inoperative, TCU FC# A379 (rpl 4/06)</b>
<b>Phone, Navigation systems</b>	<b>84 14 06</b>	<b>May-07</b>	<b>E60/E63/E90</b>	<b>Service Action: Reactivation of Telematics Control Unit (TCU) - (superseded Dec 06)</b>
Phone, Navigation systems	84 15 06	May-06	E60/E63/E90	CCC Navigation Address Book Shows Duplicate Entries after Programming
Phone, Navigation systems	84 18 06	June-06	E60/E63/E90	Low Bluetooth Signal is Displayed in the Handset or the Bluetooth® Connection is Lost
Phone, Navigation systems	84 20 06	September-06	E60/E63/E90	CCC Navigation Stuck on "Accept" Screen(Supersedes Jun 06)
<b>Phone, Navigation systems</b>	<b>84 23 06</b>	<b>May-07</b>	<b>E60/E63/E90</b>	<b>Service Action: Telematics Control Unit (TCU) – MOST-bus Vehicles Supersedes Dec 06)</b>
Phone, Navigation systems	84 25 06	December-06	E60/E63/E90/E65	NAD Check, Recovery or Deactivation Procedure (MOST-Bus vehicles) Supersedes Oct 06
Phone, Navigation systems	84 26 06	December-06	E60/E63/E90/E65	Cannot Enable BMW Assist Services (Supersedes Aug 06)
Phone, Navigation systems	84 27 06	December-06	E60/E63/E90/E65	BMW Assist Inactive Warning Message Displayed (Supersedes Aug 06)
Phone, Navigation systems	84 48 06	October-06	E60/E63	CPT9000 (V60s) Telephone Switches to Silent Mode when Connected to Vehicle
Phone, Navigation systems	84 49 06	October-06	E60/E63	Vehicle Dials BMW Assist on its Own
Phone, Navigation systems	84 50 06	October-06	E60/E63	CPT9000 Handset Phone does not Load into Vehicles
Phone, Navigation systems	84 51 06	October-06	E60/E63	The BMW Assist "Embedded" Phone Rings Erroneously in the Vehicle
Phone, Navigation systems	84 58 06	November-06	E60/E63/E90/E92	Real Time Traffic Information w/PDF attachment (Updated in Nov 06)
Phone, Navigation systems	84 59 06	October-06	E90/E92	CCC Telephone Address Book Not in Alphabetical Order
Phone, Navigation systems	84 61 06	March-07	E60/E63/E90/E92	CCC Navigation System Pop-up Arrow Display Missing During Route Guidance (rpl 10/06)
Phone, Navigation systems	84 62 06	December-06	E60/E63/E90/E92	Program Displays "The TEL Control Module is Malfunctioning" on the Final Report
Phone, Navigation systems	84 01 07	January-07	E60/E63/E90/E92	CCC SVS: Letter and Number Inputs by Voice are Misinterpreted
<b>Phone, Navigation systems</b>	<b>84 02 07</b>	<b>March-07</b>	<b>E60/E63/E90/E92</b>	<b>Service Action: Activation of Telematics Control Unit (TCU)</b>
Phone, Navigation systems	84 04 07	March-07	E60/E63/E90/E92	Bluetooth® Handsets No Longer Pairs to the Vehicle
Phone, Navigation systems	84 06 07	March-07	E90	Call Cannot be Answered if the Voice Recognition System (SVS) is Active
Phone, Navigation systems	84 07 07	April-07	E60/E63/E90	NAD was Found to be Faulty when Performing SI B84 22 05 (Reactivation of BMW Assist Services)
Phone, Navigation systems	84 09 07	July-07	E60/E63/E90	Echo on Landline Side of Phone Call
<b>Phone, Navigation systems</b>	<b>84 11 07</b>	<b>August-07</b>	<b>E60/E90</b>	<b>Service Action: Replace the Hands-Free Charging Electronics (MULF2-High) rpl 7/07</b>
Phone, Navigation systems	84 12 07	July-07	E60/E63/E90/E92	Voice Only Call, No Data Transmitted When Placing a BMW Assist Call
Phone, Navigation systems	84 13 07	July-07	E60/E63/E90/E92	BMW Assist Location (GPS) Unknown or Inaccurate, When Placing a BMW Assist Call
<b>Phone, Navigation systems</b>	<b>84 16 07</b>	<b>September-07</b>	<b>E60/E63/E90/E92</b>	<b>Erroneous SOS Inactive Warning Message (rpl 7/07)</b>
<b>Phone, Navigation systems</b>	<b>84 17 07</b>	<b>September-07</b>	<b>E60/E63/E90/E92</b>	<b>SOS Inactive Warning Message, No Communication with TCU</b>
<b>Phone, Navigation systems</b>	<b>84 18 07</b>	<b>August-07</b>	<b>E60/E63/E90/E92</b>	<b>Enable Services Status Bar Does NOT Progress</b>
<b>Phone, Navigation systems</b>	<b>84 19 07</b>	<b>October-07</b>	<b>E60/E63/E90/E92</b>	<b>One Way Audio when Using a Bluetooth Enabled Handset</b>

-03 other model

**NOTE: Text in Maroon represents new data or updated since previous edition (SIB\_List\_rev\_13)**

**Red = Safety recall notice**

**Bold = Service Action or Recall campaigns**

Another Service Bulletin resource ----> Checkout periodically to see if they keep c

**This link seems to have been closed to non-subscribers sometime in January 2007**

Most Recent

No Longer available fr <http://www.alldata.com/tsb/BMW/index-post.html>