

SIB Date (If known)*	Application	ISTA/P (formerly PROGMAN/formerly CIP) to Target data Status	Comments/Fix list	Features Added/Changed
		Reference (Edited and compiled by Cobradav) Courtesy of KoTR @ bimmerdrivers.com		
Announced and available in May 09, other BMW source	E60/E63	ISTA/P 2.33.3 (Target data Status E060-09-03-512) Online	SIB 651809 - HD Radio activation	UNK
Announced and available in May 09, other BMW source	E60/E63	ISTA/P 2.33.2 (Target data Status E060-09-03-512) Online	UNK	UNK
Announced and available in Apr 09, other BMW source	E60/E63	ISTA/P 2.33.1 (Target data Status E060-09-03-512) DVD	SIB 651009 w/CIC - Nav error - recode and recal CIC  Plan 3 hours to load ISTA/P software - info for ALL updates	UNK
Announced and available in Apr 09, other BMW source	E60/E63	ISTA/P 2.33.0 (Target data Status E060-09-03-510) DVD	SIB 120509 Turbo misfire SIB 240309 /550/650 - Intermittent harsh 4-3, 3-2 or 2-1 downshift (jolt) when coming to a stop with light brake application. Jolts and/or jerks felt when reaccelerating after coasting. Judder when gently accelerating (most noticeable at an engine speed below 2,000 RPM). SIB 840809 - Poor voice qual at landside end	UNK
Announced and available in Feb 09, other BMW source	E60/E63	ISTA/P 2.32.2 (Target data Status E060-08-09-530) Online	SIB 250109 - D or R cannot be selected - Fix GWS (New shifter) software	UNK
Announced in Nov 08, and available in Jan 09 - other BMW source	E60/E63	ISTA/P 2.32.1 (Target data Status E060-08-09-530) Online	<b>Fix "Turbo lag" by going back to original setup (see PROGMAN 29.02.00), fix TCU error in certain build dates, fix DME (service engine soon caused by misfires) errors in Turbo engine (but SIB 120509 related)</b> SIB 841108 - BMW assist inop in some areas	UNK
<u>First use of ISTA/P designation</u>	E60/E63	ISTA/P 2.32.0 (Target data Status E060-08-09-530) DVD		UNK
Announced in Nov 08, other BMW Source	E60/E63	PROGMAN 31.02.00 (Target data Status E060-08-09-530) DVD	E60 EGS	UNK
Announced in Sep 08, for rel in Oct other BMW Source	E60/E63	PROGMAN 31.01.00 (Target data Status E060-08-09-520) DVD	SIB 240308 - E60 EGS harsh shift - NIC, Fix GWS shifter error	UNK
<b>Rel Sep 08, other BMW Source</b>	<b>E60/E63</b>	<b>PROGMAN 31.00.00 (Target data Status E060-08-09-515) DVD</b>	<b>Programming Fix SMG III gear select, fix intermittent Adaptive Headlights</b>	<b>UNK</b>
Rel May 08, other BMW Source	E60/E63	PROGMAN 30.00.02 (Target data Status E060-08-03-550) Online-update	Programming	UNK
Rel May 08, other BMW Source	E60/E63	PROGMAN 30.00.01 (Target data Status E060-08-03-550) Online-update	Programming	UNK
Rel May 08, other BMW Source	E60/E63	PROGMAN 30.00.00 (Target data Status E060-08-03-550) DVD	Programming	UNK
<b>Rel 23 Apr 08, other BMW Source - no SIB</b>	<b>E60/E63</b>	<b>PROGMAN 29.02.00 (Target data Status E060-08-03-525) Online-update</b>	<b>Introduced "Turbo lag" in attempt to fix some complaints on "noise"</b>	<b>UNK</b>
Rel Mar 08, other BMW Source - no SIB	E60/E63	PROGMAN 29.01.01 (Target data Status E060-08-03-525) Online-update	Coding & Programming for 5 and 6 series	UNK
Rel Mar 08, other BMW Source - no SIB	E60/E63	PROGMAN 29.01.00 (Target data Status E060-08-03-515) Online-update	Coding & Programming for 5 and 6 series	UNK

SIB Date (If known)*	Application	ISTA/P (formerly PROGMAN/formerly CIP) to Target data Status	Comments/Fix list	Features Added/Changed
		Reference (Edited and compiled by Cobradav) Courtesy of KoTR @ bimmerdrivers.com		
Rel Mar 08, other BMW Source - no SIB	E60/E63	PROGMAN 29.00.00 (Target data Status E060-08-03-510) DVD only	Coding & Programming for 5 and 6 series	UNK
Rel Dec 07, other BMW Source - no SIB	E60/E63	PROGMAN 28.00.01 (Target data Status E060-07-09-530) Online-update	Coding changes only	UNKnown
Rel Dec 07, other BMW Source - no SIB	E60/E63	PROGMAN 28.00.00 (Target data Status E060-07-09-521) DVD only	No Vehicle changes for 5, 6, 7, X5 series	
Rel Oct 07, other BMW Source - no SIB	E60/E63	PROGMAN 27.02.01 (Target data Status E060-07-09-521) Online-Update	Coding only for 5 & 6 series	
Rel Oct 07, other BMW Source - no SIB	E60/E63	PROGMAN 27.02.00 (Target data Status E060-07-09-521) Online-Update	No coding/programming for 5 or 6 series	
Rel Sep, other BMW Source - no SIB	E60/E63	PROGMAN 27.01.01 (Target data Status E060-07-09-521) Online-Update	Unknown	
Contained in another SIB on SOS	E60/E63	PROGMAN 27.01.00 (Target data Status E060-07-09-520) DVD / Online-Update	Fix erroneous SOS Inactive Warning Message	
SIB released 27 Sept 07	E60/E63	PROGMAN 27.00.00 (Target data Status E060-07-09-515) DVD	iPod switch to FM, radio select different station, intermittent FM audio, E64 driver seat shifting	Only to be used with DIS v48 or v49 & SSS Base Xpe v3.1
Released in June no SIB	E60/E63	PROGMAN 26.02.00 (Target data Status E060-07-03-525) Online-Update	No changes for US Market	
Released in June no SIB	E60/E63	PROGMAN 26.01.02 (Target data Status E060-07-03-520) Online-Update	Coding changes only	
Released in June no SIB	E60/E63	PROGMAN 26.01.01 (Target data Status E060-07-03-520) Online-Update	No changes	
Released in June no SIB	E60/E63	PROGMAN 26.01.00 (Target data Status E060-07-03-520) Online-Update	Application update only	
Released in June no SIB	E60/E63	PROGMAN 26.01.00 (Target data Status E060-07-03-520) Online-Update	Application update only	
Released in June no SIB	E60/E63	PROGMAN 26.00.00 (Target data Status E060-07-03-525) DVD only	Only to be used with DIS v48 or v49 & SSS Base Xpe v3.1	
Rel Apr, other BMW Source	E60/E63	PROGMAN 25.02.00 (Target data Status E060-07-03-525) Online-Update	Programming for 5 and 6 series	
<b>4/7/2007 (posted on TIS ~ 22 April)</b>	<b>E60/E63</b>	<b>PROGMAN 25.01.00 (Target data Status E060-07-03-520) DVD + online update</b>	<b>Fix RTTI/SAT Radio</b>	
Rel Mar, other BMW Source	E60/E63	PROGMAN 25.00.02 (Target data Status E060-07-03-516) Online-Update	No coding or programming	
Rel Mar, other BMW Source	E60/E63	PROGMAN 25.00.01 (Target data Status E060-07-03-516) Online-Update	Fix errors induced by 25.00.00 & coding & programming for 5 & 6 series	
3/7/2007 (posted on TIS ~ 4 April)	E60/E63	PROGMAN 25.00.00 (Target data Status E060-07-03-510)	<b>Fix CD Run on/Nav Pop up arrows in small screen, many other CCC fixes, may have VR issues</b>	<b>POI Search, colors changed in display, faster response time, AUX input now selectable from steering wheel button</b>
Released in Dec, no SIB	E60/E63	PROGMAN 24.01.01 (Target data Status E060-06-12-510) Online-Update	No changes to 5 or 6 series	
Released in Dec, no SIB	E60/E63	PROGMAN 24.01.00 (Target data Status E060-06-12-510) Online-Update	New Coding data - no fixes	
<b>12/6/2006 (posted ~ 6 Dec)</b>	<b>E60/E63</b>	<b>PROGMAN 24.00.00 (Target data Status E060-06-12-510) DVD</b>	<b>Fix front/side marker in 5 series, coding data for all series and programming data for 5 &amp; 6 series &amp; VC on RTTI</b>	
Rel in Nov, other BMW source	E60/E63	PROGMAN 23.02.02 (Target data Status E060-06-09-520)	Patched to make iPod retrofit work, coding data for 5 & 6 series & programming data for 5 series	
November-06	E60/E63	PROGMAN 23.02.01 (Target data Status E060-06-09-520)	No changes to 5 or 6 series	

SIB Date (If known)*	Application	ISTA/P (formerly PROGMAN/formerly CIP) to Target data Status	Comments/Fix list	Features Added/Changed
		Reference (Edited and compiled by Cobradav) Courtesy of KoTR @ bimmerdrivers.com		
October-06	E60/E63	PROGMAN 23.02.00 (Target data Status E060-06-09-520)	Bug causes iPod not to work Owners report cases of DME overwrite	
September-06	E60/E63	PROGMAN 23.01.00 (Target data Status E060-06-09-520)	The set of xx.xx.00, xx.xx.01 & xx.01.xx contain programming changes for 5 & 6 series	
September-06	E60/E63	PROGMAN 23.00.01 (Target data Status E060-06-09-520) Online-Update	Must be used in conjunction w/23.01.00 load both	
September-06	E60/E63	PROGMAN 23.00.00 (Target data Status E060-06-09-520) DVD	Several CCC fixes	
June-06	E60/E63	PROGMAN 22.00.00 (Target data Status E060-06-06-510)		
<b>March-06</b>	<b>E60/E63</b>	<b>PROGMAN 21.01.00 (Target data Status E060-06-03-515)</b>	<b>Fixed for use on e64</b>	
March-06	E60/E63	PROGMAN 21.00.00 (Target data Status E060-06-03-510)	Do not use on e64	
<b>January-06</b>	<b>E60/E63</b>	<b>PROGMAN 20.02.00 Online Update (Target data Status E060-05-12-510)</b>		
January-06	E60/E63	PROGMAN 20.01.00 (Target data Status E060-05-12-510)		
December-05	E60/E63	PROGMAN 20.00.00 (Target data Status E060-05-12-500)		MP3 retrofit for CD and Nav
November-05	E60/E63	CIP 19.02.03 (Target data Status E060-05-09-535)	No Changes reported	
October-05	E60/E63	CIP 19.02.00 (Target data Status E060-05-09-530)		
September-05	E60/E63	CIP 19.01.00 (Target data Status E060-05-09-530)	RDS Coded ON	
September-05	E60/E63	CIP 19.00.00 (Target data Status E060-05-09-510)		
July-05	E60/E63	CIP 18.00.01 Online Update (Target data Status E060-05-06-510)		
July-05	E60/E63	CIP 18.00.00 (Target data Status E060-05-06-510)		
June-05	E60/E63	CIP 17.01.00 (Target data Status E060-05-06-500)		
June-05	E60/E63	CIP 17.00.00 (Target data Status E060-05-03-520)		
<b>March-05</b>	<b>E60/E63</b>	<b>CIP 16.1 (Target data Status E060-05-03-520)</b>		<b>Perspective View on NAV and new NAV menu selections on left side</b>
February-05	E60/E63	CIP 16.0 (Target data Status E060-04-09-555)		
<b>December-04</b>	<b>E60/E63</b>	<b>CIP 15.2 (Target data Status E060-04-09-555)</b>	<b>As delivered version</b>	
December-04	E60/E63	CIP 15.0 (Target data Status E060-04-09-555)		
October-04	E60/E63	CIP 13.3 (Target data Status E060-04-09-504)		
September-04	E60/E63	CIP 13.2 (Target data Status E060-04-09-504)		
June-04	E60/E63	CIP 12.0 (Target data Status E060-04-06-500)	Last Time DME was updated, RDS coded OFF	
April-04	E60/E63	CIP 11.0 (Target data Status E060-04-03-505)		
January-04	E60/E63	CIP 10.1 (Target data Status E060-03-12-527)		
December-03	E60/E63	CIP 10.0 (Target data Status E060-03-12-525)		
<b>Red = New since last report</b>				
<b>Green = versions installed on my car</b>				
* First reported use date if the official SIB Bulletin date is unknown.				
<b>Notes:</b>				
1) Not ALL updates contain changes to a specific series. - i.e coding changes for new features on new models, changes to work with diagnostic software, etc.				
2) New features are not included in the SIB - may be available via other BMW source or from user reports on forums				
3) Service personnel often truncate version number based on diagnostic & update equipment that display the version info i.e. v30.00.02 will be reported as 30.2				
4) Nomenclature has changed through the years from CIP, PROGMAN and most recently ISTA/P. In some cases new dealer hardware was required to implement change				