

Official

Carly Diagnostics Report

5 (E60), Build Year 2006

categorized as Upper middle class was diagnosed with Carly on

Mar 20 2019

Carly found 22 control units.

18 fault codes were detected.



Motor Control

 Engine / Motor

 Fault Code: 00CDA8

 Fault Explanation: Message (status COMBI, 1B4)

 Fault Code: 00CD94

 Fault Explanation: Message (outside temperature / relative time, 310)



ABS / DSC / Brake

Dynamische Stabilitaets Kontrolle / DSC

Fault Code: 00D35E

Fault Explanation: :CAN message: PT CAN KILOMETERST ID: 0x330 / PT-CAN: not received message A TEMP RELATIVE TIME (ID 0x310). [Channel: Combined] / CAN fault: A message TEMP RELATIVE TIME (ID 0x310) is missing! / CAN message / EHC Error: air suspension - Embassy EHC1 (ID 0x5DC) missing (RCV) (DSC-ECU received). / PT-CAN: A message TEMP relative time (ID 0x310) does not receive [Channel: Combination]. / PT-CAN: A message TEMP relative time (ID 0x310) does not receive (ID 0x310) does not receive [Channel: Combination]. / PT-CAN: A message TEMP relative time (ID 0x310) does not receive [Channel: Combined] --- (DSC: message (temperature 310) is missing)



Airbag

Advanced Crash and Safety Management (ACSM)	
Fault Code: 0093C1	×
Fault Explanation: :Package abound / SBE passenger / SBE - Passenger / Timeout ID 35H (telegram live) AFS (Only E6x)	

X



Transmission Control

Transmission / Getriebe GS 19Fault Code: 00CF23Fault Explanation: :Message (status pendants, PT-CAN) by AHM /
Invalid data received from instrument pack status / CAN bus /
Embassy of the instrument cluster: Status COMBIFault Code: 00CF21Fault Explanation: :CAN bus / Embassy of the instrument cluster:
Mileage Range / CAN message of the combination: outside
temperature relative time / Embassy (raw data longitudinal
acceleration, PT-CAN) from the DSC / Invalid Data Received from
Operation gear selector



Instrument cluster

Instrument cluster / Kombiinstrument	
Fault Code: 00A559	×
Fault Explanation: :Klemme30g f shutdown / KL30g f shutdown / KL.30g f shutdown / KL30g f Cutoff	^
Central info display / Zentrales Display	
Fault Code: 00A46D	
Fault Explanation: :Malfunction CID by resetting the Head Unit / Head-Unit Reset (no defect) / Hardware Error: vehicle electrical system voltage measurement path is broken	×



Light/Rain Control

Rain/light sensor / Regen-Lichtsensor RLS	
ECU OK, no Fault Code	
Light / Licht	
ECU OK, no Fault Code	



Heating / AC

Air conditioning / Klimaanlage	
Fault Code: 00E715	
Fault Explanation: :Embassy (KCAN: Mileage / reach, 330) / CAN message outside temperature / Can embassy outside temperature	
Fault Code: 00E717	V
Fault Explanation: :Embassy (KCAN: relative time, 328) / CAN message engine data / Can embassy motor data	^
Fault Code: 00E71B	
Fault Explanation: :Can embassy heat flow engine / Embassy (KCAN: Outside temperature 2CA) / CAN message heat flow engine	



Immobilizer System





Park distance control

Park Distance Control / PDC	
ECU OK, no Fault Code	



Sunroof / Roof

Sunroof / Schiebedach ECU OK, no Fault Code



 \checkmark



Audio/Navi/Communication

Car Communication Computer CCC	
Fault Code: 00E18D	
Fault Explanation: :Awakening device has three times unsuccessfully, the network tries to awaken (Error WakeUp Failed) / Awakening device has unsuccessfully tried to wake the network times. 3 (Error WakeUp Failed).	×
Fault Code: 00E18F	
Fault Explanation: :Central Registry does not match the target configuration (Error Registry New).	
MASK	
ECU OK, no Fault Code	
Center-Konsole	
ECU OK, no Fault Code	
Navigation	
ECU OK, no Fault Code	
CD-Changer / Wechsler	
ECU OK, no Fault Code	



Systems

Gateway	
Fault Code: 0093B7	
Fault Explanation: : Drive folded in mirror passenger side defective	X
Fault Code: 0093B4	
Fault Explanation: : Drive folded in mirror driver side defect	
Steering column switch / Lenkstockschalter	
Fault Code: 00951A	
Fault Explanation: :Voltage monitoring LRE lower limit exceeded / System undervoltage	
Fault Code: 00C9A4	X
Fault Explanation: :PTCAN message: Outside temperature / relative time-out	
Fault Code: 00C9A6	
Fault Explanation: : PTCAN message: Mileage timeout	
Fuel pump / Kraftstoffpumpe	
ECU OK, no Fault Code	



Chassis

Central Control / Zentrale Bedieneinheit

ECU OK, no Fault Code

 \checkmark



Car Body Module	
ECU OK, no Fault Code	