

Error Memory

Date: 3/21/23 4:33:09 PM
VIN: WBANA73534B058596

01 Safety and information module

2 errors

9402: UpFront left sensor defective

9404: Upfront parameter inconsistent

40 Car access system

1 error

D904: K_CAN_Leitungsfehler

41 Antitheft alarm system

1 error

D944: K-Can Physical error

43 Micro-power module

1 error

D9C4: K-CAN bus low

44 Sliding/tilting sunroof

2 errors

DA04: Error K_CAN_LOW

A092: Error normalization SHD

60 Instrument panel

1 error

E104: CAN LOW ERROR

65 Centre console control panel

1 error

E244: CAN low, physical bus error

67 Controller

1 error

E2C4: Error CAN physical error

6D Seat module, driver, rear

1 error

E444: CAN low, physical bus error

6E Seat module, passenger, rear

1 error

E484: CAN low, physical bus error

70 Lights module

2 errors

E504: CAN low, physical error

E519: Alive signal from the ALC system is missing

72 Basic body module

1 error

E584: K_CAN_KURZSCHLUSS

78 Heating/air-conditioning control

3 errors

9C77: Auxiliary water pump

E704: K-Can physical bus error

9C54: AUC sensor

A2 Satellite, B-pillar, right

1 error

95B8: OC3 error