

Function changes (50503510 V16.1 F05)

Programming the vehicle will produce the following changes in function. Please keep this document with the Owner's Handbook.

The following changes in function are described:

- Status information faded out when Control Display switched off. Modified displays.
- BMW contact*: Revised menu guidance.
- Navigation system*: Expanded menu in arrow view.
- Navigation system Professional*: New menu in map view. New "perspective" map view.
- Touring: Automatic tailgate actuation*: New function "Set opening height".
- BMW radio Professional: Playback of compressed audio files.
- Service requirements: Modified display if service is not performed on time.

Status information faded out when Control Display switched off. Modified displays.

Status information on the Control Display is now faded out when the Control Display is switched off.

The status information displays have been modified.

