



Rib interference.  
Consider removing material from the backside of the grill instead of the car!



