



Calgary BMW
 150 Glendee Circle S.E., Calgary, Alberta T2H 2V4
 Tel: (403) 253-0338 Fax: (403) 253-6638
 www.calgarybmw.ca
 Account Inquiries: (403) 253-6531

NI

G.S.T. Vendor # 13087 7384 RT

CELL: 403-870-2109

Terms


| | | | | | |
|--------------------------|--------------------------|--------------------------|--------------------------|--------------------------|--------------------------|
| Cash | Cheque | Visa | M/C | AMEX | Debit |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

Indebtedness is hereby acknowledged in the sum of \$ _____ being all of the balance owing for repairs, parts and accessories described in this work order. Payment is due in full upon receipt of statement.

| | | | | |
|----------------------------|-----------------------------------|----------------------------------|--------------------------------|---------------------------------|
| Customer No. 100353 | Advisor | Tag No. 2322 | Invoice Date 12/20/06 | Invoice No. BMCS62593 |
| DEMITT | License No. GTU530 | Km 20,041 | Colour CARBON BLAC | Stock No. N6018 |
| CALGARY, AB T2S 1Z7 | Year/Make/Model 06/BMW/530 | Vehicle Id. No. WBANN7358 | Delivery Date 06/08/05 | Delivery Km. 14,215 |
| | Vehicle Id. No. WBANN7358 | RO. No. | Selling Retailer No. 10 | Production Date 05/01/05 |
| | Comments | | R.G. Date 17/08/06 | In Service Date 06/08/05 |

JOB# 5 CHARGES----- MO: 20041

LABOR-----
 34 54BMZ400 SUNROOF TECH(S) 1104/1208 WARRANTY
 COMPLAINT: CHECK HIGH LEVEL OF WINDNOISE FROM SUN ROOF - WORSE WHEN GOING INTO HEAD WINDS - BULLITENS? WITH SUNROOF LINER OPEN. VEHICLE LEAKED WATER WHEN IT WENT THROUGH A CARWASH
 CORRECTION: REPROGRAMMED SHD (SUN ROOF MODULE) WITH PROGMAN 24.1 AS PER PUMA MEASURE 6050811-02. REINITIALIZED ROOF.
 SEE JOB 1



JOB# 5 TOTALS-----
 JOB# 6 CHARGES----- JOB# 5 JOURNAL PREFIX BMCS JOB# 5 TOTAL 0.00

LABOR-----
 34 6 36RMZ WHEEL/TIRE DIAGNOSE TECH(S) 1208 INTERNAL
 COMPLAINT: R-REAR TIRE IS NOW FLAT - TIRE MONITORING SYSTEM NOT WORKING
 CAUSE: NAIL IN TIRE
 CORRECTION: REPLACED LEFT REAR RUN FLAT TIRE. PLEASE NOTE THAT THIS TIRE HAS BEEN REPAIRED PREVIOUSLY VERY CLOSE TO THE SIDE WALL WITH A PLUG PATCH. RFT ARE NOT REPAIRABLE.

| PARTS | QTY | FP NUMBER | DESCRIPTION | UNIT PRICE | TOTAL - PARTS |
|-------|-----|------------|--------------|------------|---------------|
| | 1 | D225-50R12 | WIN SPORT M3 | | INTERNAL 0.00 |

JOB# 6 TOTALS-----
 JOB# 6 JOURNAL PREFIX BMCS JOB# 6 TOTAL 0.00

COMMENTS-----
 ACT-LOANER
 TAX SUMMARY-----
 GST 0.00 R-130877384RT0001

Parts & Service Department Hours

Monday - Friday
 7:00 AM - 6:00 PM
 Saturday
 9:00 AM - 4:00 PM

Sales Department Hours

Monday - Thursday
 8:00 AM - 9:00 PM
 Friday
 8:00 AM - 6:00 PM
 Saturday
 9:00 AM - 6:00 PM

All repairs performed using BMW original parts are warranted against defects in material and workmanship for a period of 12 months.

Thank you for choosing Calgary BMW

The Ultimate Driving Experience.™

CUSTOMER COPY

[CONTINUED ON NEXT PAGE] 02:33pm