

The following is an updated list of bmw approved bluetooth phones:

AT & T:

Motorola V600

Sony Erickson T616

Sony Erickson T637

Sony Erickson T68i *discontinued

Siemens S56 *discontinued

CINGULAR:

Motorola V600

Sony Erickson T637

SPRINT:

Sony Erickson T608

TEAM MOBILE:

Motorola V600

Sony Erickson T610






VERIZON:

Motorola V600.....not fully supported due to verizon software

Blue tooth will work on 03/04-on 5 series. However, production of cars prior to 09/04 must have a software update to 13.2 or greater and must have the Bluetooth program turned on. The phone must also be paired to the car via the I-drive.

Recommended Bluetooth™ Phones:

While Bluetooth™ is a standardized protocol, not every phone has been tested with the BMW ULF Hands-Free Phone System with Bluetooth wireless technology. This list of recommended phones will be updated as new phones are tested. While in theory all Bluetooth™ phones should work with the ULF system, BMW can only recommend phones that we have tested. Functions such as synchronizing the address book, and transferring a call in or out of the vehicle will function differently from phone to phone. Please consult the BMW ULF owner's manual and your phone manual for detailed information.

	Model	Carriers*
	<p align="center">Sony Ericsson T68i</p>	<p>AT&T Wireless Cingular T-Mobile</p>
	<p align="center">Motorola V600 (Important Pairing Instructions)</p>	<p>AT&T Wireless and Cingular</p>
	<p align="center">Sony Ericsson T610/T616</p>	<p>Cingular AT&T Wireless T-Mobile</p>
	<p align="center">Nokia 6310i</p>	<p>AT&T Wireless</p>
	<p align="center">Siemens S56/S55</p>	<p>AT&T Wireless Cingular</p>

* This list is provided for reference only and does not guarantee availability from each wireless carrier. Please check with your local provider for more information on phones with Bluetooth wireless technology, offered in your area.

5/1/2004