

Replacing windscreen for head-up display (HUD)

E60

Situation:

On the vehicle affected, various information that is of relevance to the driver (e.g. speed, navigation) is projected as a virtual image by the head-up display (HUD) onto the windscreen, depending on the vehicle's equipment.

To ensure that the image is projected correctly, a special windscreen must be installed. This windscreen is made up of three parts. An outer and an inner glass sheet are connected by a wedge-shaped plastic film. This wedge shape prevents the head-up display from producing a double image.

E

X

ample of display using a conventional windscreen:



I

f a conventional windscreen is used, the projected image will be reflected onto both the inner and outer glass. This overlap will cause a double image.

Affected vehicles:

E60 with head-up display (option 610)

Procedure:

I

f the windscreen has to be replaced, a special windscreen **must** be used.

This is

mar

k

ed with the letters "HUD" at the bottom right edge and guarantees the correct function of the head-up display.

Proceed as described in Repair

I

nstructions RA 51 31 000 "Removing and installing windscreen".