

EGS/SMG must be reprogrammed
Part no., progr. ECU: 7558398 (is)
7560696 (should)

DWA must be reprogrammed
Part no., progr. ECU: 6958414 (is)
6974370 (should)

MPM must be reprogrammed
Part no., progr. ECU: 6939655 (is)
6982347 (should)

SZM must be reprogrammed
Part no., progr. ECU: 6969418 (is)
6985748 (should)

CID must be reprogrammed
Part no., progr. ECU: 6952328 (is)
6970343 (should)

SZL must be reprogrammed
Part no., progr. ECU: 6962920 (is)
6978183 (should)
