

FSC Enabling Codes Part Sales

As of November 2012

Description	Application-Number (AN)	Upgrade-Index (UI)	MEDIA-TYPE
CCC			
CCC Voice Recognition Code Retrofit/Repair	0002	0001	Download from ASAP
CIC HIGH			
CIC Navigation Code HB Retrofit/Repair	0019	0001	Download from ASAP
CIC Voice Recognition Code Retrofit/Repair	0017	0001	Download from ASAP
CIC Navigation Enabler Code Retrofit/Repair	001B	0001	Download from ASAP
CIC Map Europe 2010	0028	0001	Download from ASAP
CIC Map Europe 2010.	0028	0002	Download from ASAP
CIC Map Europe 2011	0028	0003	Download from ASAP
CIC Map Europe 2012	0028	0004	Download from ASAP
CIC Map Europe 2013	0028	0005	Download from ASAP
CIC Map North America 2010	002D	0001	Download from ASAP
CIC Map North America 2010.	002D	0002	Download from ASAP
CIC Map North America 2011	002D	0003	Download from ASAP
CIC Map North America 2012	002D	0004	Download from ASAP
CIC Map North America 2013	002D	0005	Download from ASAP
CIC SDARS Code Retrofit/Repair	006F	0001	Download from ASAP
CIC BMW Apps Enabling Code	009C	0001	Download from ASAP
CIC MID			
CIC MID Voice Recognition Code Retrofit/Repair	0044	0001	Download from ASAP
CIC MID SDARS Code Retrofit/Repair	006F	0001	Download from ASAP
Champ2			
Champ2 Voice Recognition Repair Code	0024	0001	Download from ASAP
Champ2 Media Player (USB) Repair Code	0072	0001	Download from ASAP
Champ2 BMW Apps Enabling Code	008E	0001	Download from ASAP
Entry Radio Headunit			
Entry SDARS Retrofit/Repair	006F	0001	Download from ASAP
Entry Media Player Retrofit/Repair	0081	0001	Download from ASAP
Entry Telephone Retrofit/Repair	0082	0001	Download from ASAP
Entry Voice Recognition Retrofit/Repair	008F	0001	Download from ASAP
Entry Online Browser Retrofit/Repair	0090	0001	Download from ASAP
NBT			
Navigation Code HB Retrofit/Repair	00A0	0001	Download from ASAP
Navigation Enabler Code Retrofit/Repair	00DE	0001	Download from ASAP
Voice Recognition Code Retrofit/Repair	009E	0001	Download from ASAP
Lab Timer(M-Vehicles only)	00E5	0001	Download from ASAP
Map Europe 2012	00A9	0001	Download from ASAP
Map Europe 2013	00A9	0002	Download from ASAP
Map North America 2012	00A8	0001	Download from ASAP
CIC SDARS Code Retrofit/Repair	006F	0001	Download from ASAP
CIC BMW Apps Enabling Code	009C	0001	Download from ASAP
TextToSpeech	009F	0001	Download from ASAP
RADIO2			
Radio2 SDARS Retrofit/Repair	0078	0001	Download from ASAP
Radio2 Bluetooth telephone Retrofit/Repair	007C	0001	Download from ASAP
Radio2 Audio player Ipod Retrofit/Repair	007D	0001	Download from ASAP
EPS			
Servotronic Retrofit Code (EPS) for F25	0083	0001	Download from ASAP
Servotronic Retrofit Code (EPS) for E8x and E9x	0084	0001	Download from ASAP
BMW Tuning			
Power Kit Enabling Code N54 (MSD81/ MSD80)	007A	0001	Envelope/Download ASAP
Power Kit Enabling Code N55	0086	0001	Envelope/Download ASAP
Power Kit Enabling Code N63 (MSD851)	0085	0001	Envelope/Download ASAP
Power Kit Enabling Code N54 (MSD81)	0096	0001	Download ASAP

NVC

Night Vision Control Unit Enabling Code
Night Vision Camera Enabling Code

0004
0005

0001
0001

CD supplied with Kit
CD supplied with Kit