

The table below summarizes all possible ways of installing the GW500 in BMW models. (Please note: This description is **valid only for iDrive3** Audio Systems, **not for iDrive 4**)

### **BMW with iDrive-3**

Options	E65 <sup>1</sup> before 03/2005	E60 <sup>2</sup> M-ASK	All other models
original CD changer fitted and MP3 capability <sup>3</sup> is already available	not possible combination <sup>4</sup>	convert CD Changer option to „IPOD” retrofit	no programming required
original CD changer fitted and no MP3 capability is available, <b>text</b> capable BMW mode is used			retrofit “KMP3” option with service computer
original CD changer fitted and no MP3 capability is available, <b>non text</b> capable BMW mode is used	no programming required		
original CD changer not fitted	use BMW non-text DIP switch setting and retrofit CD Changer	retrofit “IPOD” option with service computer	

### **Important note:**

- If the SW of the car requires an update or a KMP3 activation, switch the Gateway to bypass/service mode before you start the procedure. Before converting or retrofitting IPOD option, switch back to GW mode.

<sup>1</sup> - E65 means all 7 series model variations (E65/E66)

<sup>2</sup> - E60 means all 5 and 6 series model variations (E60/E61/E63/E64)

<sup>3</sup> - the car is MP3 capable if the front CD-Slot reads MP3 audio discs and the ID3 tags are visible on the display

<sup>4</sup> - In case of E65 there was a Head Unit hardware change in 03/2005. Cars which were produced before this date cannot be enabled for MP3, therefore text capability will not be available with the Gateway