

CX02203 Maintenance

Engine

- New spark plugs
- Refreshed Injectors
- New coolant expansion tank
- Intake valves cleaned of carbon
- Engine oil and filter change
- Cleaned Vanos solenoids and MAF
- Replaced Bank 1 O2 sensor
- New vacuum lines
- New engine mounts x2

Drivetrain

- Transmission Service
 - o Pan/filter/fluid
 - o Mechatronics sealing sleeves
- Refreshed rear suspension
 - o New control and upper guide arms
 - o New ball joints
 - o M5 integral links
 - o Replaced axles (128k with 70k)
 - o New rear bump stops
- Brakes fluid flushed and bled
- New transfer case bushing
- New center support bearing
- Serviced transfer case actuator
- Replaced guibo
- 4 wheel alignment
- Transfer case fluid flush
- F/R Differential Fluid flush

Body

- Replaced Panoramic roof cassette, installed new gasket
- New headlight gaskets x2
- Replaced windshield cowl
- Replaced lower rear seat cushion
- Replaced cabin air filters
- New OEM roundals F/R
- Replaced driver seat belt
- Replaced front door weather stripping
- New cargo floor handle
- Repaired front seat thigh support gears