GEICO

Northern New Jersey E-mail Supplements to: R8ADSuppNNJ@geico.com Visit us Online at www.geico.com 300 Crosspoint Parkway Getzville, NY 14068 Phone: (551) 497-1366 Fax: (855) 331-4005

Claim #: Workfile ID: 0457317710101037-01 48396f9d

Supplement of Record 2 Summary

Written By: PETER VARACALLI, 11/7/2014 10:29:13 AM Adjuster: GONEL, JEFFREY, (551) 404-8085 Cellular

			· j ···· ,·	, (, , , , , , , , , , , , , , , , , ,						
Insured: Type of Loss: Point of Impact:	Kewill Ta Collision 11 Left F	[Date of Loss: 08	84035609 /11/2014 05:5 0.00		Claim #: Days to Repair:	0457317710101 30	037-01		
Owner: Kewill Taveras Elizabeth, NJ 072 (908) 305-1530 E		Inspection QUALITY AU 811 New Bru Rahway, NJ (Non Drive-in (732) 388-24	TO BODY - XF P Inswick Ave (1 07065-3838	ppraiser Inf Varacalli@geid 551) 497-1366	co.com	(8 ((2	Repair Facility: 2UALITY AUTO BC 311 NEW BURNSW RAHWAY, NJ 0706 (732) 388-2400 Ev (732) 388-2535 Fa 222269253 Federa 20361A License Nu	/ICK AVE 5 ening x I ID		
			V	EHICLE						
'ear: 2008		Color:	BLACK Int: BLACK	License:	Z68DZE	F	Production Date:			
Make: BMW Model: 535XI		Body Style: Engine:	4D SED 6-3.0L-T	State: VIN:	NJ WBANV9358		Odometer: Condition:	77506		
FRANSMISSIO		Console/S	0	Stereo			Reclining/Lounge S	Seats		
Automatic Transr	nission	Wood Inte		Search/S			eather Seats			
Overdrive		CONVEN		CD Playe SAFETY	r		NHEELS	noole		
Wheel Drive		Air Condit	ent Wipers		ide Air Raa		Aluminum/Alloy Wl PATNT	IEEIS		
Power Steering		Tilt Wheel	-	Drivers Side Air Bag Passenger Air Bag			Clear Coat Paint			
ower Brakes		Cruise Co		-	Brakes (4)		Metallic Paint			
ower Windows		Rear Defo			Disc Brakes		OTHER			
ower Locks		Keyless Ei		Front Sid	e Impact Air E	Bags F	og Lamps			
ower Mirrors		Alarm		Head/Curtain Air Bags		Head/Curtain Air Bags		Ţ	Traction Control	
leated Mirrors		Steering V	Wheel Touch Controls	trols Communications System		m S	Stability Control			
ower Driver Sea	t	Telescopio	c Wheel	Hands Fr	ee Device	>	Kenon Headlamps			
ower Passenger		Climate C	ontrol	ROOF		ŀ	Headlamp Washers	6		
lemory Package		RADIO			Blass Sunroof	F	Power Trunk/Gate	Release		
DECOR AM Radio SEAT		SEATS								
DECOR Dual Mirrors		FM Radio		Bucket S						

Claim #: 0457317710101037-01 Workfile ID: 48396f9d

Supplement of Record 2 Summary

2008 BMW 535XI AWD 4D SED 6-3.0L-T BLACK

Line			Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	#			No Supplement Will Be Honored Unless Authorized By Geico		1			
2	INFORM	ΙΟΙΤΑΝ	N LABE	LS					
3			Repl	Emission label 3.0L	71227568805	1	15.39	0.2	
4	FRONT	BUMPE	ER & GI	RILLE					
5	**		Repl	A/M CAPA Bumper cover w/park distance control	BM1000193C	1	608.00	2.6	3.2
6				Add for Clear Coat					1.3
7				Add for park sensor				0.4	
8			Repl	LT Cover lamp washer	51117111741	1	24.78	Incl.	0.2
9				Add for Clear Coat					0.1
10			R&I	RT Lower grille w/o active cruise	51117178098			Incl.	
11			Repl	LT Lower grille w/o active cruise	51117178097	1	40.69	Incl.	
12			Repl	Tow eye cap	51117184708	1	21.92	Incl.	0.2
13				Add for Clear Coat					0.1
14			R&I	RT Reflector	63147185744			Incl.	
15			Repl	LT Reflector	63147185743	1	21.71	Incl.	
16			R&I	RT Grille chrome	51137065702			Incl.	
17			R&I	LT Grille chrome	51137065701			Incl.	
18			Repl	License bracket	51117193522	1	52.36	0.2	
19			•	LT Energy absorber	51117178083	1	37.89	0.3	
20			Repl	Reinf beam	51117178087	1	372.53	0.4	
21			Repl	Spoiler	51117198363	1	15.65	Incl.	
22				LT Outer support	51117178077	1	12.39	Incl.	
23		S01	-	LT Lever	51117060585	1	7.07	Incl.	
			- 1-	NOTE: DAMAGED					
24	#	S01	Repl	Bracket Cover		1	8.03	0.2	
25	FRONT								
26			R&I	RT R&I headlamp assy	63127177756			0.7	
27				Deduct for Overlap				-0.4	
28		S01	Repl	LT Headlamp assy	63127045695	1	1,612.86	1.3	
20			nop.	NOTE: LKQ CAME IN DAMAGED, OEI			.,		
29		S01		Add for h'lamp washer				0.4	
30		S01		Deduct for Overlap				-0.4	
31		001	R&I	LT Repeater lamp	63137165741			Incl.	
32			R&I	RT Fog lamp	63177177712			Incl.	
33	* *		Repl	A/M LT Fog lamp	B2405	1	118.46	Incl.	
34	RADIAT	OR SU			D2100	•	110.10	inoi.	
35		500		LT Side panel (ALU)	51647163483	1	86.28	2.0	0.3
36				Add for Clear Coat	0.017100100	•	00.20	2.0	0.1
37				Aim headlamps				0.5	0.1
0,				LT Support bracket			11.48	0.3	

Claim #: Workfile ID: 0457317710101037-01 48396f9d

Supplement of Record 2 Summary

2008 BMW 535XI AWD 4D SED 6-3.0L-T BLACK

			Dal		54 (170007 14				4 5	
39			R&I	Upper tie bar (ALU)	51647033741				1.5	
40	HOOD **		Devel		00740	1	052.05		0.1	
41	~ ~		Repl	A/M CAPA Hood (ALU)	B074C	1	953.85		2.1	3.2
42				Add for Clear Coat						1.3
43				Add for Underside(Complete)						1.6
44	*		R&I	Emblem	51148132375				<u>0.1</u>	
45		S01	Repl	RT Lift cylinder	51237008745	1	53.95		0.2	
				NOTE: DAMAGED						
46		S01	Repl	LT Lift cylinder	51237008745	1	53.95		0.2	
				NOTE: DAMAGED						
47	FENDE	R								
48			Blnd	RT Fender w/o M5 (ALU)	41357111430					1.(
49	* *		Repl	A/M CAPA LT Fender w/o M5 (ALU)	B0628	1	236.92		2.2	2.0
50				Overlap Major Adj. Panel						-0.4
51				Add for Clear Coat						0.3
52				Add for Edging						0.5
53				Deduct for Overlap					-0.4	
54			Repl	LT Fender liner w/o M5 w/o aero pkg	51717186921	1	178.17		Incl.	
55			Repl	LT Upper rail (ALU)	41117111289	1	284.30	S	5.5	0.8
56			Repl	LT Rail assy (ALU)	41117111075	1	611.02	S	10.0	1.5
57				Overlap Minor Panel						-0.2
58			Repl	LT Front section (ALU)	41147111069	1	285.17	S	2.5	1.0
59				Overlap Major Non-Adj. Panel						-0.2
60		S01	Repl	LT Cover panel (ALU)	41217111809	1	28.69			
				NOTE: DAMAGED						
61	WHEEL	.S								
62			Repl	LT/Front Wheel, alloy style 122 8x17	36116776778	1	365.55	m	0.3	
63	FRONT	SUSPE	NSION	J						
64		S01		O/H frt susp It				m	3.5	
65			Repl	LT Ft lwr cntl arm	31106770685	1	251.74	m	Incl.	
66		S01	Repl	LT Rr lwr cntl arm from 4-06	31122347981	1	188.11	m	Incl.	
67			Repl	LT Strut	31316786517	1	410.72	m	Incl.	
68		S01	Repl	LT Hub	31206768308	1	107.83	m	Incl.	
69		S01	Repl	LT Bearing	31226783913	1	103.67		Incl.	
70		S01	Repl	LT Bearing lock ring	07119934760	1	4.24		Incl.	
71		S01	Repl	LT Dust cover	31216768313	1	6.57		Incl.	
72		S01	Repl	LT Ft lwr cntl arm bushing	31120406872	1	79.88			
73		S01	Repl	LT Lower ball joint	31126779840	1	68.10			
74		S01	Repl	LT Knuckle	31216768315	1	358.88	m	Incl.	
75	STEERI	NG GE		INKAGE						
76		S01		LT Outer tie rod w/AWD	32216767860	1	105.40	m	0.5	
77	#	S01		LT Hydro bearing		1	57.23		0.2	

Claim #: Workfile ID:

0457317710101037-01 48396f9d

Supplement of Record 2 Summary

2008 BMW 535XI AWD 4D SED 6-3.0L-T BLACK

78	WINDSHIELD)						
79		Repl	Washer reservoir w/lamp washer	61677179453	1	52.76	1.0	
80	PILLARS, RO	CKER &	FLOOR					
81		R&I	RT Rocker molding w/o M5	51777178126			0.8	
82		R&I	LT Rocker molding w/o M5	51777178125			Incl.	
83	FRONT DOOR							
84		Blnd	LT Door shell	41517202339				1.0
85		R&I	LT Belt molding black	51217207257			0.4	
86		R&I	LT R&I mirror	51167189571			0.4	
87		R&I	LT Mirror cover	51167078359			0.2	
88	*	Rpr	LT Mirror cover	51167078359			<u>0.5</u>	0.4
89			Add for Clear Coat					0.1
90		R&I	LT Handle, outside	51216961443			0.5	
91		R&I	LT R&I trim panel	51416983561			0.6	
92	MISCELLANE	DUS OF	PERATIONS					
93	*	Repl	Cover car/bag		1		0.0	0.2
94	#	Repl	Flex Additive adj		1	10.00 T		
95	#	Subl	Four Wheel Alignment		1	69.95 X		
96	#	Repl	Restore Corrosion Protection		1	10.00 T	0.2	
97	#	Rpr	Unibody setup and measure				2.0 F	
98	#	Rpr	Unibody pull				2.0 F	
99	#	Rpr	Reset Electronic Components				0.5	
100	#	Subl	Balance wheel and tire		1	8.00 T		
101	# S02	Subl	JMK DIAG CRUISE/HEADLAMP ISSUE		1	297.46 X		
			NOTE: AS PER JEFF GONEL, DIAG HEA REIMBURSEMENT	DLAMP ISSUE/CRUISE C	ONTROL	ISSUE. OK TO PA	Y CUSTOMERB FOR	
102	OTHER CHAR	GES						
103	#		E.P.C.		1	2.50		
				SUBTOTALS		8,312.10	46.2	19.6

NOTES

Prior Damage Notes: Lt fender: Windshield: ROCK CHIPS Wheels & wheel covers: Tires: Front lamps/foglamps: Front bumper: Grille and Hood: Rt Fender: DENTED Rt front door, moldings, glass, mirrors: Rt rocker and uniside: Rt rear door, moldings, glass: Rt 1/4 panel: Back Glass: Deck Lid/Tail Gate/Spoiler:

Rear Bumper and exhaust: SCRATCHES Rear lamps: Lt 1/4 Panel: Lt rocker and uniside: Lt rear door, moldings, glass: Lt front door, moldings, glass, mirror: Roof and sunroof: Interior-seats, carpets, dash, headliner:

ESTIMATE TOTALS

Category	Basis		Rate	Cost \$
Parts				7,914.19
Body Labor	42.2 hrs	@	\$ 47.00 /hr	1,983.40
Paint Labor	19.6 hrs	@	\$ 47.00 /hr	921.20
Frame Labor	4.0 hrs	@	\$ 47.00 /hr	188.00
Paint Supplies	19.6 hrs	@	\$ 27.00 /hr	529.20
Miscellaneous				395.41
Other Charges				2.50
Subtotal				11,933.90
Sales Tax	\$ 11,566.49	@	7.0000 %	809.65
Total Cost of Repairs				12,743.55
Deductible				500.00
Total Adjustments				500.00
Net Cost of Repairs				12,243.55

					Claim #: Workfile ID:	0457317	710101037-01 48396f9c
		Supplement	of Record 2 Summ	nary			
		2008 BMW 535XI	AWD 4D SED 6-3.0L-T B	LACK			
		SUPPLE	MENT SUMMARY				
Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
Added Items							
101 #	S02 Subl	JMK DIAG CRUISE/HEADLAMP ISSUE		1	297.46 X		
		NOTE: AS PER JEFF GONEL, DIAG REIMBURSEMENT	HEADLAMP ISSUE/CRUIS	E CONTRO	DL ISSUE. OK TO PA	Y CUSTOMERB F	OR
			SUBTOTALS		297.46	0.0	0.0
			NOTES				
Prior Damage Note Lt fender: Windshield: ROCK Wheels & wheel co Tires: Front lamps/foglar Front bumper: Grille and Hood: Rt Fender: DENTE Rt front door, mold Rt rocker and unis Rt rear door, mold Rt 1/4 panel: Back Glass: Deck Lid/Tail Gate Rear lamps: Lt 1/4 Panel: Lt rocker and unisi Lt rear door, mold Lt front door, mold Rt front door, mold Roof and sunroof: Interior-seats, carg	CHIPS overs: nps: dings, glass, m ide: ings, glass: /Spoiler: exhaust: SCRA ide: ings, glass: dings, glass, mi	TCHES irror:					
		TOTALS SUMMARY					

Category	Basis	Rate	Cost \$
Parts			0.00
Miscellaneous			297.46
Subtotal			297.46
Total Supplement Amount			297.46
NET COST OF SUPPLEMENT			297.46

Estimate	10,434.27	JEFFREY GONEL
Supplement S01	2,011.82	JEFFREY GONEL
Supplement S02	297.46	PETER VARACALLI
Workfile Total:	\$ 12,743.55	
TOTAL ADJUSTMENTS:	\$ 500.00	
NET COST OF REPAIRS:	\$ 12,243.55	

CUMULATIVE EFFECTS OF SUPPLEMENT(S)

This is not an authorization to repair.

All GEICO customers have the right to have their vehicle repaired in the shop of their choice.

No Supplement will be honored unless authorized by GEICO.

NOTICE: Vehicles constructed of special metals may require the use of specialized welding and bonding equipment. Proper measuring and structural repair systems are required on today's vehicle to accurately accomplish vehicle repairs. Make sure your shop has the proper equipment to repair your vehicle.

ALTERNATE PARTS DISCLAIMER:

IF A QUALITY REPLACEMENT PART (A/M, LKQ, RECOND OR OPT OEM) APPEARS ON THIS ESTIMATE, IT INDICATES THAT THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. GUARANTEES, IF ANY, APPLICABLE TO THESE REPLACEMENT CRASH PARTS ARE PROVIDED BY THE PART MANUFACTURER OR DISTRIBUTOR RATHER THAN BY THE MANUFACTURER OF YOUR VEHICLE.

***IN ADDITION TO ANY SUCH GUARANTEES, GEICO PROVIDES THE FOLLOWING:

****OWNER LIMITED GUARANTEE**** WE GUARANTEE THAT ALL QUALITY REPLACEMENT BODY PARTS (PARTS NOT MANUFACTURED BY THE MANUFACTURER) IDENTIFIED ON YOUR ESTIMATE, ARE FREE OF DEFECTS IN MATERIAL AND WORKMANSHIP AND MEET GENERALLY ACCEPTED INDUSTRY STANDARDS. THIS PARTS AND LABOR GUARANTEE WILL BE IN EFFECT FOR AS LONG AS YOU OWN THE VEHICLE DESCRIBED IN THE ESTIMATE. THIS GUARANTEE COVERS THE COST OF THE PART, LABOR TO INSTALL, AND INCIDENTALS SUCH AS PAINT AND MATERIALS AND IS SPECIFICALLY LIMITED TO THOSE ITEMS. THIS GUARANTEE DOES NOT COVER LOSS OR DAMAGE THAT IS UNRELATED TO DEFECTS IN THE QUALITY REPLACEMENT PARTS. THIS IS NOT TRANSFERABLE. IF ANY QUALITY REPLACEMENT PARTS ARE DEFECTIVE IN EITHER MATERIAL OR WORKMANSHIP, CONTACT YOUR LOCAL GEICO REPRESENTATIVE.

ANY PERSON WHO KNOWINGLY FILES A STATEMENT OF CLAIM CONTAINING ANY FALSE OR MISLEADING INFORMATION IS SUBJECT TO CRIMINAL AND CIVIL PENALTIES.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF AUTOMOBILE PARTS NOT MADE BY THE ORIGINAL MANUFACTURER. PARTS USED IN THE REPAIR OF YOUR VEHICLE BY OTHER THAN THE ORIGINAL MANUFACTURER ARE REQUIRED TO BE AT LEAST EQUAL IN LIKE, KIND AND QUALITY IN TERMS OF FIT, QUALITY AND PERFORMANCE TO REPLACEMENT PARTS AVAILABLE FROM THE ORIGINAL MANUFACTURER.

Estimate based on MOTOR CRASH ESTIMATING GUIDE. Unless otherwise noted all items are derived from the Guide ERE1912, CCC Data Date 10/17/2014, and the parts selected are OEM-parts manufactured by the vehicles Original Equipment Manufacturer. OEM parts are available at OE/Vehicle dealerships. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships. OPT OEM or ALT OEM parts may include "Blemished" parts provided by OEM's through OEM vehicle dealerships. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor information provided by MOTOR may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM or A/M. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Record. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2015 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a complete list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Information Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

YOU MAY USE A REPAIR FACILITY OF YOUR CHOICE. PURSUANT TO LAW, ANY ENTITY ENGAGED IN THE BUSINESS OF AUTO BODY REPAIRS MUST BE DULY LICENSED. N.J.A.C. 11:3 - 10.3 PROHIBITS AN INSURER BY LAW FROM NEGOTIATING, ADJUSTING OR SETTLING AN AUTOMOBILE DAMAGE CLAIM WITH AN UNLICENSED FACILITY.

Claim #: 0457317710101037-01 Workfile ID: 48396f9d

Supplement of Record 2 Summary

2008 BMW 535XI AWD 4D SED 6-3.0L-T BLACK

ALTERNATE PARTS SUPPLIERS

Line	Supplier	Description	Price
5	KEYSTONE - TOTOWA, NJ	#BM1000193C	\$ 608.00
	55 SHEPHERDS LANE	A/M CAPA Bumper cover w/park distance control	
	TOTOWA NJ 07512	Quote: 14754616	
	(973) 389-8200	Expires: 09/27/14	
33	Empire Auto Parts, NJ	#B2405	\$ 118.46
	Bollander, Randall	A/M LT Fog lamp	
	15 Jackson Road		
	Totowa NJ 07512		
	(973) 772-4206		
41	Empire Auto Parts, NJ	#B074C	\$ 953.85
	Bollander, Randall	A/M CAPA Hood (ALU)	
	15 Jackson Road		
	Totowa NJ 07512		
	(973) 772-4206		
49	Empire Auto Parts, NJ	#B0628	\$ 236.92
	Bollander, Randall	A/M CAPA LT Fender w/o M5 (ALU)	
	15 Jackson Road		
	Totowa NJ 07512		
	(973) 772-4206		

ALTERNATE PARTS USAGE

Year:	2008	Color:	BLACK Int: BLACK	License:	Z68DZE	Production Date:	
Make:	BMW	Body Style:	4D SED	State:	NJ	Odometer:	77506
Model:	535XI AWD	Engine:	6-3.0L-T	VIN:	WBANV93588CZ65702	Condition:	

Alternate Part Type	# Of Available Parts	# Of Parts Selected
Aftermarket	40	4
Optional OEM	15	0
Reconditioned	7	0
Recycled	134	0