

Final report

Session name: E60_B859909
Duration: 00:04:59
Measures plan implementation successful: Yes
Concluding work, notes: Not fitted
Change vehicle order: No

Header data

Date:	9/1/2017	Time:	5:35:30 PM	ISTA/P version:	3.55.0.300
-------	----------	-------	------------	-----------------	------------

Model series:	E60	Type/description:	NA53 / E60 Saloon M54B25 OL LHD US
---------------	-----	-------------------	------------------------------------

Odometer:	222959	Vehicle ID number:	WBANA53575B859909
-----------	--------	--------------------	-------------------

Integration level (plant):	Integration level (old):	Integration level (new):
E060-04-09-550	E060-14-11-500	E060-14-11-500

Time criterion:	0904	Paint code:	0300	Upholstery code:	LCRK
-----------------	------	-------------	------	------------------	------

E words:

K words:	B110, K633
----------	------------

SA numbers: 1CA, 205, 248, 2CF, 302, 319, 354, 403, 430, 431, 438, 441, 442, 459, 473, 488, 494, 502, 522, 524, 534, 540, 563, 605, 639, 645, 676, 693, 694, 697, 785, 818, 823, 845, 850, 853, 876, 925, 992

Programmings sequential OBD (K line, DCAN)

*fixed sorting according to execution sequence

Control module	Action	Result / fault code	Status	Type	Hardware index	Part number prog. ECU old	Part number prog. ECU new
EGS/SMG	Program P	Successful	✓	MAN	72	7548092	7548092

Actions, post-programming initialisations

Action	Note	Result	Status	Type
Save MOST configuration	-	Successful	✓	Sys
Clear fault code memory	-	Successful	✓	Sys
Read fault code memory	-	Successful	✓	Sys

Data recovery

Control module	Action	Result	Status	Type
-	Read CKM settings	Successful	✓	Sys
-	Write CKM settings	Successful	✓	Sys

Additional actions

Control module	Action	Result / fault code	Status
-	Update integration level	Successful	✓
-	Vehicle order alignment	Successful	✓